

I 29.88:EL 5/V.4/APP.A/PT.2

V.4.2

PUBLIC DOCUMENTS
DEPOSITORY ITEM

FEB 27 1989

CLEMSON
LIBRARY

existing condition survey

units 2, 3, and 4

volume 4

appendix A

part two

Clemson University



3 1604 019 703 349

ELLIS ISLAND

STATUE OF LIBERTY

NATIONAL MONUMENT/NEW YORK-NEW JERSEY



*Funds for preparation and printing of this
document were provided by a donation from the
Statue of Liberty/Ellis Island Foundation*



ELLIS ISLAND
STATUE OF LIBERTY NATIONAL MONUMENT
EXISTING CONDITION SURVEY
UNITS 2, 3 AND 4

Volume 4
Appendix A
Part Two

Prepared by

Beyer Blinder Belle/
Anderson Nottter Finegold

U.S. Department of the Interior / National Park Service



Digitized by the Internet Archive
in 2012 with funding from
LYRASIS Members and Sloan Foundation

<http://archive.org/details/existingconditiov4appapt2>

EXISTING CONDITION SURVEY

TABLE OF CONTENTS

PAGE

Part I

I. Introduction.....	1
II. Survey Methodology	
A. Explanation of Forms.....	3
B. Definition of Existing Conditions.....	5
Floor - Tile.....	6
Floor - Wood.....	7
Floor - Linoleum.....	8
Floor & Base - Resilient Tile.....	9
Base - Wood.....	10
Base & Walls - Tile/Tile Wainscot.....	11
Walls & Ceilings - Plaster.....	12
Walls & Ceilings - Gypsum Board/ Glazed Wood Partitions/Acoustic Panels.....	13
Doors/Openings - Wood/Glass Panelled.....	14
Doors/Openings - Wood Veneer.....	15
Doors/Openings - Galvanized Metal.....	16
Lighting Fixtures.....	17
Heating/Ventilation/Plumbing.....	21

C. Definitions of Architectural Significance.....	26
Areas of Most Architectural Significance.....	27
Areas of Some Architectural Significance.....	28
Areas of Minor Architectural Significance.....	29
Areas of Negligible Architectural Significance.....	30

III. Inventory & Plans Building

A. Ferry House	
1. Plan Depicting Existing Conditions	
First Floor.....	31
2. Plan Depicting Architectural Significance	
First Floor.....	32
3. Inventory	
First Floor.....	33
B. Administration Building	
1. Floor Plans	
Second Floor.....	57
Third Floor.....	58
2. Inventory	
Second Floor.....	59
Third Floor.....	77

C. New Hospital Extention

1. Plans Depicting Existing Conditions	
Basement.....	127
First Floor.....	128
Second Floor.....	129
Third Floor.....	130
2. Plans Depicting Architectural Significance	
First Floor.....	131
Second Floor.....	132
Third Floor.....	133
3. Inventory	
Basement.....	134
First Floor.....	140
Second Floor.....	218
Third Floor.....	280

Part II

D. Staff House	
1. Plans Depicting Existing Conditions	
First Floor.....	360
Second Floor.....	361
2. Plans Depicting Architectural Significance	
First Floor.....	358
Second Floor.....	359
3. Inventory	
First Floor.....	362
Second Floor.....	388
E. Immigrant Building	
1. Plans Depicting Existing Conditions	
First Floor.....	424
2. Plan Depicting Architectural Singificance	
First Floor.....	425
3. Inventory	
First Floor.....	426

F. Recreation Building	
1. Plans Depicting Existing Conditions	
First and Second Floor.....	560
2. Plans Depicting Architectural Significance	
First and Second Floor.....	561
3. Inventory	
First Floor.....	562
Second Floor.....	596
IV. Revised Interior Condition Survey	
A. Explanation of Forms.....	606
1. Inventory.....	607
V. Exterior Condition Survey	
A. Explanation of Forms.....	618
1. Inventory.....	619




STAFF HOUSE

EXISTING CONDITIONS



Exhibit 16



356 | 26,013 / 1 of 8
DSC | JUL 88




UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE DENVER SERVICE CENTER	
ARCHITECTS BETTER BUILDING BELLE / HOTTER PRINGOLD & ALEXANDER 41 EAST 11 STREET NEW YORK, NY 10003 (212) 777-2600	
STRUCTURAL ENGINEERS ROBERT SULMAN ASSOCIATES, P.C. MECHANICAL & ELECTRICAL ENGINEERS BYRGA & HENNESSY INC.	
SURVEY OF STRUCTURES UNIT 3	
ELLIS ISLAND STATUE OF LIBERTY NATIONAL MONUMENT NEW YORK / NEW JERSEY	
TITLE OF SHEET STAFF HOUSE FIRST FLOOR PLAN	
SUB SHEET NO. DRAWING NO.	
PAGE NO. OF	
DESIGNED DATE	
DRAWN J. SEN	
TECH. REVIEW	
KEY	

EXISTING CONDITIONS



Exhibit 17



356	26,013 / 2 of 8
DSC	JUL 88

FEET 1/4 INCH
 METERS 1/48

UNITED STATES DEPARTMENT
OF THE INTERIOR
NATIONAL PARK SERVICE
DENVER SERVICE CENTER

ARCHITEC:78

BEVER BLUNDER BELLE /
MOTTER FINEGOLD & ALE
41 EAST 11 STREET
NEW YORK, NY 10003
(212) 777-7900

STRUCTURAL ENGINEER

ROBERT SALMAN ASSOCIATES, P.C.

MECHANICAL & ELECTRICAL ENGINEERS

NEW YORK & HENRIE BLY INC.

SURVEY OF STRUCTURES UNIT 3

ELLIS ISLAND
STATUE OF LIBERTY
NATIONAL MONUMENT
NEW YORK / NEW JERSEY

	DATE	DATE
SIGNED	TECH REVIEW	





TABLE OF SHEET
TUFF HOUSE
SECOND FL PLAN

PAGE	SHEET
NO	

Exhibit 18


ARCHITECTURAL SIGNIFICANCE



"MINOR" DUE TO INFILLED AREAS.

"MINOR" DUE TO PARTITIONING.

"MINOR" DUE TO PARTITIONING.



356 26,013 / 3 of 8

DSC JUL 88



UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE DENVER SERVICE CENTER		ARCHITECTS BETTER BUILDERS BELL / MOTTER PINEGOLD & ALEXANDER 41 EAST 11 STREET NEW YORK, NY 10003 (212) 777-1800		STRUCTURAL ENGINEERS ROBERT BILMAN ASSOCIATES, P.C. MECHANICAL & ELECTRICAL ENGINEERS SYSTEMS & HERMES INC.		SURVEY OF STRUCTURES UNIT 3		ELLIS ISLAND STATUE OF LIBERTY NATIONAL MONUMENT NEW YORK / NEW JERSEY		DESIGNED DATE TECH REVIEW DATE KEY		TITLE OF SHEET STAFF HOUSE FIRST FLOOR PLAN SUB SHEET NO. DRAWING NO.	
--	--	--	--	--	--	--	--	---	--	--	--	--	--

ARCHITECTURAL SIGNIFICANCE

MOST

SOME

MINOR

WE GROWN




Exhibit 19


UNITED STATES DEPARTMENT
OF THE INTERIOR
NATIONAL PARK SERVICE
DENVER SERVICE CENTER

ARCHITECTS
SEYER BLUMBERG SELLE /
NOTTER FINEGOLD & ALEXANDER
41 EAST 11 STREET
NEW YORK, NY 10003
212 777-7800

STRUCTURAL ENGINEERS
ROBERT SALMAN ASSOCIATES, P.C.
MECHANICAL & ELECTRICAL ENGINEERS
SYRIZA & MANNING INC.

SURVEY OF STRUCTURES UNIT 3

ELLIS ISLAND
STATUE OF LIBERTY
NATIONAL MONUMENT
NEW YORK / NEW JERSEY

[illegible]

TITLE OF SHEET
STAFF HOUSE
SECOND FL. PLAN

DRAWING NO.	DRAWING NO.	
	PKG.	SHEET

356	26,013 / 4 of 8
DSC	JUL 88

4 0 4 8
FEET 1/4" = 1'-0"

4 0 4 8
METERS 1/48 = 1M



ELLIS ISLANDEXISTING CONDITION SURVEYStaff Housepage: 362

ROOM NO: 101

LAST KNOWN USE: Dining room



CEILING HEIGHT: 10'-2 1/4"DATE: 25 Nov. 1985

SQUARE FEET: 490

	FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	☒ Tile/Concrete Resilient ☒ Wood ☐ Other:	Good ☒ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	
BASE:	☐ Tile/Concrete Resilient ☒ Wood ☐ Other:	Good ☒ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	
WALLS:	☒ Plaster Partitions ☐ Tile Wainscot ☐ Other:	Good ☒ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	Picture rail. chain rail.
CEILING:	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	Good ☒ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	
DOORS/ OPENINGS:	☒ Wood/Glass Panelled ☐ Wood Veneer ☐ Galvanized Metal ☐ Other:	Good ☒ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	1 pair double 5-panel doors to hall. Windows have wood valance. evidence of venetian blinds.
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☒ CML/Sconce ☐ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	Evidence (flat metal caps in wall) of 9 removed sconces.
HEATING/ VENTILATION PLUMBING:	☒ Radiators ☐ Vents/Fans ☐ Sink/Toilet/Urinal ☐ Other:	☒ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	
MISCELLANEOUS:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	Fireplace: Hearth - tile block. face - brick.
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	ARCHITECTURAL SIGNIFICANCE: ☒ Most ☐ Some ☐ Minor ☐ Negligible


PHOTOGRAPHS: ① view North ② view South ③ view East ④ view West

ROOM NO. 101



ROOM NO:	102	LAST KNOWN USE:	Kitchen	SQUARE FEET:	208	CEILING HEIGHT:		DATE:	25 Nov. 1985
		FINISHES:	CONDITION:	DATE:		NOTES:			
FLOOR:	☒ Tile/Concrete ☒ Resilient ☒ Wood ☒ Other:	☒ Good ☒ Fair ☒ Poor ☒ Destroyed	☒ 1911-1923 ☒ 1924-1933 ☒ 1934-present ☒ In question	Probable replacement boards - no indication of wall removal, as in plan.					
BASE:	☒ Tile/Concrete ☒ Resilient ☒ Wood ☒ Other:	☒ Good ☒ Fair ☒ Poor ☒ Destroyed	☒ 1911-1923 ☒ 1924-1933 ☒ 1934-present ☒ In question	Some rot in NE corner.					
WALLS:	☒ Plaster ☒ Partitions ☒ Tile Wainscot ☒ Other:	☒ Good ☒ Fair ☒ Poor ☒ Destroyed	☒ 1911-1923 ☒ 1924-1933 ☒ 1934-present ☒ In question	Cove at ceiling - not corners. Ghosts of alterations: door replacement; pantry removal; window infill.					
CEILING:	☒ Plaster ☒ Acoustic panels ☒ Cove ☒ Other:	☒ Good ☒ Fair ☒ Poor ☒ Destroyed	☒ 1911-1923 ☒ 1924-1933 ☒ 1934-present ☒ In question	Ghost of pantry wall on ceiling.					
DOORS/ OPENINGS:	☒ Wood/Glass Panelled ☒ Wood Veneer ☒ Galvanized Metal ☒ Other: french doors	☒ Good ☒ Fair ☒ Poor ☒ Destroyed	☒ 1911-1923 ☒ 1924-1933 ☒ 1934-present ☒ In question	1 pair french doors sept: E. wall. Door removed = arched opening: W. wall. 3 panel door w/ altered wood infill light w/ diamond shaped glass light. (attached) to 102A.					
LIGHTING:	☒ Incandescent/Type A ☒ Incandescent/Type B ☒ CML/Sconce ☒ Other:	☒ Destroyed ☒ Destroyed ☒ Destroyed ☒ Destroyed	☒ 1911-1923 ☒ 1924-1933 ☒ 1934-present ☒ In question	Metal rod - approx. 2' w/ support for removed shade. Standard for staff House.					
HEATING/ VENTILATION PLUMBING:	☒ Radiators ☒ Vents/Fans ☒ Sink/Toilet/Urinal ☒ Other:	☒ Intact ☒ Intact ☒ Intact ☒ Intact	☒ 1911-1923 ☒ 1924-1933 ☒ 1934-present ☒ In question	none.					
MISCELLANEOUS:		☒ Good ☒ Fair ☒ Poor ☒ Destroyed	☒ 1911-1923 ☒ 1924-1933 ☒ 1934-present ☒ In question	cupboard w/ varnished interior where range used to be. Surrounds and this room are different from rest of bldg.					
SUMMARY:		☒ Good ☒ Fair ☒ Poor ☒ Destroyed	☒ 1911-1923 ☒ 1924-1933 ☒ 1934-present ☒ In question	ARCHITECTURAL SIGNIFICANCE: ☐ Most ☐ Some ☒ Minor ☐ Negligible					

③ View East ④ View West



PHOTOGRAPHS: ① View North ② View South



ELLIS ISLAND

EXISTING CONDITION SURVEY

STAFF HOUSE

page: 26

ROOM NO: 102A

LAST KNOWN USE: Kitchen

SQUARE FEET: 111

CEILING HEIGHT: 11

DATE: 25 Nov. 1985

	FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	☒ Tile/Concrete ☒ Resilient vinyl flk. ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	Adhering to base.
BASE:	☐ Tile/Concrete ☐ Resilient ☐ Wood ☒ Other: Vinyl	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
WALLS:	☒ Plaster ☒ Partitions ☐ Tile Wainscot ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	ghosts of prior walls and shelving.
CEILING:	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	ghosts of prior wall on ceiling.
DOORS/ OPENINGS:	☒ Wood/Glass Panelled ☐ Wood Veneer ☐ Galvanized Metal ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	☐ 5-panel door to central hall. ☐ altered 3-panel swinging door to 102, diamond light, 1/2 hinges. ☐ casement window: alteration.
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☒ CM Sconce 1 ☐ Other:	☐ Intact ☐ Intact ☒ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	no shade.
HEATING/ VENTILATION PLUMBING:	☐ Radiators ☒ Vents/Fans ☒ Sink/Toilet/Urinal ☐ Other:	☐ Intact ☐ Intact ☒ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	☐ ceramic sink on "youngstown" ☐ Metal kitchen cabinet base: rusting. ☐ exhaust fan over sink.
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	☐ wood counter in corner, on legs. ☐ rusted metal wall hung box = switch. ☐ ceramic box = N. wall.
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	ARCHITECTURAL SIGNIFICANCE: Most Some ☒ Minor Negligible

② view Northwest



PHOTOGRAPHS: ① view East



PHOTOGRAPHS: ③ View North

ROOM NO. 102A



PHOTOGRAPHS:

ROOM NO.

ELLIS ISLAND

EXISTING CONDITION SURVEY

Staff House

page: 370

ROOM NO: 103

LAST KNOWN USE: Library

SQUARE FEET: 326

CEILING HEIGHT:

DATE: 25 Nov. 1985

	FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	Tile/Concrete Resilient Wood Other:	Good Fair Poor Destroyed	1911-1923 1924-1933 1934-present In question	evidence of brown stain
BASE:	Tile/Concrete Resilient Wood Other:	Good Fair Poor Destroyed	1911-1923 1924-1933 1934-present In question	
WALLS:	Plaster Partitions Tile Wainscot Other:	Good Fair Poor Destroyed	1911-1923 1924-1933 1934-present In question	E. wall - rusting thru of metal sub-surface; electric cable to removed sconce. chair rail.
CEILING:	Plaster Acoustic panels Cove Other:	Good Fair Poor Destroyed	1911-1923 1924-1933 1934-present In question	Severe crack, SE area - extends down wall.
DOORS/ OPENINGS:	Wood/Glass Panelled Wood Veneer Galvanized Metal Other:	Good Fair Poor Destroyed	1911-1923 1924-1933 1934-present In question	Wood valance over window. Evidence of Venetian blinds. Doorways to 104, panelled reveals, no doors. 1 wood 5-panel door to H102A.
LIGHTING:	Incandescent/Type A Incandescent/Type B CML/Sconce Other:	Intact Intact Intact Intact Destroyed Destroyed Destroyed Destroyed	1911-1923 1924-1933 1934-present In question	evidence of 2 removed sconces: E wall. 1 metal rod suspended from ceramic fixture - no shade.
HEATING/ VENTILATION PLUMBING:	Radiators Vents/Fans Sink/Toilet/Urinal Other:	Intact Intact Intact Intact Destroyed Destroyed Destroyed Destroyed	1911-1923 1924-1933 1934-present In question	
MISCELLANEOUS:		Good Fair Poor Destroyed	1911-1923 1924-1933 1934-present In question	Fireplace: Brick, wood mantel w/ egg + dart molding; brackets
SUMMARY:		Good Fair Poor Destroyed	1911-1923 1924-1933 1934-present In question	ARCHITECTURAL SIGNIFICANCE: Most Some Minor Negligible

PHOTOGRAPHS: ① view South




② view North



PHOTOGRAPHS: ③ View East



④ View West



ROOM NO. 103

PHOTOGRAPHS:

ROOM NO.

PHOTOGRAPHS: ① view North ② view South ③ view East ④ view West

ROOM NO. 104



ELLIS ISLAND

EXISTING CONDITION SURVEY

Staff House

page: 514

ROOM NO: 105

LAST KNOWN USE: Kitchen

SQUARE FEET: 110

CEILING HEIGHT: 9'-10"

DATE: 25 Nov. 1985

		FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	☒ Tile/Concrete ☒ Resilient ☐ Wood ☐ Other:	☐ Good ☐ Fair ☒ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	cement substrate. vinyl tiles.	
BASE:	☒ Tile/Concrete ☒ Resilient ☐ Wood ☐ Other:	☐ Good ☐ Fair ☒ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question		
WALLS:	☒ Plaster ☐ Partitions ☐ Tile Wainscot ☐ Other:	☐ Good ☐ Fair ☒ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	plaster over pebble dash - exposed in S.W. corner. square ghost of wall-mount near window.	
CEILING:	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	☐ Good ☐ Fair ☒ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	1 wood 3-panel door, 4 lights, 1 metal 9-light casement window: E. 1 metal 6-light window: N. 1 destroyed vehicular blind: E. 1 draw curtain, pleated: N.	
DOORS/ OPENINGS:	☒ Wood/Glass Panelled ☐ Wood Veneer ☐ Galvanized Metal ☐ Other:	☐ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question		
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☒ CML Sconce 1 ☐ Other:	☐ Intact ☐ Intact ☒ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	1911-1923 1924-1933 1934-present In question	1 double ceramic sink on rusted "Youngstown Kitchen" base. 1 exhaust wall fan: e. wall. 1 century box.	
HEATING/ VENTILATION PLUMBING:	☒ Radiators 1 ☒ Vents/Fans ☒ Sink/Toilet/Urinal ☐ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	1911-1923 1924-1933 1934-present In question	2 unfulfilled windows made into cupboards; floral decal on door. 1 rusted metal electric stove. 1 rusted paper towel holder/side shelves. 1 table w/ wood top, 1 counter on brackets.	
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question		
SUMMARY:		☐ Good ☒ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	ARCHITECTURAL SIGNIFICANCE: ☐ Most ☐ Some ☒ Minor ☐ Negligible	

PHOTOGRAPHS: ① view North



② view South



PHOTOGRAPHS: ③ stove, Northeast Corner



④ Sink, East Wall

ROOM NO. 105



PHOTOGRAPHS:

ROOM NO.

ELLIS ISLAND

EXISTING CONDITION SURVEY

Staff House

page: 380

ROOM NO: 4101

LAST KNOWN USE: Entry Vestibule

SQUARE FEET: 39


CEILING HEIGHT:

DATE: 25 Nov. 1985

	FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	Tile/Concrete Resilient Wood Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	
BASE:	Tile/Concrete Resilient Wood Other:	☐ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	
WALLS:	Plaster Partitions Tile Wainscot Other: door surrounds	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	Wood partition wall to H101A w/ 3 lights in upper portion: S. wall. N. wall = cupboard: closet. chair rail and floral detail (paint) in closet. E. and W. walls - doorways.
CEILING:	Plaster Acoustic panels Cove Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	
DOORS/ OPENINGS:	Wood/Glass Panelled Wood Veneer Galvanized Metal Other:	☐ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	E. door: 3-panel w/ upper light (infilled). W. door: 1 1/2 panel w/ upper light; cast iron sill. Dimpled glass side lights. Transoms have 3 lights.
LIGHTING:	Incandescent/Type A Incandescent/Type B CMD/Sconce Other:	☐ Intact ☐ Intact ☒ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	1911-1923 1924-1933 1934-present In question	
HEATING/ VENTILATION PLUMBING:	Radiators Vents/Fans Sink/Toilet/Urinal Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	1911-1923 1924-1933 1934-present In question	
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	Double door closet w/ double door upper closet area. 1 door of lower section removed.
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	ARCHITECTURAL SIGNIFICANCE: Most Some Minor Negligible

PHOTOGRAPHS: ① view East from covered way. ② view Northwest

ROOM NO. 4101



ROOM NO: H101A

LAST KNOWN USE: Toilet

SQUARE FEET: 17

CEILING HEIGHT:

DATE: 25 Nov. 1985

	FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	☒ Tile/Concrete ☒ Resilient ☐ Wood ☐ Other:	☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
BASE:	☐ Tile/Concrete ☐ Resilient ☒ Wood ☐ Other:	☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
WALLS:	☒ Plaster ☐ Partitions ☐ Tile Mainscot ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	char rail.
CEILING:	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	
DOORS/ OPENINGS:	☒ Wood/Glass Panelled ☒ Wood Veneer ☐ Galvanized Metal ☐ Other:	☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	sidelight w/ dimpled glass. partition door to H101.
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☒ CML Sconce ☐ Other:	☐ Intact ☐ Intact ☒ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
HEATING/ VENTILATION PLUMBING:	☐ Radiators ☐ Vents/Fans ☒ Sink/Toilet/Urinal ☐ Other:	☐ Intact ☐ Intact ☒ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	toilet - partially destroyed. sink on metal front supports w/ fanatics
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	
SUMMARY:		☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	ARCHITECTURAL SIGNIFICANCE: Most Some ☒ Minor Negligible

PHOTOGRAPHS:

ROOM NO.

ELLIS ISLAND EXISTING CONDITION SURVEY				Staff House		page: 384						
ROOM NO: H102	LAST KNOWN USE: Hall	SQUARE FEET: 291	CEILING HEIGHT: 10'-1 1/4"	DATE: 25 Nov. 1985								
	FINISHES:	CONDITION:	DATE:	NOTES:								
FLOOR:	Tile/Concrete Resilient Wood Other:	Good Fair Poor Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question									
BASE:	Tile/Concrete Resilient Wood Other:	Good Fair Poor Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	Base curves up stairs.								
WALLS:	Plaster Partitions Tile Wainscot Other:	Good Fair Poor Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	Chair rail. Picture rail.								
CEILING:	Plaster Acoustic panels Cove Other:	Good Fair Poor Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question									
DOORS/ OPENINGS:	Wood/Glass Panelled Wood Veneer Galvanized Metal Other:	Good Fair Poor Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	single-light wood panelled door w/ sidelights and transom: W. wall. 2 pairs 5-panel double doors: E. & W. walls.								
LIGHTING:	Incandescent/Type A Incandescent/Type B CML/Sconce Other:	Intact Intact Intact Intact Destroyed Destroyed Destroyed Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	2 ceiling fixtures w/ metal rods. 1 w/ shade, 1 shade on floor.								
HEATING/ VENTILATION PLUMBING:	Radiators / Vents/Fans Sink/Toilet/Urinal Other:	Intact Intact Intact Intact Destroyed Destroyed Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question									
MISCELLANEOUS:		Good Fair Poor Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	1 rusting circuiting box. opening to pipe cellar under stairs: detached door; bottles on shelves.								
SUMMARY:		Good Fair Poor Destroyed	☒ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	ARCHITECTURAL SIGNIFICANCE:								
				Most	☒ Some	☐ Minor	☐ Negligible					

PHOTOGRAPHS: ① View East



② View West



ROOM NO. H102

ROOM NO: H102A	LAST KNOWN USE:	SQUARE FEET: 47	CEILING HEIGHT: 7'-11 ³ / ₄ "	DATE: 25 Nov. 1985
	FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	Tile/Concrete Resilient Wood Other:	Good Fair Poor Destroyed	1911-1923 1924-1933 1934-present In question	
BASE:	Tile/Concrete Resilient Wood Other:	Good Fair Poor Destroyed	1911-1923 1924-1933 1934-present In question	
WALLS:	Plaster Partitions Tile Wainscot Other:	Good Fair Poor Destroyed	1911-1923 1924-1933 1934-present In question	
CEILING:	Plaster Acoustic panels Cove Other:	Good Fair Poor Destroyed	1911-1923 1924-1933 1934-present In question	
DOORS/ OPENINGS:	Wood/~~Glass~~ Panelled Wood Veneer Galvanized Metal Other:	Good Fair Poor Destroyed	1911-1923 1924-1933 1934-present In question	2 5-panel doors: w. 4 s. walls. 1 doorway - no door. 2 unfilled windows.
LIGHTING:	Incandescent/Type A Incandescent/Type B ~~CML~~ Sconce Other:	Intact Intact Intact Intact Destroyed Destroyed Destroyed Destroyed	1911-1923 1924-1933 1934-present In question	No shade.
HEATING/ VENTILATION PLUMBING:	Radiators Vents/Fans Sink/Toilet/Urinal Other:	Intact Intact Intact Intact Destroyed Destroyed Destroyed Destroyed	1911-1923 1924-1933 1934-present In question	
MISCELLANEOUS:		Good Fair Poor Destroyed	1911-1923 1924-1933 1934-present In question	
SUMMARY:		Good Fair Poor Destroyed	1911-1923 1924-1933 1934-present In question	ARCHITECTURAL SIGNIFICANCE: Most Some Minor Negligible

PHOTOGRAPHS:

① view North

ROOM NO.



ELLIS ISLAND EXISTING CONDITION SURVEY

Staff House

page: 388

ROOM NO: 201/2018

LAST KNOWN USE: Bedroom

SQUARE FEET: 170

CEILING HEIGHT:

DATE: 26 Nov. 1985

	FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	☒ Tile/Concrete ☒ Resilient ☒ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	
BASE:	☒ Tile/Concrete ☒ Resilient ☒ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	
WALLS:	☒ Plaster ☐ Partitions ☐ Tile Wainscot ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	
CEILING:	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	
DOORS/ OPENINGS:	☒ Wood/~~Glass~~ Panelled ☐ Wood Veneer ☐ Galvanized Metal ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	3 wood 5-panel doors.
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☒ CML/Sconce 2 ☒ Other: 1	☐ Intact ☐ Intact ☐ Intact ☐ Intact	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	1 Standard staff House lamp (w/ metal rod and shade) shade is on floor. 2 ghosts removed sconces.
HEATING/ VENTILATION PLUMBING:	☒ Radiators 1 ☐ Vents/Fans ☐ Sink/Toilet/Urinal ☐ Other:	☒ Intact ☐ Intact ☐ Intact ☐ Intact	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	
MISCELLANEOUS:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	201 B closet: 2 upper shelves. Lower shelves and clothes rod missing.
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	ARCHITECTURAL SIGNIFICANCE: ☐ Most ☒ Some ☐ Minor ☐ Negligible

PHOTOGRAPHS: ① View West ② View South ③ View North ④ View East

ROOM NO. 201



ROOM NO: 201A	LAST KNOWN USE: Ballroom	SQUARE FEET: 51	CEILING HEIGHT:	DATE: 26 Nov. 1985	
	FINISHES:	CONDITION:	DATE:	NOTES:	
FLOOR:	☒ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	Hexagonal white tile.	
BASE:	☒ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question		
WALLS:	☐ Plaster ☐ Partitions ☒ Tile Wainscot ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	Picture rail.	
CEILING:	☒ Plaster ☐ Acoustic panels ☒ Cove ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question		
DOORS/ OPENINGS:	☒ Wood/ ~~Glass~~ Panelled ☐ Wood Veneer ☐ Galvanized Metal ☐ Other:	☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	5-panel door	
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☒ CML Sconce ☐ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	1 CML w/ broken shade. 1 oval sconce, no shade. unusual light switch: knob end.	
HEATING/ VENTILATION PLUMBING:	☒ Radiators ☐ Vents/Fans ☒ Sink/Toilet/Urinal ☐ Other: tubs	☐ Intact ☐ Intact ☒ Intact ☒ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	radiator removed. 1 wall mounted sink w/ faucets. 1 toilet w/ tank. 1 tub w/ shower pan tile backpiece.	
MISCELLANEOUS:		☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	1 cupboard over sink.	
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	ARCHITECTURAL SIGNIFICANCE:	Most Some ☒ Minor Negligible

PHOTOGRAPHS: ① View South



② View East



ELLIS ISLAND				EXISTING CONDITION SURVEY				Staff House				page: 392			
ROOM NO: 202		LAST KNOWN USE: Bedroom		SQUARE FEET: 148		CEILING HEIGHT:		DATE:							
		FINISHES:		CONDITION:		DATE:		NOTES:							
FLOOR:		Tile/Concrete		Good		1911-1923									
		Resilient		Fair		1924-1933									
		Wood		Poor		1934-present									
		Other:		Destroyed		In question									
BASE:		Tile/Concrete		Good		1911-1923									
		Resilient		Fair		1924-1933									
		Wood		Poor		1934-present									
		Other:		Destroyed		In question									
WALLS:		Plaster		Good		1911-1923		picture rail. Some cracking of plaster.							
		Partitions		Fair		1924-1933									
		Tile Mainscot		Poor		1934-present									
		Other:		Destroyed		In question									
CEILING:		Plaster		Good		1911-1923									
		Acoustic panels		Fair		1924-1933									
		Cove		Poor		1934-present									
		Other		Destroyed		In question									
DOORS/ OPENINGS:		Wood/Glass-Panelled		Good		1911-1923									
		Wood Veneer		Fair		1924-1933									
		Galvanized Metal		Poor		1934-present									
		Other:		Destroyed		In question									
LIGHTING:		Incandescent/Type A		Intact		1911-1923		1 standard metal rod lamp. ghosts and plates of 2 removed sconces.							
		Incandescent/Type B		Intact		1924-1933									
		CML/Sconce		Intact		1934-present									
		Other:		Destroyed		In question									
HEATING/ VENTILATION PLUMBING:		Radiators		Intact		1911-1923									
		Vents/Fans		Intact		1924-1933									
		Sink/Toilet/Urinal		Intact		1934-present									
		Other:		Destroyed		In question									
MISCELLANEOUS:				Good		1911-1923		Venetian blinds. Fabric valance over N. window. (Floral) 2 built-in closets w/ mirrored doors: mirrors shattered. shelves in closets removed. (202 A - 202 B).							
				Fair		1924-1933									
				Poor		1934-present									
				Destroyed		In question									
SUMMARY:				Good		1911-1923		ARCHITECTURAL SIGNIFICANCE:							
				Fair		1924-1933									
				Poor		1934-present									
				Destroyed		In question									
								Most							
								Some							
								Minor							
								Negligible							

PHOTOGRAPHS: ① view West

② view East

ROOM NO. 202



PHOTOGRAPHS: ③ View North

④ Valence, North Window

ROOM NO. 202




PHOTOGRAPHS:

ROOM NO.

ELLIS ISLAND EXISTING CONDITION SURVEY				Staff House		page: 576			
ROOM NO: 203	LAST KNOWN USE: Bathroom		SQUARE FEET: 52	CEILING HEIGHT: 8'-11 1/4" DATE: 26 Nov. 1985					
	FINISHES:	CONDITION:	DATE:	NOTES:					
FLOOR:	☒ Tile/Concrete Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	Hexagonal white tiles.					
BASE:	☒ Tile/Concrete Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question						
WALLS:	☐ Plaster ☐ Partitions ☒ Tile Wainscot ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question						
CEILING:	☒ Plaster ☐ Acoustic panels ☒ Cove ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	cracking, NE corner.					
DOORS/ OPENINGS:	☒ Wood/Glass Panelled ☐ Wood Veneer ☐ Galvanized Metal ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	Marble window and door sills. Dimpled glass windows					
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☒ CML Sconce 1 ☐ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	1 oval ceramic sconce, no shade.					
HEATING/ VENTILATION PLUMBING:	☒ Radiators 1 ☐ Vents/Fans ☒ Sink/toilet/Urinal 1 ☒ Other: tub	☒ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	1 toilet w/ tank. 1 tub w/ shower + tiled back + tiled foot shelf. 1 wall mounted sink w/ faucets.					
MISCELLANEOUS:		☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☒ In question	Cream colored cloth window shade. 1 hanging wood cabinet w/ mirror. 1 toilet paper roller.					
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	ARCHITECTURAL SIGNIFICANCE:					
				Most Some Minor Negligible					

PHOTOGRAPHS: ① view North




② toilet, SE corner.



ELLIS ISLAND EXISTING CONDITION SURVEY				Staff House		page: 398			
ROOM NO: 204	LAST KNOWN USE: Bedroom		SQUARE FEET: 164	CEILING HEIGHT:	DATE: 26 Nov. 1985				
	FINISHES:	CONDITION:	DATE:	NOTES:					
FLOOR:	☐ Tile/Concrete ☒ Resilient ☒ Wood ☐ Other:	☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	Weathered surface.					
BASE:	☐ Tile/Concrete ☐ Resilient ☒ Wood ☐ Other:	☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	Some deterioration due to weathering thru opened windows.					
WALLS:	☒ Plaster ☐ Partitions ☐ Tile Wainscot ☐ Other:	☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question						
CEILING:	☒ Plaster ☐ Acoustic panels ☒ Cove ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question						
DOORS/ OPENINGS:	☒ Wood/ ~~Glass~~ Panelled ☐ Wood Veneer ☐ Galvanized Metal ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	Door had hinged upper panel. Hooks on back of door. Venturian blinds: E. window. Drapery rod: N. window.					
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☒ CML ~~Scence~~ 2 ☒ Other: 1	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☒ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	ghosts of 2 removed sconces. 1 standard picture - shade detached, on floor.					
HEATING/ VENTILATION PLUMBING:	☒ Radiators / ☐ Vents/Fans ☐ Sink/Toilet/Urinal ☐ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question						
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question						
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	ARCHITECTURAL SIGNIFICANCE:		☐ Most ☒ Some ☐ Minor ☐ Negligible			

PHOTOGRAPHS: ① view East ② view West ③ view North ④ view South



ROOM NO: 205	LAST KNOWN USE: Bedroom	SQUARE FEET: 161	CEILING HEIGHT:	DATE: 26 Nov. 1985
	FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	Tile/Concrete Resilient Wood Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	
BASE:	Tile/Concrete Resilient Wood Other:	☒ Good ☒ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	
WALLS:	☒ Plaster Partitions Tile Wainscot Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	picture rail.
CEILING:	☒ Plaster Acoustic panels Cove Other:	☒ Good ☒ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	Fairly significant exposure of structural tile: E and.
DOORS/ OPENINGS:	☒ Wood/~~Glass~~-Panelled Wood Veneer Galvanized Metal Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	5-panel door to Hall - w/ hinged top panel. 5-panel door to closet.
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B CML/Sconce Other: 1	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	Standard fixture: rod w/ dish.
HEATING/ VENTILATION PLUMBING:	☒ Radiators 1 Vents/Fans Sink/Toilet/Urinal Other:	☐ Intact ☒ Destroyed ☐ Intact ☐ Destroyed ☐ Intact ☐ Destroyed ☐ Intact ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	radiator removed.
MISCELLANEOUS:		☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	closet: clothes rod; hooks on door. Removed lower rod. Removed upper shelf. (205A)
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☒ 1924-1933 ☒ 1934-present ☐ In question	ARCHITECTURAL SIGNIFICANCE: Most ☒ Some ☐ Minor ☐ Negligible

PHOTOGRAPHS: ① view Northwest




② view East



ELLIS ISLAND EXISTING CONDITION SURVEY Staff House page: 40Z			
ROOM NO: 206/207		LAST KNOWN USE: Bedroom	SQUARE FEET: 328
		CEILING HEIGHT:	DATE: 25 Nov. 1985
	FINISHES:	CONDITION:	DATE:
FLOOR:	☐ Tile/Concrete	☐ Good	☒ 1911-1923
	☒ Resilient	☒ Fair	☐ 1924-1933
	☒ Wood	☐ Poor	☐ 1934-present
	☐ Other:	☐ Destroyed	☐ In question
BASE:	☐ Tile/Concrete	☐ Good	☒ 1911-1923
	☐ Resilient	☒ Fair	☐ 1924-1933
	☒ Wood	☐ Poor	☐ 1934-present
	☐ Other:	☐ Destroyed	☐ In question
WALLS:	☒ Plaster	☐ Good	☒ 1911-1923
	☐ Partitions	☒ Fair	☐ 1924-1933
	☐ Tile Wainscot	☐ Poor	☐ 1934-present
	☐ Other:	☐ Destroyed	☐ In question
CEILING:	☒ Plaster	☐ Good	☒ 1911-1923
	☐ Acoustic panels	☒ Fair	☐ 1924-1933
	☒ Cove	☐ Poor	☐ 1934-present
	☐ Other:	☐ Destroyed	☐ In question
DOORS/ OPENINGS:	☒ Wood/ ~~Glass~~ Panelled	☐ Good	☒ 1911-1923
	☐ Wood Veneer	☒ Fair	☐ 1924-1933
	☐ Galvanized Metal	☐ Poor	☐ 1934-present
	☐ Other:	☐ Destroyed	☐ In question
LIGHTING:	☐ Incandescent/Type A	☐ Intact	☐ 1911-1923
	☐ Incandescent/Type B	☐ Intact	☐ 1924-1933
	☐ CML/Sconce	☐ Intact	☐ 1934-present
	☐ Other:	☐ Intact	☐ In question
HEATING/ VENTILATION PLUMBING:	☒ Radiators 2	☒ Intact	☒ 1911-1923
	☐ Vents/Fans	☐ Intact	☐ 1924-1933
	☐ Sink/Toilet/Urinal	☐ Intact	☐ 1934-present
	☐ Other:	☐ Intact	☐ In question
MISCELLANEOUS:	☐	☐ Good	☐ 1911-1923
	☐	☒ Fair	☐ 1924-1933
	☐	☐ Poor	☒ 1934-present
	☐	☐ Destroyed	☐ In question
SUMMARY:	☒	☐ Good	☒ 1911-1923
	☐	☐ Fair	☐ 1924-1933
	☐	☐ Poor	☒ 1934-present
	☐	☐ Destroyed	☐ In question
ARCHITECTURAL SIGNIFICANCE:			Most ☒ Some ☐ Minor ☐ Negligible
NOTES:			joint where wall was removed.
			E. wall - cloth wall covering, "Wall-Tex" type. Overpainted w/ blue.
			ghost of removed wall.
			1 5-panel door, w. wall.
			Built-in closet w/ cupboards above and side cupboard: S.W. wall. (207A).

PHOTOGRAPHS: ① View North



② View South



ROOM NO.

PHOTOGRAPHS: ③ wall covering, East wall

④ closet, west wall

ROOM NO. 206/207



PHOTOGRAPHS:

ROOM NO.

ELLIS ISLAND

EXISTING CONDITION SURVEY

Staff House

page: 406

ROOM NO: 208

LAST KNOWN USE: Bathroom

SQUARE FEET: 52

CEILING HEIGHT: 8'-10³/₄"

DATE: 26 Nov. 1985

	FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	☒ Tile/Concrete ☒ Resilient ☐ Wood ☐ Other:	☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
BASE:	☒ Tile/Concrete ☒ Resilient ☐ Wood ☐ Other:	☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
WALLS:	☒ Plaster ☒ Partitions ☒ Tile Wainscot ☐ Other:	☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	Wall paper: silver and cream - underwater design. Tile painted over.
CEILING:	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	
DOORS/ OPENINGS:	☒ Wood/Glass Panelled ☐ Wood Veneer ☐ Galvanized Metal ☐ Other:	☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	5-panel door window has marble sill and dimpled glass.
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☒ CML Sconce ☐ Other:	☐ Intact ☐ Intact ☒ Intact ☐ Intact ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	wall-mounted fixture, bulb points downward.
HEATING/ VENTILATION PLUMBING:	☒ Radiators ☐ Vents/Fans ☒ Sink/Toilet/Urinal ☒ Other: tub	☐ Intact ☐ Intact ☒ Intact ☐ Intact ☐ Destroyed	☒ 1911-1923 ☒ 1924-1933 ☒ 1934-present ☐ In question	1 wall - hung sink w/ faucet. 1 toilet base - no tank. 1 tub w/ tile back area.
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	shelves hung over sink. 2 metal drinking glass holders on each side of sink (dominated chrome finish over brass).
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☒ 1924-1933 ☒ 1934-present ☐ In question	ARCHITECTURAL SIGNIFICANCE: ☐ Most ☐ Some ☒ Minor ☐ Negligible

② wallpaper + scone, E. wall

ROOM NO. 208



PHOTOGRAPHS: ① view South

ELLIS ISLAND				EXISTING CONDITION SURVEY				Staff House				page: 408			
ROOM NO: 209		LAST KNOWN USE: Bedroom		SQUARE FEET: 145		CEILING HEIGHT:		DATE: 26 Nov. 1985							
		FINISHES:		CONDITION:		DATE:		NOTES:							
FLOOR:		☒ ☐ ☐ ☒ ☐ Tile/Concrete Resilient Wood Other:		☒ ☐ ☐ ☐ ☐ Good Fair Poor Destroyed		☒ ☐ ☐ ☐ ☐ 1911-1923 1924-1933 1934-present In question		Ghost of removed picture rail.							
BASE:		☒ ☐ ☐ ☒ ☐ Tile/Concrete Resilient Wood Other:		☒ ☐ ☐ ☐ ☐ Good Fair Poor Destroyed		☒ ☐ ☐ ☐ ☐ 1911-1923 1924-1933 1934-present In question		Ghost of removed picture rail.							
WALLS:		☒ ☐ ☐ ☐ ☐ Plaster Partitions Tile Wainscot Other:		☒ ☐ ☐ ☐ ☐ Good Fair Poor Destroyed		☒ ☐ ☐ ☐ ☐ 1911-1923 1924-1933 1934-present In question		Cracking/ cracking of surface.							
CEILING:		☒ ☐ ☐ ☒ ☐ Plaster Acoustic panels Cove Other		☒ ☐ ☐ ☐ ☐ Good Fair Poor Destroyed		☒ ☐ ☐ ☐ ☐ 1911-1923 1924-1933 1934-present In question		2 5-panel doors - painted blue. Venetian blinds.							
DOORS/ OPENINGS:		☒ ☐ ☐ ☐ ☐ Wood/Glass Panelled Wood Veneer Galvanized Metal Other:		☒ ☐ ☐ ☐ ☐ Good Fair Poor Destroyed		☒ ☐ ☐ ☐ ☐ 1911-1923 1924-1933 1934-present In question		ghosts of 2 sconces. E and W. walls.							
LIGHTING:		☐ ☐ ☐ ☐ ☐ Incandescent/Type A Incandescent/Type B CML Sconce 2 Other:		☐ ☐ ☐ ☒ ☐ Intact Intact Intact Intact Destroyed		☒ ☐ ☐ ☐ ☐ 1911-1923 1924-1933 1934-present In question		radiators removed; pipes remain.							
HEATING/ VENTILATION PLUMBING:		☒ ☐ ☐ ☐ ☐ Radiators Vents/Fans Sink/Toilet/Urinal Other:		☒ ☐ ☐ ☐ ☐ Intact Intact Intact Intact Destroyed		☒ ☐ ☐ ☐ ☐ 1911-1923 1924-1933 1934-present In question		closet w/ 1 shelf, S.E. corner. (209A).							
MISCELLANEOUS:				☐ ☐ ☐ ☐ ☒ Good Fair Poor Destroyed		☐ ☐ ☒ ☐ ☐ 1911-1923 1924-1933 1934-present In question									
SUMMARY:				☒ ☐ ☐ ☐ ☐ Good Fair Poor Destroyed		☒ ☐ ☐ ☐ ☐ 1911-1923 1924-1933 1934-present In question		ARCHITECTURAL SIGNIFICANCE: Most ☒ Some ☒ Minor ☒ Negligible ☐							

ROOM NO. 209

PHOTOGRAPHS: ① View North ② View East ③ View South ④ View West



ELLIS ISLAND EXISTING CONDITION SURVEY				Staff House		page: 410			
ROOM NO: 210/210B		LAST KNOWN USE: Bedroom		SQUARE FEET: 174		CEILING HEIGHT:			
						DATE: 26 Nov 1985			
	FINISHES:	CONDITION:	DATE:	NOTES:					
FLOOR:	☒ Tile/Concrete	☒ Good	☒ 1911-1923						
	☐ Resilient	☐ Fair	☐ 1924-1933						
	☒ Wood	☐ Poor	☐ 1934-present						
	☐ Other:	☐ Destroyed	☐ In question						
BASE:	☐ Tile/Concrete	☐ Good	☒ 1911-1923	Corner raised where pipe for radiator enters room.					
	☐ Resilient	☒ Fair	☐ 1924-1933						
	☒ Wood	☐ Poor	☐ 1934-present						
	☐ Other:	☐ Destroyed	☐ In question						
WALLS:	☒ Plaster	☒ Good	☒ 1911-1923	Ghost of removed picture rail some delineation of finish coat; s. wall.					
	☐ Partitions	☐ Fair	☐ 1924-1933						
	☐ Tile Wainscot	☐ Poor	☐ 1934-present						
	☐ Other:	☐ Destroyed	☐ In question						
CEILING:	☒ Plaster	☒ Good	☒ 1911-1923	Cragging/cracking.					
	☐ Acoustic panels	☐ Fair	☐ 1924-1933						
	☐ Cove	☐ Poor	☐ 1934-present						
	☐ Other:	☐ Destroyed	☐ In question						
DOORS/ OPENINGS:	☒ Wood/Glass Panelled	☐ Good	☒ 1911-1923	3 5-panel doors. Venetian blinds.					
	☐ Wood Veneer	☒ Fair	☐ 1924-1933						
	☐ Galvanized Metal	☐ Poor	☐ 1934-present						
	☐ Other:	☐ Destroyed	☐ In question						
LIGHTING:	☐ Incandescent/Type A	☐ Intact	☐ 1911-1923	Ghosts of 2, possibly 3 sconces.					
	☐ Incandescent/Type B	☐ Intact	☐ 1924-1933						
	☒ CML/Sconce	☐ Intact	☐ 1934-present						
	☐ Other:	☐ Intact	☒ In question						
HEATING/ VENTILATION PLUMBING:	☒ Radiators	☒ Intact	☐ 1911-1923						
	☐ Vents/Fans	☐ Intact	☐ 1924-1933						
	☐ Sink/Toilet/Urinal	☐ Intact	☒ 1934-present						
	☐ Other:	☐ Intact	☐ In question						
MISCELLANEOUS:	☐	☐ Good	☐ 1911-1923	210 B: Addition of closet w/ 2 upper shelves and 1 lower shelf for shoes. Clothes rods and hooks.					
	☐	☐ Fair	☐ 1924-1933						
	☐	☐ Poor	☒ 1934-present						
	☐	☐ Destroyed	☐ In question						
SUMMARY:	☒	☒ Good	☒ 1911-1923	ARCHITECTURAL 210					
	☐	☐ Fair	☐ 1924-1933						
	☐	☐ Poor	☒ 1934-present						
	☐	☐ Destroyed	☐ In question						
				SIGNIFICANCE:		210 B			
						☒ Most ☒ Some ☒ Minor ☒ Negligible			

PHOTOGRAPHS: ① View North ② View South ③ View East ④ View West


ROOM NO. 210



ROOM NO: 21DA LAST KNOWN USE: Bathroom SQUARE FEET: 53 CEILING HEIGHT: DATE: 26 Nov. 1985

	FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	☒ Tile/Concrete ☒ Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	asphalt
BASE:	☒ Tile/Concrete ☒ Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	asphalt. Some areas detached.
WALLS:	☐ Plaster ☐ Partitions ☒ Tile Mainscot ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	Tile overpainted. Silver wallpaper with flowers & waterfowl - on plaster above Mainscot.
CEILING:	☒ Plaster ☐ Acoustic panels ☒ Cove ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	some delamination
DOORS/ OPENINGS:	☒ Wood/Glass Panelled ☐ Wood Veneer ☐ Galvanized Metal ☐ Other:	☐ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	5 - panel door
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☒ CML Sconce ☐ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	1911-1923 1924-1933 1934-present In question	with shade.
HEATING/ VENTILATION PLUMBING:	☒ Radiators ☐ Vents/Fans ☒ Sink/Toilet/Urinal ☒ Other: tubs	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	1911-1923 1924-1933 1934-present In question	1 toilet w/ tank 1 wall-hung sink w/ faucets. 1 tub w/ curved front, curtain rod.
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	2 glass holders as 208. 1 hanging cupboard as 208 w/ central mirror.
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	ARCHITECTURAL SIGNIFICANCE: Most ☐ Some ☐ Minor ☒ Negligible ☐

② view Northwest



PHOTOGRAPHS: ① view East



ELLIS ISLAND

EXISTING CONDITION SURVEY

Staff House

page: 414

ROOM NO: H201

LAST KNOWN USE: Hall

SQUARE FEET: 68

CEILING HEIGHT: 8'-11"

DATE: 25 Nov. 1985

	FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	Tile/Concrete Resilient Wood Other:	Good Fair Poor Destroyed	1911-1923 1924-1933 1934-present In question	
BASE:	Tile/Concrete Resilient Wood Other:	Good Fair Poor Destroyed	1911-1923 1924-1933 1934-present In question	
WALLS:	Plaster Partitions Tile Wainscot Other:	Good Fair Poor Destroyed	1911-1923 1924-1933 1934-present In question	Picture rail. Chair rail.
CEILING:	Plaster Acoustic panels Cove Other:	Good Fair Poor Destroyed	1911-1923 1924-1933 1934-present In question	
DOORS/OPENINGS:	Wood/Glass Panelled Wood Veneer Galvanized Metal Other:	Good Fair Poor Destroyed	1911-1923 1924-1933 1934-present In question	4 5-panel wood doors.
LIGHTING:	Incandescent/Type A Incandescent/Type B CML/Sconce Other:	Intact Intact Intact Intact Destroyed Destroyed Destroyed Destroyed	1911-1923 1924-1933 1934-present In question	
HEATING/VENTILATION/PLUMBING:	Radiators Vents/Fans Sink/Toilet/Urinal Other:	Intact Intact Intact Intact Destroyed Destroyed Destroyed Destroyed	1911-1923 1924-1933 1934-present In question	
MISCELLANEOUS:		Good Fair Poor Destroyed	1911-1923 1924-1933 1934-present In question	Clset: Plaster walls and ceiling. fitted w deep shelves. CML. Double pronged clothes hook.
SUMMARY:		Good Fair Poor Destroyed	1911-1923 1924-1933 1934-present In question	ARCHITECTURAL SIGNIFICANCE: Most Some Minor Negligible

PHOTOGRAPHS: ① view West, closet ② view West

③ view East, stair

ROOM NO.



ROOM NO: H201A

LAST KNOWN USE: Hall


SQUARE FEET: 86

CEILING HEIGHT:

DATE: 26 Nov. 1985

	FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	Tile/Concrete	☒ Good	☒ 1911-1923	
	Resilient	☐ Fair	☐ 1924-1933	
	Wood	☐ Poor	☐ 1934-present	
	Other:	☐ Destroyed	☐ In question	
BASE:	Tile/Concrete	☒ Good	☒ 1911-1923	
	Resilient	☐ Fair	☐ 1924-1933	
	Wood	☐ Poor	☐ 1934-present	
	Other:	☐ Destroyed	☐ In question	
WALLS:	Plaster	☒ Good	☒ 1911-1923	Picture rail.
	Partitions	☐ Fair	☐ 1924-1933	
	Tile Wainscot	☐ Poor	☐ 1934-present	
	Other:	☐ Destroyed	☐ In question	
CEILING:	Plaster	☒ Good	☒ 1911-1923	
	Acoustic panels	☐ Fair	☐ 1924-1933	
	Cove	☐ Poor	☐ 1934-present	
	Other:	☐ Destroyed	☐ In question	
DOORS/ OPENINGS:	Wood/ ~~Glass~~ Panelled	☒ Good	☒ 1911-1923	6 5-panel doors, panelled jambs.
	Wood Veneer	☒ Fair	☐ 1924-1933	
	Galvanized Metal	☐ Poor	☐ 1934-present	
	Other:	☐ Destroyed	☐ In question	
LIGHTING:	Incandescent/Type A	☐ Intact	☒ 1911-1923	glass globe.
	Incandescent/Type B	☐ Intact	☐ 1924-1933	
	CMU/Sconce 1	☐ Intact	☐ 1934-present	
	Other:	☒ Destroyed	☐ In question	
HEATING/ VENTILATION PLUMBING:	Radiators	☐ Intact	☐ 1911-1923	
	Vents/Fans	☐ Intact	☐ 1924-1933	
	Sink/Toilet/Urinal	☐ Intact	☒ 1934-present	
	Other:	☐ Intact	☐ In question	
MISCELLANEOUS:		☐ Good	☐ 1911-1923	1 circuit panel box: "#339" in brass on top.
		☐ Fair	☐ 1924-1933	
		☐ Poor	☐ 1934-present	
		☒ Destroyed	☐ In question	
SUMMARY:		☒ Good	☒ 1911-1923	ARCHITECTURAL SIGNIFICANCE:
		☐ Fair	☐ 1924-1933	
		☐ Poor	☒ 1934-present	
		☐ Destroyed	☐ In question	
			☐ Most	
			☒ Some	
			☐ Minor	
			☐ Negligible	

PHOTOGRAPHS: ① view North



② view South



ELLIS ISLAND EXISTING CONDITION SURVEY

Staff House

page: 418

ROOM NO: H201B

LAST KNOWN USE: Hall

SQUARE FEET: 93

CEILING HEIGHT: 8'-11"

DATE: 25 Nov. 1985

	FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	☐ Tile/Concrete ☒ Resilient ☐ Wood ☐ Other:	☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	
BASE:	☐ Tile/Concrete ☐ Resilient ☒ Wood ☐ Other:	☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	
WALLS:	☒ Plaster ☐ Partitions ☐ Tile Wainscot ☐ Other:	☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	Doorway to 206 unfilled. Ghost of removed picture rail.
CEILING:	☒ Plaster ☐ Acoustic panels ☒ Cove ☐ Other:	☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	
DOORS/ OPENINGS:	☒ Wood/ ~~Glass~~ Panelled ☐ Wood Veneer ☐ Galvanized Metal ☐ Other:	☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	5 5-panel doors.
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☒ CML/Sconce / ☐ Other:	☐ Intact ☐ Intact ☒ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
HEATING/ VENTILATION PLUMBING:	☐ Radiators ☐ Vents/Fans ☐ Sink/Toilet/Urinal ☐ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	1 c. 1950's sideboard sitting in hall.
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☒ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	ARCHITECTURAL SIGNIFICANCE: ☐ Most ☒ Some ☐ Minor ☐ Negligible

PHOTOGRAPHS: ① view South



ELLIS ISLAND EXISTING CONDITION SURVEY

Staff House

page: 420

ROOM NO: S01 LAST KNOWN USE: Staircase SQUARE FEET:

CEILING HEIGHT:

DATE: 11/26/85

DESCRIPTION:

General:

First floor central hall stairway. Stair serves the second-floor with two runs and one mid-floor landing. Stair structure is pre-cast concrete with iron balustrade and wood handrail. An arched three bay window lights the landing.

Good Condition: General rusting of metal surfaces.

Floor:

Treads are concrete with panelled outer stringer. Each tread is individually carpeted with maroon carpeting.

Condition: Good condition.

Base:

Wood.

Condition: Surface abrasion.

Walls:

Painted plaster with wood chair rail.

Condition: Good condition.

Ceiling:

Painted plaster with coffered ceilings over stair runs.

Condition: Good condition.

Openings:

One three bay arched window located at mid-floor landing. Fitted with a quilted valance and venetian blinds.

SUMMARY:

XX Good
Fair
Poor
Destroyed

ARCHITECTURAL SIGNIFICANCE:



XX Most
Some
Minor
Negligible

PHOTOGRAPHS:

① View East

② Newel post


ROOM NO. 501



PHOTOGRAPHS: ③ panelled stringer.

④ carpeted treads


ROOM NO. 501



PHOTOGRAPHS:


ROOM NO.

IMMIGRANT BUILDING



ROOM NO: 101 A, B, C,	LAST KNOWN USE: NPS office	SQUARE FEET: 258	CEILING HEIGHT: 258	DATE: 6 Dec. 1985	
	FINISHES:	CONDITION:	DATE:	NOTES:	
FLOOR:	☒ Tile/Concrete Resilient ☒ Wood ☒ Other:	☒ Good ☒ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	Carpet over composite sheet-board. Remains in place.	
BASE:	☐ Tile/Concrete Resilient ☐ Wood ☒ Other: asphalt	☐ Good ☐ Fair ☒ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	Not on partition walls.	
WALLS:	☒ Plaster ☒ Partitions ☐ Tile Mainscot ☐ Other:	☒ Good ☐ Fair ☒ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	101A, E wall: severe surface chemical reaction and deterioration (with crusting, possible efflorescence). All partitions, good cond.	
CEILING:	☒ Plaster ☒ Acoustic panels ☐ Cove ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question		
DOORS/ OPENINGS:	☒ Wood/Glass Panelled ☒ Wood Veneer ☐ Galvanized Metal ☐ Other:	☐ Good ☒ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	Doors removed from partition walls to 101c and 101D.	
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☐ CFL/Sconce ☒ Other: fluorescent	☐ Intact ☐ Intact ☐ Intact ☒ Destroyed	1911-1923 1924-1933 1934-present In question		
HEATING/ VENTILATION PLUMBING:	☒ Radiators ☐ Vents/Fans ☐ Sink/Toilet/Urinal ☐ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☒ Destroyed	1911-1923 1924-1933 1934-present In question		
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	Door signage from H101: "VOCATIONAL"	
SUMMARY:		☐ Good ☒ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	ARCHITECTURAL SIGNIFICANCE:	☐ Most ☐ Some ☒ Minor ☐ Negligible

PHOTOGRAPHS: ① 101A, view SW. ② 101B, view S. ③ 101D, view S. ④ 101D, NE ROOM NO. 101/A, EXC 1



PHOTOGRAPHS: ⑤ 101c, view S.E. ⑥ 101c, South ⑦ 101c, North ROOM NO. 101c



PHOTOGRAPHS:

ROOM NO.

ROOM NO: 102	LAST KNOWN USE: Bathroom	SQUARE FEET: 37	CEILING HEIGHT:	DATE:	NOTES:
FLOOR:	FINISHES: ☒ Tile/Concrete Resilient ☐ Wood ☐ Other: CONDITION: ☒ Good ☐ Fair ☐ Poor ☐ Destroyed			1911-1923 1924-1933 ☒ 1934-present In question	
BASE:	FINISHES: ☒ Tile/Concrete Resilient ☐ Wood ☐ Other: CONDITION: ☒ Good ☐ Fair ☐ Poor ☐ Destroyed			1911-1923 1924-1933 ☒ 1934-present In question	
WALLS:	FINISHES: ☒ Plaster Partitions ☒ Tile Wainscot ☐ Other: CONDITION: ☒ Good ☐ Fair ☐ Poor ☐ Destroyed			1911-1923 1924-1933 ☒ 1934-present In question	Plaster highly deteriorated around windows
CEILING:	FINISHES: ☒ Plaster ☒ Acoustic panels ☐ Cove ☐ Other: CONDITION: ☒ Good ☐ Fair ☐ Poor ☐ Destroyed			1911-1923 1924-1933 ☒ 1934-present In question	Water stains.
DOORS/ OPENINGS:	FINISHES: ☒ Wood/Glass Panelled ☒ Wood Veneer ☐ Galvanized Metal ☐ Other: CONDITION: ☒ Good ☐ Fair ☐ Poor ☐ Destroyed			1911-1923 1924-1933 ☒ 1934-present In question	ghost of plaque on door.
LIGHTING:	FINISHES: ☐ Incandescent/Type A ☐ Incandescent/Type B ☐ CML/Sconce ☒ Other: bathroom st. CONDITION: ☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed			1911-1923 1924-1933 ☒ 1934-present In question	Hanging lamp: chain intact fluted glass shade destroyed.
HEATING/ VENTILATION PLUMBING:	FINISHES: ☒ Radiators ☐ Vents/Fans ☒ Sink/Toilet/Urinal ☐ Other: tub CONDITION: ☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed			1911-1923 1924-1933 ☒ 1934-present In question	sink and toilet obscured by stored artifacts.
MISCELLANEOUS:				1911-1923 1924-1933 1934-present In question	Mirror w/ white painted wood frame.
SUMMARY:				1911-1923 1924-1933 ☒ 1934-present In question	ARCHITECTURAL SIGNIFICANCE: Most Some ☒ Minor Negligible

PHOTOGRAPHS: ① View East



ROOM NO: 103

LAST KNOWN USE: *Huber's quarters*

SQUARE FEET: 301

CEILING HEIGHT:

DATE:

2 Jan. 1986

	FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	☒ Tile/Concrete ☒ Resilient <i>rolled</i> ☐ Wood ☐ Other:	☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
BASE:	☒ ~~Tile/Concrete~~ ☒ Resilient ☐ Wood ☐ Other:	☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
WALLS:	☒ Plaster ☐ Partitions ☐ Tile Wainscot ☐ Other:	☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
CEILING:	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
DOORS/ OPENINGS:	☐ Wood/Glass Panelled ☐ Wood Veneer ☐ Galvanized Metal ☐ Other:	☐ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	<i>Window covered with plywood.</i>
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☐ CFL/Sconce ☒ Other: <i>fluorescent</i>	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
HEATING/ VENTILATION PLUMBING:	☒ Radiators ☐ Vents/Fans ☐ Sink/Toilet/Urinal ☐ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	<i>Small wood panel in N. wall, lower right-hand corner - behind tub in 102.</i>
SUMMARY:		☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	ARCHITECTURAL SIGNIFICANCE: ☐ Most ☐ Some ☒ Minor ☐ Negligible

② View Southeast



PHOTOGRAPHS: ① View North



ROOM NO: 104

LAST KNOWN USE: Officers Quarters

SQUARE FEET: 285


CEILING HEIGHT:

DATE:

2 Jan. 1986

	FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	☒ Tile/Concrete ☒ Resilient <i>rolled</i> ☐ Wood ☐ Other:	☐ Good ☐ Fair ☒ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
BASE:	☒ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
WALLS:	☒ Plaster ☐ Partitions ☐ Tile Mainscot ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
CEILING:	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other	☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	Water stains and hole.
DOORS/ OPENINGS:	☒ Wood/Glass Panelled ☐ Wood Veneer 1 ☐ Galvanized Metal ☐ Other:	☐ Good ☐ Fair ☒ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	Missing lower.
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☐ CML/Sconce ☒ Other: <i>fluorescent</i>	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☒ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
HEATING/ VENTILATION PLUMBING:	☒ Radiators ☐ Vents/Fans ☐ Sink/Toilet/Urinal ☐ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	
SUMMARY:		☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	ARCHITECTURAL SIGNIFICANCE:
				Most Some Minor Negligible

PHOTOGRAPHS: ① View South



② View North




ROOM NO: 104A LAST KNOWN USE: *Storage closed* SQUARE FEET: 47 CEILING HEIGHT: DATE: 2 Jan. 1986

	FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	☒ Tile/Concrete ☒ Resilient <i>rolled</i> ☐ Wood ☐ Other:	☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
BASE:	☒ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
WALLS:	☒ Plaster ☐ Partitions ☐ Tile Wainscot ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
CEILING:	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
DOORS/ OPENINGS:	☒ Wood/Glass Panelled ☐ Wood Veneer ☐ Galvanized Metal ☐ Other:	☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	<i>"Domitory 2" stenciled in black on outside of door.</i>
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☐ CML/Sconce ☒ Other: <i>fluorescent</i>	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
HEATING/ VENTILATION PLUMBING:	☐ Radiators ☐ Vents/Fans ☐ Sink/Toilet/Urinal ☐ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	ARCHITECTURAL SIGNIFICANCE: Most Some ☒ Minor Negligible


PHOTOGRAPHS: ① View South

ROOM NO. 104A



ROOM NO: 104B	LAST KNOWN USE: Bathroom	SQUARE FEET: 43	CEILING HEIGHT: 8	DATE: 2 Jan. 1986	NOTES:
FLOOR:	FINISHES: ☒ Tile ☒ Concrete ☐ Resilient ☐ Wood ☐ Other:	CONDITION: ☒ Good ☐ Fair ☐ Poor ☐ Destroyed	DATE: 1911-1923 1924-1933 1934-present In question		
BASE:	FINISHES: ☒ Tile ☒ Concrete ☐ Resilient ☐ Wood ☐ Other:	CONDITION: ☒ Good ☐ Fair ☐ Poor ☐ Destroyed	DATE: 1911-1923 1924-1933 1934-present In question		
WALLS:	Plaster ☐ Partitions ☒ Tile Wainscot ☐ Other:	CONDITION: ☒ Good ☐ Fair ☐ Poor ☐ Destroyed	DATE: 1911-1923 1924-1933 1934-present In question		
CEILING:	Plaster ☒ Acoustic panels ☐ Cove ☐ Other:	CONDITION: ☒ Good ☐ Fair ☐ Poor ☐ Destroyed	DATE: 1911-1923 1924-1933 1934-present In question		
DOORS/ OPENINGS:	Wood/Glass Panelled ☒ Wood Veneer ☐ Galvanized Metal ☐ Other:	CONDITION: ☒ Good ☐ Fair ☐ Poor ☐ Destroyed	DATE: 1911-1923 1924-1933 1934-present In question		
LIGHTING:	Incandescent/Type A ☐ Incandescent/Type B ☐ CML/Sconce ☒ Other:	Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	DATE: 1911-1923 1924-1933 1934-present In question		Standard Immigrant Building bathroom light fixture w/ fluted glass shade.
HEATING/ VENTILATION PLUMBING:	Radiators ☒ Vents/Fans ☒ Sink/Toilet/Urinal ☒ Other: Shower	Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	DATE: 1911-1923 1924-1933 1934-present In question		1 toilet. 1 slop sink: wall mounted. 1 shower: plumbing destroyed.
MISCELLANEOUS:		Good ☐ Fair ☐ Poor ☐ Destroyed	DATE: 1911-1923 1924-1933 1934-present In question		2 mirrors w/ wood frames. 1 rusted paper towel dispenser.
SUMMARY:	FINISHES: ☒ Good ☐ Fair ☐ Poor ☐ Destroyed	CONDITION: ☒ Good ☐ Fair ☐ Poor ☐ Destroyed	DATE: 1911-1923 1924-1933 1934-present In question		ARCHITECTURAL SIGNIFICANCE: Most Some Minor Negligible

PHOTOGRAPHS: ① View South



② View North



PHOTOGRAPHS: ③ Standard Immigrant Building bathroom light fixture. ROOM NO. 104B



PHOTOGRAPHS:

ROOM NO.

ROOM NO: 105

LAST KNOWN USE: *others*
Quarters

SQUARE FEET: 290

CEILING HEIGHT:

DATE: 16 Dec. 1985

	FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	☒ Tile/Concrete ☒ Resilient <i>rolled</i> ☐ Wood Other:	Good ☒ Fair Poor Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
BASE:	☒ Tile/Concrete ☒ Resilient ☐ Wood Other:	Good ☒ Fair Poor Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
WALLS:	☒ Plaster Partitions Tile Wainscot Other:	Good ☒ Fair Poor Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
CEILING:	☒ Plaster ☒ Acoustic panels Cove Other:	Good ☒ Fair Poor Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
DOORS/ OPENINGS:	☒ Wood/Glass Panelled ☒ Wood Veneer Galvanized Metal Other:	Good ☒ Fair Poor Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	<i>Standard door, lowire boarded over. Window covered with plywood.</i>
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☐ CML/Sconce ☒ Other: <i>fluorescent</i>	Intact Destroyed Destroyed Destroyed Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
HEATING/ VENTILATION PLUMBING:	☒ Radiators Vents/Fans Sink/Toilet/Urinal Other:	Intact Destroyed Destroyed Destroyed Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
MISCELLANEOUS:		Good Fair Poor Destroyed	1911-1923 1924-1933 1934-present In question	
SUMMARY:		Good ☒ Fair Poor Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	ARCHITECTURAL SIGNIFICANCE: Most Some ☒ Minor Negligible

② View North



① View South



ELLIS ISLAND EXISTING CONDITION SURVEY

Immigrant Building

page: 44-4

ROOM NO: 105A

LAST KNOWN USE:

*Storage
closed*

SQUARE FEET: 47

CEILING HEIGHT:

DATE:

16 Dec. 1985

	FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	☒ Tile/Concrete ☒ Resilient <i>rolled</i> ☐ Wood ☐ Other:	☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
BASE:	☒ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
WALLS:	☒ Plaster ☐ Partitions ☐ Tile Wainscot ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
CEILING:	☐ Plaster ☒ Acoustic panels ☐ Cove ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
DOORS/ OPENINGS:	☐ Wood/Glass Panelled ☒ Wood Veneer 2 ☐ Galvanized Metal ☐ Other:	☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	"Dormitory 1" stenciled in black. Door to 105 - Louvre boarded over.
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☐ CML/Sconce ☒ Other: <i>fluorescent</i>	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
HEATING/ VENTILATION PLUMBING:	☐ Radiators ☐ Vents/Fans ☐ Sink/Toilet/Urinal ☐ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	ARCHITECTURAL SIGNIFICANCE: Most Some ☒ Minor Negligible

① View South

PHOTOGRAPHS:



ROOM NO: 105B

LAST KNOWN USE: Bathroom

SQUARE FEET: 43

CEILING HEIGHT:

DATE: 16 Dec. 1985

	FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	☒ Tile/Concrete Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
BASE:	☒ Tile/Concrete Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
WALLS:	☐ Plaster Partitions ☒ Tile Mainscot ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	plaster above wainscot-fair cond.
CEILING:	☒ Plaster ☒ Acoustic panels ☐ Cove ☐ Other	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	waterstained.
DOORS/ OPENINGS:	☒ Wood/Glass Panelled ☒ Wood Veneer ☐ Galvanized Metal ☐ Other:	☐ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☐ CML/Sconce ☒ Other:	Intact Intact Intact Intact	Destroyed Destroyed Destroyed Destroyed	Standard bathroom.
HEATING/ VENTILATION PLUMBING:	☐ Radiators ☐ Vents/Fans ☒ Sink/Toilet/Urinal ☒ Other: shower	Intact Intact Intact Intact	Destroyed Destroyed Destroyed Destroyed	1 sink. 1 toilet.
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☒ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	1 curtain, white with floral print.
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	ARCHITECTURAL SIGNIFICANCE: Most Some ☒ Minor Negligible

PHOTOGRAPHS: ① View North



② View South



ROOM NO:	LAST KNOWN USE:	SQUARE FEET:	CEILING HEIGHT:	DATE:	NOTES:
106	Officers Quarters	290		2 Jan 1986	
FLOOR:	FINISHES:	CONDITION:	DATE:		
	☒ Tile/Concrete ☒ Resilient rolled ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question		
BASE:	☒ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question		
WALLS:	☒ Plaster ☐ Partitions ☐ Tile Mainscot ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question		Painted finish gone.
CEILING:	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question		
DOORS/ OPENINGS:	☒ Wood/Glass Panelled ☐ Wood Veneer ☐ Galvanized Metal ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question		
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☐ CML/Sconce ☒ Other: fluorescent 2	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question		
HEATING/ VENTILATION PLUMBING:	☒ Radiators ☐ Vents/Fans ☐ Sink/Toilet/Urinal ☐ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question		
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question		3 green, rolled windows shades. Red plaque on E. wall.
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question		ARCHITECTURAL SIGNIFICANCE:
				☐ Most ☐ Some ☒ Minor ☐ Negligible	

PHOTOGRAPHS: ① View South




② View North



ROOM NO:	LAST KNOWN USE:	SQUARE FEET:	CEILING HEIGHT:	DATE:	NOTES:
106A	storage closet	47		2 Jan. 1986	
FLOOR:	FINISHES:	CONDITION:	DATE:		
	☒ Tile/Concrete ☒ Resilient rolled ☐ Wood ☐ Other:	☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question		
BASE:	FINISHES:	CONDITION:	DATE:		
	☒ Tile/Concrete ☒ Resilient ☐ Wood ☐ Other:	☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question		
WALLS:	FINISHES:	CONDITION:	DATE:		
	☒ Plaster ☐ Partitions ☐ Tile Wainscot ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question		
CEILING:	FINISHES:	CONDITION:	DATE:		
	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question		
DOORS/ OPENINGS:	FINISHES:	CONDITION:	DATE:		
	☐ Wood/Glass Panelled ☒ Wood Veneer 2 ☐ Galvanized Metal ☒ Other:	☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	screen door to 106, in addition to wood veneer door.	
LIGHTING:	FINISHES:	CONDITION:	DATE:		
	☐ Incandescent/Type A ☐ Incandescent/Type B ☐ CML/Scqnce ☒ Other: fluorescent	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question		
HEATING/ VENTILATION PLUMBING:	FINISHES:	CONDITION:	DATE:		
	☐ Radiators ☐ Vents/Fans ☐ Sink/Toilet/Urinal ☐ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question		
MISCELLANEOUS:	FINISHES:	CONDITION:	DATE:		
	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	Built-in loft w/ shelves.	
SUMMARY:	FINISHES:	CONDITION:	DATE:	ARCHITECTURAL SIGNIFICANCE:	Most Some Minor Negligible
	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	ARCHITECTURAL SIGNIFICANCE:	☐ Most ☐ Some ☒ Minor ☐ Negligible

PHOTOGRAPHS: ① View South



ELLIS ISLAND

EXISTING CONDITION SURVEY

Immigrant Building

page: 452

ROOM NO: 106B

LAST KNOWN USE: Bathroom

SQUARE FEET: 43

CEILING HEIGHT: 43

DATE: 2 Jan. 1986

	FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	☒ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
BASE:	☒ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
WALLS:	☐ Plaster ☐ Partitions ☒ Tile Wainscot ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
CEILING:	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
DOORS/ OPENINGS:	☒ Wood/Glass Panelled ☐ Wood Veneer ☐ Galvanized Metal ☐ Other:	☐ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	standard bathroom fixture; shade destroyed.
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☐ CML/Sconce ☒ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact	1911-1923 1924-1933 ☒ 1934-present In question	
HEATING/ VENTILATION PLUMBING:	☒ Radiators ☐ Vents/Fans ☒ Sink/Toilet/ ~~Urinal~~ ☒ Other: shower	☐ Intact ☐ Intact ☐ Intact ☐ Intact	1911-1923 1924-1933 ☒ 1934-present In question	1 sink 1 toilet 1 shower without plumbing.
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	ARCHITECTURAL SIGNIFICANCE: ☐ Most ☐ Some ☒ Minor ☐ Negligible



ROOM NO: 107

LAST KNOWN USE: Officers Quarters

SQUARE FEET: 285

CEILING HEIGHT:

DATE: 2 Jan. 1986

	FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	☒ Tile/Concrete ☒ Resilient rolled ☐ Wood ☐ Other:	☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
BASE:	☒ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
WALLS:	☒ Plaster ☐ Partitions ☐ Tile Wainscot ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
CEILING:	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	Water stains.
DOORS/ OPENINGS:	☒ Wood/Glass Panelled ☐ Wood Veneer ☐ Galvanized Metal ☐ Other:	☐ Good ☐ Fair ☒ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	2" plywood 5 point star nailed to outside of door.
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☐ CML/Sconce ☒ Other: fluorescent	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
HEATING/ VENTILATION PLUMBING:	☒ Radiators ☐ Vents/Fans ☐ Sink/Toilet/Urinal ☐ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	ARCHITECTURAL SIGNIFICANCE: Most Some Minor Negligible

PHOTOGRAPHS:

① View South

② View North

ROOM NO. 107



PHOTOGRAPHS: ③ View Southwest

ROOM NO. 107



PHOTOGRAPHS:

ROOM NO.

ROOM NO: 107A	LAST KNOWN USE: <i>Storage closet</i>	SQUARE FEET: 47	CEILING HEIGHT: DATE: 2 Jan. 1986	NOTES:
FLOOR:	FINISHES:	CONDITION:	DATE:	NOTES:
	☒ Tile/Concrete ☒ Resilient <i>rolled</i> ☐ Wood ☐ Other:	Good Fair Poor Destroyed	1911-1923 1924-1933 1934-present In question	
BASE:	☒ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:	Good Fair Poor Destroyed	1911-1923 1924-1933 1934-present In question	
WALLS:	☒ Plaster ☐ Partitions ☐ Tile Wainscot ☐ Other:	Good Fair Poor Destroyed	1911-1923 1924-1933 1934-present In question	
CEILING:	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	Good Fair Poor Destroyed	1911-1923 1924-1933 1934-present In question	
DOORS/ OPENINGS:	☒ Wood/Glass Panelled ☒ Wood Veneer ☐ Galvanized Metal ☐ Other:	Good Fair Poor Destroyed	1911-1923 1924-1933 1934-present In question	"Boundary 5" stenciled on outside of door. Lower missing. Coarsely woven cotton cloth over opening of missing lower.
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☐ CML/Sconce ☒ Other: <i>fluorescent</i>	Intact Intact Intact Intact Destroyed Destroyed Destroyed Destroyed	1911-1923 1924-1933 1934-present In question	
HEATING/ VENTILATION PLUMBING:	☐ Radiators ☐ Vents/Fans ☐ Sink/Toilet/Urinal ☐ Other:	Intact Intact Intact Intact Destroyed Destroyed Destroyed Destroyed	1911-1923 1924-1933 1934-present In question	
MISCELLANEOUS:		Good Fair Poor Destroyed	1911-1923 1924-1933 1934-present In question	
SUMMARY:		Good Fair Poor Destroyed	1911-1923 1924-1933 1934-present In question	ARCHITECTURAL SIGNIFICANCE:
				Most Some ☒ Minor Negligible

PHOTOGRAPHS: ① View South

ROOM NO. 107A



ROOM NO: 107B LAST KNOWN USE: Bathroom SQUARE FEET: 43 CEILING HEIGHT: DATE: 2 Jan. 1986

	FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	☒ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
BASE:	☒ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
WALLS:	☐ Plaster ☐ Partitions ☒ Tile Wainscot ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
CEILING:	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
DOORS/ OPENINGS:	☒ Wood/Glass Panelled ☐ Wood Veneer ☐ Galvanized Metal ☐ Other:	☐ Good ☐ Fair ☐ Poor ☒ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☐ CFL/Sconce ☒ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	Standard bathroom hanging fixture
HEATING/ VENTILATION PLUMBING:	☒ Radiators ☐ Vents/Fans ☒ Sink/Toilet/ ~~Unit~~ ☒ Other: shower	☐ Intact ☐ Intact ☐ Intact ☐ Intact	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	1 square, central pedestal sink.
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	1 rusted paper towel dispenser.
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	ARCHITECTURAL SIGNIFICANCE: Most Some ☒ Minor Negligible

PHOTOGRAPHS:

① View North

② View South

ROOM NO. 107B



ROOM NO: 108	LAST KNOWN USE: Officers Quarters	SQUARE FEET: 301	CEILING HEIGHT: 301	DATE: 2 Jan. 1986	NOTES:
FLOOR:	FINISHES: ☒ Tile/Concrete ☒ Resilient ☐ Wood ☐ Other:	CONDITION: ☐ Good ☐ Fair ☒ Poor ☐ Destroyed	DATE: 1911-1923 1924-1933 ☒ 1934-present In question		
BASE:	FINISHES: ☒ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:	CONDITION: ☒ Good ☐ Fair ☐ Poor ☐ Destroyed	DATE: 1911-1923 1924-1933 ☒ 1934-present In question		
WALLS:	FINISHES: ☒ Plaster ☐ Partitions ☐ Tile Wainscot ☐ Other:	CONDITION: ☒ Good ☐ Fair ☐ Poor ☐ Destroyed	DATE: 1911-1923 1924-1933 ☒ 1934-present In question		
CEILING:	FINISHES: ☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	CONDITION: ☐ Good ☐ Fair ☒ Poor ☐ Destroyed	DATE: 1911-1923 1924-1933 ☒ 1934-present In question		
DOORS/ OPENINGS:	FINISHES: ☐ Wood/Glass Panelled ☐ Wood Veneer ☐ Galvanized Metal ☐ Other:	CONDITION: ☐ Good ☐ Fair ☐ Poor ☐ Destroyed	DATE: 1911-1923 1924-1933 ☐ 1934-present In question		No doors. Windows broken and boarded over.
LIGHTING:	FINISHES: ☐ Incandescent/Type A ☐ Incandescent/Type B ☐ CML/Sconce ☒ Other: fluorescent	CONDITION: ☐ Intact ☐ Intact ☐ Intact ☐ Intact ☒ Destroyed ☒ Destroyed ☒ Destroyed ☒ Destroyed	DATE: 1911-1923 1924-1933 ☒ 1934-present In question		
HEATING/ VENTILATION PLUMBING:	FINISHES: ☒ Radiators ☐ Vents/Fans ☐ Sink/Toilet/Urinal ☐ Other:	CONDITION: ☐ Intact ☐ Intact ☐ Intact ☐ Intact ☒ Destroyed ☒ Destroyed ☒ Destroyed ☒ Destroyed	DATE: 1911-1923 1924-1933 ☒ 1934-present In question		
MISCELLANEOUS:	FINISHES: ☐ ☐ ☐ ☐	CONDITION: ☐ Good ☐ Fair ☐ Poor ☐ Destroyed	DATE: 1911-1923 1924-1933 ☐ 1934-present In question		
SUMMARY:	FINISHES: ☒ ☐ ☐ ☐	CONDITION: ☒ Good ☐ Fair ☐ Poor ☐ Destroyed	DATE: 1911-1923 1924-1933 ☒ 1934-present In question		ARCHITECTURAL SIGNIFICANCE: Most Some Minor Negligible

PHOTOGRAPHS: ① View South



② View Southwest



PHOTOGRAPHS: (3) View North

ROOM NO. 108



PHOTOGRAPHS:

ROOM NO.

ELLIS ISLAND EXISTING CONDITION SURVEY

Immigrant Building

page: 466

ROOM NO: 109

LAST KNOWN USE: Bathroom

SQUARE FEET: 37

CEILING HEIGHT:

DATE: 2 Jan. 1986

	FINISHES:	CONDITION:	DATE:	NOTES:								
FLOOR:	☒ Tile/Concrete Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question									
BASE:	☒ Tile/Concrete Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question									
WALLS:	☐ Plaster Partitions ☒ Tile Wainscot ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question									
CEILING:	☒ Plaster ☒ Acoustic panels ☐ Cove ☐ Other	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question									
DOORS/ OPENINGS:	☒ Wood/Glass Panelled ☒ Wood Veneer ☐ Galvanized Metal ☐ Other:	☐ Good ☒ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question									
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☐ CML/Sconce ☒ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	Standard bathroom fixture.								
HEATING/ VENTILATION PLUMBING:	☐ Radiators ☐ Vents/Fans ☒ Sink/Toilet/Urinal ☒ Other: Tubs	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	toilet. tub. sink missing.								
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	rusted paper towel dispenser. mirror with wood frame.								
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	ARCHITECTURAL SIGNIFICANCE: <table><tr><td>Most</td><td>Some</td><td>Minor</td><td>Negligible</td></tr><tr><td>☐</td><td>☐</td><td>☒</td><td>☐</td></tr></table>	Most	Some	Minor	Negligible	☐	☐	☒	☐
Most	Some	Minor	Negligible									
☐	☐	☒	☐									

PHOTOGRAPHS: ① View West



② View Northwest



ROOM NO: 110/110A ^{Women's} LAST KNOWN USE: toilet / ^{vestibule}

SQUARE FEET: 177

CEILING HEIGHT:

DATE: 16 Dec. 1985

	FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	☒ Tile/Concrete ☐ Resilient ☐ Wood ☒ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	Vestibule floor = poured stone, as hallway, 110 = tile.
BASE:	☒ Tile/Concrete ☐ Resilient ☐ Wood ☒ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	Vestibule = poured stone, 110 = tile.
WALLS:	☒ Plaster ☐ Partitions ☐ Tile Wainscot ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	
CEILING:	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	
DOORS/ OPENINGS:	☒ Wood/Glass Panelled ☒ Wood Veneer ☐ Galvanized Metal ☐ Other:	☐ Good ☒ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	Vestibule door - plain veneer, no louvre Door to 110 standard, louvre missing.
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☒ (MD)/Sconce ☒ Other: fluorescent	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	1911-1923 1924-1933 1934-present In question	
HEATING/ VENTILATION PLUMBING:	☐ Radiators ☐ Vents/Fans ☒ Sink/Toilet/ ~~Unit~~ ☐ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	1911-1923 1924-1933 1934-present In question	Sinks removed. Toilets may be missing - obscured by storage of artifacts.
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	2 mirrors. 1 rusted paper towel dispenser. Structural glass toilet stalls (white).
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	ARCHITECTURAL SIGNIFICANCE: ☐ Most ☐ Some ☒ Minor ☐ Negligible

PHOTOGRAPHS: ① 110A, View West ② 110, View West ③ 110, View North

ROOM NO. 110/110A



PHOTOGRAPHS: ④ View Southwest

ROOM NO. 110



PHOTOGRAPHS:

ROOM NO.

ROOM NO: 110 B LAST KNOWN USE: Slop room SQUARE FEET: 144 CEILING HEIGHT: DATE: 16 Dec. 1985

	FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	☒ Tile/Concrete ☒ Resilient rolled ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
BASE:	☒ Tile/Concrete ☒ Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
WALLS:	☒ Plaster ☐ Partitions ☐ Tile Mainscot ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
CEILING:	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
DOORS/ OPENINGS:	☒ Wood/Glass Panelled ☒ Wood Veneer ☐ Galvanized Metal ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	Louvre removed from standard door.
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☒ CFL/Sconce ☐ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
HEATING/ VENTILATION PLUMBING:	☐ Radiators ☐ Vents/Fans ☒ Sink/Toilet/Urinal ☐ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	1 slop sink.
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	1 fuse box.
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	ARCHITECTURAL SIGNIFICANCE: ☐ Most ☐ Some ☐ Minor ☒ Negligible

PHOTOGRAPHS: ① view west

ROOM NO. 110B



ROOM NO:	LAST KNOWN USE:	SQUARE FEET:	CEILING HEIGHT:	DATE:	NOTES:
111	NPS staff lounge	88		11 Dec. 1985	
FLOOR:	FINISHES:	CONDITION:	DATE:	NOTES:	
	Tile/Concrete Resilient Wood Other:	Good Fair Poor Destroyed	1911-1923 1924-1933 1934-present In question	finish gone, some warping and staining. Appears struct. sound. Patch in NE section (approx. 5'1/2 x 2'1/2) wood infill?	
	Tile/Concrete Resilient Wood Other:	Good Fair Poor Destroyed	1911-1923 1924-1933 1934-present In question	5'1/2" flat base, stained dark brown, as panelling.	
	Plaster Partitions Tile Wainscot Other: wood panel	Good Fair Poor Destroyed	1911-1923 1924-1933 1934-present In question	Red brown stain, vertical panelling Varied widths.	
	Plaster Acoustic panels Cove Other:	Good Fair Poor Destroyed	1911-1923 1924-1933 1934-present In question	some loss N/W corner. staining, w. wall along windows. wood encased beams.	
	Wood/Glass Panelled Wood Veneer Galvanized Metal Other:	Good Fair Poor Destroyed	1911-1923 1924-1933 1934-present In question	3 pairs double doors. Center doors: South door, removed - replaced w/ 1/2 door with mid-shelf.	
	Incandescent/Type A Incandescent/Type B CML/8conce Other: fluorescent	Intact Intact Intact Intact Destroyed Destroyed Destroyed Destroyed	1911-1923 1924-1933 1934-present In question		
	Radiators Vents/Fans Sink/Toilet/Urinal Other:	Intact Intact Intact Intact	1911-1923 1924-1933 1934-present In question		
		Good Fair Poor Destroyed	1911-1923 1924-1933 1934-present In question	2 fireplaces: N and S. considerable soot staining.	
MISCELLANEOUS:					
SUMMARY:				ARCHITECTURAL SIGNIFICANCE:	
				☒ Most ☐ Some ☐ Minor ☐ Negligible	

PHOTOGRAPHS:

① View South ② View North ③ View South ④ paneling

ROOM NO. 111



PHOTOGRAPHS: ⑤ Door, North end. ⑥ East wall


PHOTOGRAPHS:

⑤ Door, North end.

⑥ East wall

ROOM NO.

111




PHOTOGRAPHS:

ROOM NO.

ROOM NO: 112/112B	LAST KNOWN USE: Toilet, vestibule	SQUARE FEET: 177	CEILING HEIGHT: 16	DATE: Dec. 1985
	FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	☒ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	6" sq. beige matte tile.
BASE:	☒ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	
WALLS:	☐ Plaster ☐ Partitions ☒ Tile Wainscot ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	
CEILING:	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	
DOORS/ OPENINGS:	☐ Wood/Glass Panelled ☐ Wood Veneer ☐ Galvanized Metal ☐ Other:	☐ Good ☐ Fair ☐ Poor ☒ Destroyed missing	1911-1923 1924-1933 1934-present In question	
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☒ CML Sconce ☒ Other: fluorescent	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☒ Destroyed ☒ Destroyed ☒ Destroyed ☒ Destroyed	1911-1923 1924-1933 1934-present In question	Destroyed CML in 112A. 1 fluorescent in 112.
HEATING/ VENTILATION PLUMBING:	☒ Radiators ☐ Vents/Fans ☒ Sink/Toilet/Urinal ☐ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☒ Destroyed ☒ Destroyed ☒ Destroyed ☒ Destroyed	1911-1923 1924-1933 1934-present In question	1 sink - pipes and mounts for 2 more. 3 toilets.
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	Structural glass (white) toilet stalls. 1 rusted paper towel dispenser. wood frame for mirror - mirror missing.
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	ARCHITECTURAL SIGNIFICANCE: ☐ Most ☐ Some ☒ Minor ☐ Negligible

PHOTOGRAPHS: ① View Northwest ② View South ③ View West

ROOM NO. 112



	FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	☒ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
BASE:	☒ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
WALLS:	☒ Plaster Partitions Tile Wainscot Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
CEILING:	☒ Plaster ☒ Acoustic panels Cove Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
DOORS/ OPENINGS:	Wood/Glass Panelled Wood Veneer Galvanized Metal Other:	Good Fair Poor Destroyed	1911-1923 1924-1933 1934-present In question	No door.
LIGHTING:	Incandescent/Type A Incandescent/Type B ☒ CML/Sconce Other:	Intact Intact Intact Intact Destroyed Destroyed Destroyed Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
HEATING/ VENTILATION PLUMBING:	Radiators Vents/Fans ☒ Sink/Toilet/Urinal Other:	Intact Intact Intact Intact Destroyed Destroyed Destroyed Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	1 slop sink.
MISCELLANEOUS:		Good Fair Poor Destroyed	1911-1923 1924-1933 1934-present In question	
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	ARCHITECTURAL SIGNIFICANCE: Most ☐ Some ☐ Minor ☒ Negligible ☒

PHOTOGRAPHS: ① View Southwest



ELLIS ISLAND

EXISTING CONDITION SURVEY

Immigrant Building

page: 48Z-

ROOM NO: 113

LAST KNOWN USE: *Officers' Quarters*

301

CEILING HEIGHT:

DATE: 16 Dec. 1985

FINISHES:		CONDITION:				DATE:	NOTES:
FLOOR:	☒ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:	☒ Good ☒ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question				
BASE:	☒ <u>Tile/Concrete</u> ☐ Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question				
WALLS:	☒ Plaster ☐ Partitions ☐ Tile Wainscot ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question			N. wall, plaster poor - destroyed.	
CEILING:	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	☐ Good ☐ Fair ☒ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question			Water damage. Panels missing in center of ceiling.	
DOORS/ OPENINGS:	☐ Wood/Glass Panelled ☐ Wood Veneer ☐ Galvanized Metal ☐ Other:	☐ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question			No doors. Windows broken and boarded over.	
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☐ CML/Sconce ☒ Other: <i>fluorescent</i>	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question				
HEATING/ VENTILATION PLUMBING:	☒ Radiators ☐ Vents/Fans ☐ Sink/Toilet/Urinal ☐ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question				
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question			Strip of blue wood with clothes hooks on west wall.	
SUMMARY:		☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question			ARCHITECTURAL SIGNIFICANCE:	
						Most Some Minor Negligible	

② view Northwest



① view North



PHOTOGRAPHS:

ROOM NO.


113

ROOM NO: 113A LAST KNOWN USE: Bathroom SQUARE FEET: 43 CEILING HEIGHT: DATE: 16 Dec. 1985

	FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	☒ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
BASE:	☒ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
WALLS:	☐ Plaster ☐ Partitions ☒ Tile Wainscot ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
CEILING:	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	Door missing
DOORS/ OPENINGS:	☐ Wood/Glass Panelled ☐ Wood Veneer ☐ Galvanized Metal ☐ Other:	☐ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	Standard Bathroom - Chain w/ plated glass shade.
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☐ CML/Sconce ☒ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	1 sink 1 toilet 1 tub.
HEATING/ VENTILATION PLUMBING:	☒ Radiators ☐ Vents/Fans ☒ Sink/Toilet/Urinal ☒ Other: Tubs	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	1 mirror w/ white wood frame.
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	ARCHITECTURAL SIGNIFICANCE: Most Some Minor Negligible

PHOTOGRAPHS: ① View West

ROOM NO. 113A



ROOM NO: 114 LAST KNOWN USE: Office/shop SQUARE FEET: 285 CEILING HEIGHT: DATE: 16 Dec. 1985


	FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	☒ Tile/Concrete ☒ Resilient ☐ Wood ☐ Other:	☐ Good ☐ Fair ☐ Poor ☒ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
BASE:	☒ Tile/Concrete ☒ Resilient ☐ Wood ☐ Other:	☐ Good ☐ Fair ☐ Poor ☒ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
WALLS:	☒ Plaster ☐ Partitions ☐ Tile Wainscot ☐ Other:	☒ Good ☐ Fair ☐ Poor ☒ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
CEILING:	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	☐ Good ☒ Fair ☐ Poor ☒ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	Water staining + missing panels near E. wall.
DOORS/ OPENINGS:	☒ Wood/Glass Panelled ☒ Wood Veneer ☐ Galvanized Metal ☐ Other:	☒ Good ☐ Fair ☐ Poor ☒ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	Windows broken and boarded over.
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☐ CML/Sconce ☒ Other: Fluorescent	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☒ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
HEATING/ VENTILATION PLUMBING:	☒ Radiators ☐ Vents/Fans ☐ Sink/Toilet/Urinal ☐ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☒ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☒ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	
SUMMARY:		☐ Good ☒ Fair ☐ Poor ☒ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	ARCHITECTURAL SIGNIFICANCE: ☐ Most ☐ Some ☒ Minor ☐ Negligible

PHOTOGRAPHS:

① View North

② View South


ROOM NO. 114



ROOM NO: 114A LAST KNOWN USE: Storage closet SQUARE FEET: 47 CEILING HEIGHT: DATE: 16 Dec. 1985

	FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	☒ Tile/Concrete ☒ Resilient ☐ Wood ☐ Other:	☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
BASE:	☒ Tile/Concrete ☒ Resilient ☐ Wood ☐ Other:	☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
WALLS:	☒ Plaster ☐ Partitions ☐ Tile Mainscot ☐ Other:	☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
CEILING:	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
DOORS/ OPENINGS:	☐ Wood/Glass Panelled ☒ Wood Veneer ☐ Galvanized Metal ☐ Other:	☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☐ CML/Sconce ☒ Other: fluorescent	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
HEATING/ VENTILATION PLUMBING:	☐ Radiators ☐ Vents/Fans ☐ Sink/Toilet/Urinal ☐ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	1 shelf w/ clothes rod underneath.
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	ARCHITECTURAL SIGNIFICANCE: ☐ Most ☐ Some ☒ Minor ☐ Negligible

PHOTOGRAPHS: ① View North



ROOM NO: 114B LAST KNOWN USE: Toilet SQUARE FEET: 43 CEILING HEIGHT: DATE: 16 Dec. 1995

	FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	☒ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
BASE:	☒ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
WALLS:	☐ Plaster ☐ Partitions ☒ Tile Mainscot ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
CEILING:	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
DOORS/ OPENINGS:	☐ Wood/Glass Panelled ☒ Wood Veneer ☐ Galvanized Metal ☐ Other:	☐ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	door missing.
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☐ CML/Sconce ☒ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	Standard bathroom fixture.
HEATING/ VENTILATION PLUMBING:	☒ Radiators ☐ Vents/Fans ☒ Sink/Toilet/ ~~Urinal~~ ☐ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	1 sink, square, central pedestal. 1 toilet. - shower boxed over + made into platform
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☐ 1934-present In question	1 mirror w/ white wood frame. 1 rusted paper towel dispenser.
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	ARCHITECTURAL SIGNIFICANCE: Most Some ☒ Minor Negligible

PHOTOGRAPHS: ① View South



② View North



ROOM NO: 115 LAST KNOWN USE: *Officer's Quarters* SQUARE FEET: 290 CEILING HEIGHT: DATE: 16 Dec. 1985

	FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	☒ Tile/Concrete ☒ Resilient ☐ Wood ☐ Other:	Good ☒ Fair ☐ Poor Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
BASE:	☒ Tile/Concrete ☒ Resilient ☐ Wood ☐ Other:	Good ☒ Fair ☐ Poor Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
WALLS:	☒ Plaster ☐ Partitions ☐ Tile Wainscot ☐ Other:	Good ☒ Fair ☐ Poor Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
CEILING:	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	Good ☒ Fair ☐ Poor Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	<i>stone water stains.</i>
DOORS/ OPENINGS:	☒ Wood/Glass Panelled ☒ Wood Veneer 2 ☐ Galvanized Metal ☐ Other:	Good ☒ Fair ☐ Poor Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	<i>window boarded over.</i>
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☐ CFL/Sconce ☒ Other: <i>fluorescent</i>	Intact Destroyed Destroyed Destroyed Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
HEATING/ VENTILATION PLUMBING:	☒ Radiators ☒ Vents/Fans ☐ Sink/Toilet/Urinal ☐ Other:	Intact Destroyed Destroyed Destroyed Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
MISCELLANEOUS:		Good Fair Poor Destroyed	1911-1923 1924-1933 1934-present In question	
SUMMARY:		☒ Good ☐ Fair ☐ Poor Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	ARCHITECTURAL SIGNIFICANCE: Most Some Minor Negligible

PHOTOGRAPHS:

① view North

② view East

ROOM NO. 115



ROOM NO: 115A	LAST KNOWN USE: Storage Closet	SQUARE FEET: 47	CEILING HEIGHT: DATE: 16 Dec. 1985	
FINISHES:		CONDITION:	DATE:	NOTES:
FLOOR:	☒ Tile/Concrete ☒ Resilient rolled ☐ Wood ☐ Other:	☒ Good ☒ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
BASE:	☒ Tile/Concrete ☒ Resilient ☐ Wood ☐ Other:	☒ Good ☒ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
WALLS:	☒ Plaster ☐ Partitions ☐ Tile Wainscot ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
CEILING:	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
DOORS/ OPENINGS:	☒ Wood/Glass Panelled ☒ Wood Veneer 2 ☐ Galvanized Metal ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	Lowre missing on door to hallway.
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☐ CML/Sconce ☒ Other: fluorescent 1	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
HEATING/ VENTILATION PLUMBING:	☐ Radiators ☐ Vents/Fans ☐ Sink/Toilet/Urinal ☐ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	Shelf with clothes rod beneath (N.end).
SUMMARY:		☒ Good ☐ Fair ☐ poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	ARCHITECTURAL SIGNIFICANCE: ☐ Most ☐ Some ☒ Minor ☐ Negligible

PHOTOGRAPHS:

ROOM NO.

ELLIS ISLAND			EXISTING CONDITION SURVEY			Immigrant Building			page: 496			
ROOM NO:	115B	LAST KNOWN USE: Bathroom			SQUARE FEET: 43	CEILING HEIGHT:			DATE: 16 Dec. 1985			
		FINISHES:		CONDITION:		DATE:		NOTES:				
FLOOR:		☒ Tile/Concrete	☒ Good	☒ 1911-1923								
		☐ Resilient	☐ Fair	☐ 1924-1933								
		☐ Wood	☐ Poor	☒ 1934-present								
		☐ Other:	☐ Destroyed	☐ In question								
BASE:		☒ Tile/Concrete	☒ Good	☐ 1911-1923								
		☐ Resilient	☐ Fair	☐ 1924-1933								
		☐ Wood	☐ Poor	☒ 1934-present								
		☐ Other:	☐ Destroyed	☐ In question								
WALLS:		☐ Plaster	☒ Good	☐ 1911-1923								
		☐ Partitions	☐ Fair	☐ 1924-1933								
		☒ Tile Wainscot	☐ Poor	☒ 1934-present								
		☐ Other:	☐ Destroyed	☐ In question								
CEILING:		☐ Plaster	☒ Good	☐ 1911-1923								
		☒ Acoustic panels	☐ Fair	☐ 1924-1933								
		☐ Cove	☐ Poor	☒ 1934-present								
		☐ Other:	☐ Destroyed	☐ In question								
DOORS/ OPENINGS:		☐ Wood/Glass Panelled	☒ Good	☐ 1911-1923								
		☒ Wood Veneer	☐ Fair	☐ 1924-1933								
		☐ Galvanized Metal	☐ Poor	☒ 1934-present								
		☐ Other:	☐ Destroyed	☐ In question								
LIGHTING:		☐ Incandescent/Type A	☐ Intact	☐ Destroyed					Standard bathroom light : glass shade destroyed.			
		☐ Incandescent/Type B	☐ Intact	☐ Destroyed								
		☐ CFL/Sconce	☐ Intact	☐ Destroyed								
		☒ Other:	☐ Intact	☐ Destroyed								
HEATING/ VENTILATION PLUMBING:		☒ Radiators	☐ Intact	☐ Destroyed					shower has curtain rod - unusual for Immigrant Bldg.			
		☐ Vents/Fans	☐ Intact	☐ Destroyed								
		☒ Sink/Toilet/Urinal	☐ Intact	☐ Destroyed								
		☒ Other:	☐ Intact	☐ Destroyed								
MISCELLANEOUS:		☐	☐ Good	☐ 1911-1923								
		☐	☐ Fair	☐ 1924-1933								
		☐	☐ Poor	☐ 1934-present								
		☐	☐ Destroyed	☐ In question								
SUMMARY:		☒ Good	☐ 1911-1923					ARCHITECTURAL SIGNIFICANCE:				
		☐ Fair	☐ 1924-1933									
		☐ Poor	☒ 1934-present									
		☐ Destroyed	☐ In question									
								Most		Some		
								☐		☐		
								☒		☒		
								Minor		Negligible		

PHOTOGRAPHS:

① view South

② view North

ROOM NO. 115B



PHOTOGRAPHS: (3) View West

ROOM NO. 115B



PHOTOGRAPHS:

ROOM NO.

ELLIS ISLAND EXISTING CONDITION SURVEY				Immigrant Building		page: 500
ROOM NO: 116	LAST KNOWN USE: Officers Quarters	SQUARE FEET: 290	CEILING HEIGHT:	DATE: 16 Dec. 1985		
	FINISHES:	CONDITION:	DATE:	NOTES:		
FLOOR:	☒ Tile/Concrete ☒ Resilient rolled ☐ Wood ☐ Other:	☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question			
BASE:	☒ ~~Tile/Concrete~~ ☐ Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question			
WALLS:	☒ Plaster ☐ Partitions ☐ Tile Wainscot ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question			
CEILING:	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question			
DOORS/ OPENINGS:	☒ Wood/Glass Panelled ☐ Wood Veneer 2 ☐ Galvanized Metal ☐ Other:	☐ Good ☒ Fair ☒ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	Standard, with louvre.		
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☐ CML/Sconce ☒ Other: Fluorescent	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☒ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question			
HEATING/ VENTILATION PLUMBING:	☒ Radiators ☐ Vents/Fans ☐ Sink/Toilet/Urinal ☐ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question			
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	Green cloth rolled window shade for 3-part window.		
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	ARCHITECTURAL SIGNIFICANCE:	☐ Most ☐ Some ☒ Minor ☐ Negligible	

PHOTOGRAPHS: ① view North

② standard lowered door.

ROOM NO. 116



ROOM NO: 116A	LAST KNOWN USE: Storage closet	SQUARE FEET: 47	CEILING HEIGHT: 16	DATE: Dec. 1985
FINISHES:		CONDITION:	DATE:	NOTES:
FLOOR:	☒ Tile/Concrete ☒ Resilient ☐ Wood ☐ Other:	☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
BASE:	☒ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
WALLS:	☒ Plaster ☐ Partitions ☐ Tile Wainscot ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
CEILING:	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
DOORS/OPENINGS:	☒ Wood/Glass Panelled ☒ Wood Veneer 2 ☐ Galvanized Metal ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☐ CML/Sconce ☒ Other: fluorescent	☐ Intact ☐ Intact ☐ Intact ☐ Intact	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
HEATING/VENTILATION/PLUMBING:	☐ Radiators ☐ Vents/Fans ☐ Sink/Toilet/Urinal ☐ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact	☐ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	
MISCELLANEOUS:			☐ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	Shelf with clothes rod. (N. end).
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	ARCHITECTURAL SIGNIFICANCE: Most Some ☒ Minor Negligible

PHOTOGRAPHS: ① View North





ELLIS ISLAND				EXISTING CONDITION SURVEY				Immigrant Building				page: 504			
ROOM NO: 116B		LAST KNOWN USE: Bathroom		SQUARE FEET: 43		CEILING HEIGHT:		DATE: 16 Dec. 1985							
		FINISHES:		CONDITION:		DATE:		NOTES:							
FLOOR:		☒ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed		1911-1923 1924-1933 1934-present In question		Square beige mat tile.							
BASE:		☒ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed		1911-1923 1924-1933 1934-present In question									
WALLS:		☐ Plaster ☐ Partitions ☒ Tile Wainscot ☐ Other:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed		1911-1923 1924-1933 1934-present In question									
CEILING:		☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:		☐ Good ☐ Fair ☒ Poor ☐ Destroyed		1911-1923 1924-1933 1934-present In question									
DOORS/ OPENINGS:		☒ Wood/Glass Panelled ☒ Wood Veneer ☐ Galvanized Metal ☐ Other:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed		1911-1923 1924-1933 1934-present In question				chain with bulb, shade destroyed.					
LIGHTING:		☐ Incandescent/Type A ☐ Incandescent/Type B ☐ CML/Sconce ☒ Other:		☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed		1911-1923 1924-1933 1934-present In question									
HEATING/ VENTILATION PLUMBING:		☒ Radiators ☐ Vents/Fans ☒ Sink/Toilet/Urinal ☒ Other: Shower		☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed		1911-1923 1924-1933 1934-present In question									
MISCELLANEOUS:				☐ Good ☐ Fair ☐ Poor ☐ Destroyed		1911-1923 1924-1933 1934-present In question		mirror with wood frame, over sink. Paper towel dispenser - rusted.							
SUMMARY:				☒ Good ☐ Fair ☐ Poor ☐ Destroyed		1911-1923 1924-1933 1934-present In question		ARCHITECTURAL SIGNIFICANCE:		Most Some Minor Negligible					

PHOTOGRAPHS: ① View East

② View South

ROOM NO. 116B



PHOTOGRAPHS: ③ Door



④ Radiator



ROOM NO. 116B

PHOTOGRAPHS:

ROOM NO.

ROOM NO: 117

LAST KNOWN USE: Officers' Quarters

SQUARE FEET: 285

CEILING HEIGHT: DATE: 16 Dec. 1985

	FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	Tile/Concrete ☒ Resilient <i>rolled</i> ☐ Wood ☐ Other:	Good ☒ Fair ☐ Poor Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
BASE:	☒ <u>Tile/Concrete</u> ☐ Resilient ☐ Wood ☐ Other:	Good ☒ Fair ☐ Poor Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
WALLS:	☒ Plaster Partitions Tile Wainscot ☐ Other:	Good ☐ Fair ☐ Poor Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
CEILING:	☒ Plaster Acoustic panels Cove ☐ Other:	Good ☐ Fair ☒ Poor Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	Severe water damage, area of panels missing.
DOORS/ OPENINGS:	☒ Wood/Glass Panelled ☐ Wood Veneer <i>2</i> Galvanized Metal ☐ Other:	Good ☒ Fair ☐ Poor Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	Windows boarded with plywood.
LIGHTING:	Incandescent/Type A Incandescent/Type B CML/Sconce ☒ Other: <i>fluorescent</i> <i>2</i>	Intact Destroyed Intact Destroyed Intact Destroyed Intact Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
HEATING/ VENTILATION PLUMBING:	☒ Radiators Vents/Fans Sink/Toilet/Urinal ☐ Other:	Intact Destroyed Intact Destroyed Intact Destroyed Intact Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
MISCELLANEOUS:		Good ☐ Fair ☐ Poor Destroyed	1911-1923 1924-1933 ☐ 1934-present In question	
SUMMARY:		Good ☒ Fair ☐ Poor Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	ARCHITECTURAL SIGNIFICANCE: Most ☐ Some ☒ Minor Negligible


PHOTOGRAPHS: ① View East @ North end



ROOM NO: 117A		LAST KNOWN USE: Storage Closet		SQUARE FEET: 47	CEILING HEIGHT:	DATE: 16 Dec. 1985
		FINISHES:	CONDITION:	DATE:	NOTES:	
FLOOR:	☒ Tile/Concrete ☒ Resilient <i>rolled</i> ☐ Wood ☐ Other:	☒ Good ☒ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☒ 1924-1933 ☐ 1934-present ☐ In question			
BASE:	☒ ~~Tile~~ Concrete ☐ Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question			
WALLS:	☒ Plaster ☐ Partitions ☐ Tile Wainscot ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question			
CEILING:	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question			
DOORS/ OPENINGS:	☒ Wood/Glass Panelled ☒ Wood Veneer 2 ☐ Galvanized Metal ☐ Other:	☐ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question			
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☐ CML/Sconce ☒ Other: <i>fluorescent</i>	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question			
HEATING/ VENTILATION PLUMBING:	☐ Radiators ☐ Vents/Fans ☐ Sink/Toilet/Urinal ☐ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question			
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question			
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	ARCHITECTURAL SIGNIFICANCE: ☐ Most ☐ Some ☒ Minor ☐ Negligible		

PHOTOGRAPHS: ① View North

ROOM NO. 117A



ELLIS ISLAND		EXISTING CONDITION SURVEY		Immigrant Building		page: 512	
ROOM NO: 117B	LAST KNOWN USE: Bathroom	SQUARE FEET: 43	CEILING HEIGHT:	DATE: 16 Dec. 1985			
	FINISHES:	CONDITION:	DATE:	NOTES:			
FLOOR:	☒ Tile/Concrete-Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	Square beige matting.			
BASE:	☒ Tile/Concrete-Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question				
WALLS:	☐ Plaster ☐ Partitions ☒ Tile Wainscot ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	Plaster above wainscot in poor condition.			
CEILING:	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question				
DOORS/OPENINGS:	☒ Wood/Glass Panelled ☒ Wood Veneer ☐ Galvanized Metal ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	Hook on inside of door.			
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☐ CFL/Sconce ☒ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	chain with bulb - shade missing.			
HEATING/VENTILATION/PLUMBING:	☒ Radiators ☐ Vents/Fans ☒ Sink/Toilet/Urinal ☒ Other: shower	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	Square central pedestal sink.			
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	Attended under light switch: "22 V.D.C." Paper towel dispenser. Mirror.			
SUMMARY:		☐ Good ☒ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	ARCHITECTURAL SIGNIFICANCE:	☐ Most ☐ Some ☒ Minor ☐ Negligible		

PHOTOGRAPHS: ① View North




② View South



PHOTOGRAPHS: ③ view Northeast

④ view Northwest

ROOM NO. 118



PHOTOGRAPHS:

ROOM NO.

ROOM NO: 119

LAST KNOWN USE: Bathroom


SQUARE FEET: 37

CEILING HEIGHT:

DATE: 16 Dec. 1985

	FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	☒ Tile/ ~~concrete~~ ☐ Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
BASE:	☒ Tile/ ~~concrete~~ ☐ Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
WALLS:	☐ Plaster ☐ Partitions ☒ Tile Wainscot ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	Plaster above wainscot: fair cond.
CEILING:	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	☐ Good ☐ Fair ☒ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	severe water damage.
DOORS/ OPENINGS:	☒ Wood/Glass Panelled ☐ Wood Veneer ☐ Galvanized Metal ☐ Other:	☐ Good ☐ Fair ☐ Poor ☒ Destroyed Missing	1911-1923 1924-1933 ☒ 1934-present In question	
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☐ CML/Sconce ☒ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	Chain w/ bulb. shade missing.
HEATING/ VENTILATION PLUMBING:	☒ Radiators ☒ Vents/Fans ☒ Sink/ ~~Toilet~~ ☒ Other: tub	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	square central pedestal sink.
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	Toilet paper roller. Paper towel dispenser, (rusty). floral print cloth @ window.
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	ARCHITECTURAL SIGNIFICANCE:
				Most Some Minor Negligible

② view west



① view east



PHOTOGRAPHS:

PHOTOGRAPHS: ③ Toilet paper roller

ROOM NO. 119



PHOTOGRAPHS:

ROOM NO.

ELLIS ISLAND			EXISTING CONDITION SURVEY			Immigrant Building			page: 522		
ROOM NO:	120	LAST KNOWN USE:	office			SQUARE FEET:	428		CEILING HEIGHT:	DATE: 16 Dec. 1985	
		FINISHES:	CONDITION:		DATE:	NOTES:					
FLOOR:		☒ Tile <u>Concrete</u> ☐ Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed		1911-1923 1924-1933 ☒ 1934-present In question						
BASE:		☒ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:	☐ Good ☐ Fair ☐ Poor ☒ Destroyed		1911-1923 1924-1933 ☒ 1934-present In question						
WALLS:		☒ Plaster ☐ Partitions ☐ Tile Wainscot ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed		1911-1923 1924-1933 ☒ 1934-present In question						
CEILING:		☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	☐ Good ☐ Fair ☒ Poor ☐ Destroyed		1911-1923 1924-1933 ☒ 1934-present In question						
DOORS/ OPENINGS:		☒ Wood/Glass Panelled ☐ Wood Veneer ☐ Galvanized Metal ☐ Other:	☐ Good ☐ Fair ☒ Poor ☐ Destroyed		1911-1923 1924-1933 ☒ 1934-present In question						
LIGHTING:		☒ Incandescent/Type A ☐ Incandescent/Type B ☐ CML/Sconce ☒ Other: <u>fluorescent</u>	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☒ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed		1911-1923 1924-1933 ☒ 1934-present In question					1 incandescent w/ white glass globe, possibly original fixture.	
HEATING/ VENTILATION PLUMBING:		☒ Radiators ☐ Vents/Fans ☒ Sink/ ~~toilet~~ / ~~urinal~~ ☐ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed		1911-1923 1924-1933 ☒ 1934-present In question					1 well-mounted sink.	
MISCELLANEOUS:			☐ Good ☐ Fair ☒ Poor ☐ Destroyed		1911-1923 1924-1933 ☒ 1934-present In question					Rustled paper towel dispenser.	
SUMMARY:			☐ Good ☐ Fair ☒ Poor ☐ Destroyed		1911-1923 1924-1933 ☒ 1934-present In question					ARCHITECTURAL SIGNIFICANCE:	
										Most Some Minor Negligible	

PHOTOGRAPHS: ① View East ② View West ③ View South ④ View North

ROOM NO. 120



PHOTOGRAPHS: ⑤ sink, southeast-corner. ⑥ light fixture

ROOM NO. 120



PHOTOGRAPHS:

ROOM NO.

ROOM NO: 121

LAST KNOWN USE:

SQUARE FEET:

CEILING HEIGHT:

DATE:

11 Dec. 1985

	FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	Tile/Concrete Resilient Wood Other:	Good Fair Poor Destroyed	1911-1923 1924-1933 1934-present In question	
BASE:	Tile/Concrete Resilient Wood Other:	Good Fair Poor Destroyed	1911-1923 1924-1933 1934-present In question	
WALLS:	Plaster Partitions Tile Wainscot Other:	Good Fair Poor Destroyed	1911-1923 1924-1933 1934-present In question	
CEILING:	Plaster Acoustic panels Cove Other:	Good Fair Poor Destroyed	1911-1923 1924-1933 1934-present In question	
DOORS/ OPENINGS:	Wood/Glass Panelled Wood Veneer Galvanized Metal Other:	Good Fair Poor Destroyed	1911-1923 1924-1933 1934-present In question	
LIGHTING:	Incandescent/Type A Incandescent/Type B CML/Sconce Other:	Intact Intact Intact Intact Destroyed Destroyed Destroyed Destroyed	1911-1923 1924-1933 1934-present In question	
HEATING/ VENTILATION PLUMBING:	Radiators Vents/Fans Sink/Toilet/Urinal Other:	Intact Intact Intact Intact Destroyed Destroyed Destroyed Destroyed	1911-1923 1924-1933 1934-present In question	
MISCELLANEOUS:		Good Fair Poor Destroyed	1911-1923 1924-1933 1934-present In question	Door locked; room inaccessible.
SUMMARY:		Good Fair Poor Destroyed	1911-1923 1924-1933 1934-present In question	ARCHITECTURAL SIGNIFICANCE:
				Most Some Minor Negligible

PHOTOGRAPHS:

ROOM NO.

ROOM NO: 122 LAST KNOWN USE: Office SQUARE FEET: 428 CEILING HEIGHT: DATE: 11 Dec. 1985

	FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	☒ Tile/Concrete ☒ Resilient <i>rolled</i> ☐ Wood ☐ Other:	Good ☒ Fair ☐ Poor Destroyed	1911-1923 1924-1933 1934-present In question	
BASE:	☒ ~~Tile~~ /Concrete ☐ Resilient ☐ Wood ☐ Other:	Good ☒ Fair ☐ Poor Destroyed	1911-1923 1924-1933 1934-present In question	
WALLS:	☒ Plaster ☐ Partitions ☐ Tile Wainscot ☐ Other:	Good ☒ Fair ☐ Poor Destroyed	1911-1923 1924-1933 1934-present In question	
CEILING:	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	Good ☒ Fair ☐ Poor Destroyed	1911-1923 1924-1933 1934-present In question	
DOORS/ OPENINGS:	☒ Wood/Glass Panelled ☒ Wood Veneer ☐ Galvanized Metal ☐ Other:	Good ☒ Fair ☐ Poor Destroyed	1911-1923 1924-1933 1934-present In question	4 extant 1 removed and infilled to 120. "Office" stenciled on door from H101.
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☐ CML/Sconce ☒ Other:	Destroyed Destroyed Destroyed Destroyed Intact Intact Intact Intact	1911-1923 1924-1933 1934-present In question	4 fluorescent. 1 chain w/ base, no shade.
HEATING/ VENTILATION PLUMBING:	☒ Radiators ☐ Vents/Fans ☒ Sink/ ~~Toilet/Urinal~~ ☐ Other:	Destroyed Destroyed Destroyed Destroyed Intact Intact Intact Intact	1911-1923 1924-1933 1934-present In question	1 wall-mounted sink w/ faucets.
MISCELLANEOUS:		Good ☐ Fair ☐ Poor Destroyed	1911-1923 1924-1933 1934-present In question	closet: door blocked by furniture.
SUMMARY:		Good ☒ Fair ☐ Poor Destroyed	1911-1923 1924-1933 1934-present In question	ARCHITECTURAL SIGNIFICANCE:
				Most Some Minor Negligible

PHOTOGRAPHS: ① View North ② View Northwest ③ View East

ROOM NO. 122



ROOM NO: H101

LAST KNOWN USE: Entryway

SQUARE FEET: 583

CEILING HEIGHT:

DATE: 11 Dec. 1985


	FINISHES:	CONDITION:	DATE:	NOTES:								
FLOOR:	☒ Tile/Concrete Resilient ☐ Wood ☒ Other: <i>terrazzo</i>	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	stairs: <i>terrazzo</i> - gray with dark borders.								
BASE:	☐ Tile/Concrete Resilient ☐ Wood ☒ Other: <i>terrazzo</i>	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question									
WALLS:	☒ Plaster Partitions ☐ Tile Wainscot ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	Some damage to walls in corners. Walls are <i>terrazzo</i> in stairwell up to main floor level.								
CEILING:	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	One missing panel.								
DOORS/ OPENINGS:	☐ Wood/Glass Panelled ☒ Wood Veneer ☒ Galvanized Metal ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	One pair 16" light french doors, w/ 4-light side lights.								
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☐ CFL/Sconce ☒ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☒ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	2 fluorescent. 2 emergency flood lights.								
HEATING/ VENTILATION PLUMBING:	☒ Radiators ☐ Vents/Fans ☐ Sink/Toilet/Urinal ☐ Other:	☒ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	2 radiators inset in wall niches, above stairwell.								
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ present In question	Fire extinguisher: "Allied Fire + Safety Co. Red Bank, N.J."								
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	ARCHITECTURAL SIGNIFICANCE: <table><tr><td>Most</td><td>Some</td><td>Minor</td><td>Negligible</td></tr><tr><td>☐</td><td>☒</td><td>☐</td><td>☐</td></tr></table>	Most	Some	Minor	Negligible	☐	☒	☐	☐
Most	Some	Minor	Negligible									
☐	☒	☐	☐									

PHOTOGRAPHS: ① View West, stairs. ② View West from center. ROOM NO. H101



ROOM NO. H101

PHOTOGRAPHS: ⑤ View Northwest, radiator niche



PHOTOGRAPHS: ③ View East

④ Main doors.

ROOM NO. H101



ROOM NO: 1102 (North) LAST KNOWN USE: Corridor SQUARE FEET: 409 CEILING HEIGHT:

	FINISHES:	CONDITION:	DATE:	NOTES:								
FLOOR:	☒ Tile/Concrete Resilient ☐ Wood ☒ Other: Terrazzo	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present In question	Gray with darker border, brass dividing strips.								
BASE:	☐ Tile/Concrete Resilient ☐ Wood ☒ Other: Terrazzo	☐ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present In question	Dark gray.								
WALLS:	☒ Plaster Partitions ☐ Tile Wainscot ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present In question	"Shelter" sign on wall								
CEILING:	☐ Plaster ☒ Acoustic panels ☐ Cove ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present In question									
DOORS/ OPENINGS:	☒ Wood/Glass Panelled ☐ Wood Veneer ☐ Galvanized Metal ☐ Other:	☐ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present In question	New plywood door at S. end. Stenciled never door to H107 - "M132" Over door to 502 - "M108" "Employees only" Over door to H11.								
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☐ CML/Sconce ☒ Other: fluorescent's 2	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present In question									
HEATING/ VENTILATION PLUMBING:	☐ Radiators ☐ Vents/Fans ☐ Sink/Toilet/Urinal ☐ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☐ 1934-present In question									
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present In question	"4, 5, 6" sign over door to H106.								
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present In question	ARCHITECTURAL SIGNIFICANCE: <table><tr><td>Most</td><td>Some</td><td>Minor</td><td>Negligible</td></tr><tr><td></td><td>☒</td><td>☐</td><td>☐</td></tr></table>	Most	Some	Minor	Negligible		☒	☐	☐
Most	Some	Minor	Negligible									
	☒	☐	☐									

PHOTOGRAPHS: ① View North ② View North



PHOTOGRAPHS: ① View North ② View South ③ Door to H105



ROOM NO: H103/H103A	LAST KNOWN USE: <i>cond</i>	SQUARE FEET: 129	CEILING HEIGHT: 16	DATE: Dec. 1985	NOTES:
FLOOR:	FINISHES: ☒ Tile/Concrete ☐ Resilient <i>wood</i> ☐ Wood ☐ Other:	CONDITION: ☒ Good ☐ Fair ☐ Poor ☐ Destroyed	DATE: ☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question		
BASE:	FINISHES: ☒ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:	CONDITION: ☒ Good ☐ Fair ☐ Poor ☐ Destroyed	DATE: ☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question		
WALLS:	FINISHES: ☒ Plaster ☐ Partitions ☐ Tile Wainscot ☐ Other:	CONDITION: ☒ Good ☐ Fair ☐ Poor ☐ Destroyed	DATE: ☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question		
CEILING:	FINISHES: ☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	CONDITION: ☒ Good ☐ Fair ☐ Poor ☐ Destroyed	DATE: ☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question		
DOORS/ OPENINGS:	FINISHES: ☒ Wood/Glass Panelled ☐ Wood Veneer ☐ Galvanized Metal ☐ Other:	CONDITION: ☒ Good ☐ Fair ☐ Poor ☐ Destroyed	DATE: ☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question		"Dormitory 3" stenciled on door to 103 "Dormitory 2" stenciled on door to 104A. "Dormitory 1" stenciled on door to 105A.
LIGHTING:	FINISHES: ☐ Incandescent/Type A ☐ Incandescent/Type B ☐ CML/Sconce ☒ Other:	CONDITION: ☐ Intact ☐ Intact ☐ Intact ☐ Intact ☒ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	DATE: ☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question		2 fluorescent 1 chain of fluted glass shade.
HEATING/ VENTILATION PLUMBING:	FINISHES: ☒ Radiators ☐ Vents/Fans ☐ Sink/Toilet/Urinal ☐ Other:	CONDITION: ☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	DATE: ☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question		
MISCELLANEOUS:		CONDITION: ☐ Good ☐ Fair ☐ Poor ☐ Destroyed	DATE: ☐ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question		
SUMMARY:		CONDITION: ☐ Good ☐ Fair ☐ Poor ☐ Destroyed	DATE: ☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question		ARCHITECTURAL SIGNIFICANCE: ☐ Most ☐ Some ☒ Minor ☐ Negligible

PHOTOGRAPHS: ① H103, view East ② H103A, view East

ROOM NO. H103/H103A



ROOM NO: H104	LAST KNOWN USE: <i>Courtyard</i>	SQUARE FEET: 191	CEILING HEIGHT: 16	DATE: 16 Dec. 1985	NOTES:
FLOOR:	FINISHES: ☒ Tile/Concrete ☒ Resilient rolled ☐ Wood ☐ Other:	CONDITION: ☒ Good ☐ Fair ☐ Poor ☐ Destroyed	DATE: 1911-1923 1924-1933 1934-present In question		
BASE:	FINISHES: ☒ Tile/Concrete ☒ Resilient ☐ Wood ☐ Other:	CONDITION: ☒ Good ☐ Fair ☐ Poor ☐ Destroyed	DATE: 1911-1923 1924-1933 1934-present In question		
WALLS:	FINISHES: ☒ Plaster ☐ Partitions ☐ Tile Wainscot ☐ Other:	CONDITION: ☒ Good ☐ Fair ☐ Poor ☐ Destroyed	DATE: 1911-1923 1924-1933 1934-present In question		
CEILING:	FINISHES: ☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	CONDITION: ☒ Good ☐ Fair ☐ Poor ☐ Destroyed	DATE: 1911-1923 1924-1933 1934-present In question		
DOORS/ OPENINGS:	FINISHES: ☒ Wood/Glass Panelled ☒ Wood Veneer 3 ☒ Galvanized Metal ☐ Other: 1	CONDITION: ☐ Good ☐ Fair ☐ Poor ☐ Destroyed	DATE: 1911-1923 1924-1933 1934-present In question		Screen door dividing hallway. woven Cotton padding on door frame.
LIGHTING:	FINISHES: ☐ Incandescent/Type A ☐ Incandescent/Type B ☐ CML/Sconce ☒ Other: 2	CONDITION: ☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	DATE: 1911-1923 1924-1933 1934-present In question		1 fluorescent 1 chain w/ fluted glass shade.
HEATING/ VENTILATION PLUMBING:	FINISHES: ☒ Radiators ☐ Vents/Fans ☐ Sink/Toilet/Urinal ☐ Other:	CONDITION: ☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	DATE: 1911-1923 1924-1933 1934-present In question		
MISCELLANEOUS:		CONDITION: ☐ Good ☐ Fair ☐ Poor ☐ Destroyed	DATE: 1911-1923 1924-1933 1934-present In question		"Dormitory 4" stenciled on 106A door. "Dormitory 5" stenciled on 107A door. "Dormitory 6" stenciled on H104A door.
SUMMARY:		CONDITION: ☒ Good ☐ Fair ☐ Poor ☐ Destroyed	DATE: 1911-1923 1924-1933 1934-present In question		ARCHITECTURAL SIGNIFICANCE: Most Some Minor Negligible

PHOTOGRAPHS: ① view west



② view west, screen door ROOM NO. H104



PHOTOGRAPHS: (3) view west

ROOM NO.

H104A



PHOTOGRAPHS:

ROOM NO.

ELLIS ISLAND EXISTING CONDITION SURVEY				Immigrant Building		page: 544	
ROOM NO: H105		LAST KNOWN USE: Corridor		SQUARE FEET: 129		CEILING HEIGHT:	
						DATE: 16 Dec. 1985	
						NOTES:	
FLOOR:	☒	Tile/Concrete	☒	Good	1911-1923		
	☐	Resilient	☐	Fair	1924-1933		
	☐	Wood	☐	Poor	1934-present		
	☒	Other: terrazzo	☐	Destroyed	In question		
BASE:	☒	Tile/Concrete	☒	Good	1911-1923		
	☐	Resilient	☐	Fair	1924-1933		
	☐	Wood	☒	Poor	1934-present		
	☒	Other: terrazzo	☐	Destroyed	In question		
WALLS:	☒	Plaster	☒	Good	1911-1923	Partition wall dividing H102 from H105.	
	☒	Partitions	☐	Fair	1924-1933		
	☒	Tile Wainscot	☒	Poor	1934-present		
	☐	Other:	☐	Destroyed	In question		
CEILING:	☒	Plaster	☐	Good	1911-1923		
	☒	Acoustic panels	☐	Fair	1924-1933		
	☐	Cove	☒	Poor	1934-present		
	☐	Other:	☐	Destroyed	In question		
DOORS/ OPENINGS:	☒	Wood/Glass Panelled	☐	Good	1911-1923	Wood and glass door in partition wall. yellow and blue paint, sponge print pattern. Remnants of paint on glass. W. door, Metal + glass, finish double, 8 lights each door. 4-pane transom-light.	
	☐	Wood Veneer	☒	Fair	1924-1933		
	☐	Galvanized Metal	☒	Poor	1934-present		
	☒	Other:	☐	Destroyed	In question		
LIGHTING:	☐	Incandescent/Type A	☐	Intact	1911-1923	Radiator mounted on blocks.	
	☐	Incandescent/Type B	☐	Intact	1924-1933		
	☐	CML/Sconce	☐	Intact	1934-present		
	☐	Other:	☒	Intact	In question		
HEATING/ VENTILATION PLUMBING:	☒	Radiators	☐	Intact	1911-1923		
	☐	Vents/Fans	☐	Intact	1924-1933		
	☐	Sink/Toilet/Urinal	☐	Intact	1934-present		
	☐	Other:	☐	Intact	In question		
MISCELLANEOUS:	☐		☐	Good	1911-1923	glass fire hose cabinet. "1 fire hose stencilled in red on glass. fire extinguisher mount.	
	☐		☐	Fair	1924-1933		
	☐		☒	Poor	1934-present		
	☐		☐	Destroyed	In question		
SUMMARY:	☒		☒	Good	1911-1923	ARCHITECTURAL SIGNIFICANCE:	
	☐		☐	Fair	1924-1933		
	☐		☒	Poor	1934-present		
	☐		☐	Destroyed	In question		
							Most Some Minor Negligible

② View East



① View West



PHOTOGRAPHS:

ROOM NO. 4105

PHOTOGRAPHS: ③ View West

ROOM NO. H105



PHOTOGRAPHS:

ROOM NO.

ROOM NO: H106/H106A	LAST KNOWN USE: Corridor	SQUARE FEET: 191	CEILING HEIGHT: 16	DATE: 16 Dec. 1986	
	FINISHES:	CONDITION:	DATE:	NOTES:	
FLOOR:	☒ Tile/Concrete ☒ Resilient rolled ☐ Wood ☐ Other:	☒ Good ☒ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question		
BASE:	☒ Tile/Concrete ☒ Resilient ☐ Wood ☐ Other:	☒ Good ☒ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question		
WALLS:	☒ Plaster ☐ Partitions ☐ Tile Wainscot ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question		
CEILING:	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	☒ Good ☒ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question		
DOORS/ OPENINGS:	☒ Wood/Glass Panelled ☒ Wood Veneer ☐ Galvanized Metal ☐ Other:	☒ Good ☒ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	"Dormitory 10" stenciled on door to 116A. "Dormitory 11" stenciled on door to 117A. "Dormitory 12" stenciled on door at center of hall.	
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☐ CML/Sconce ☒ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	1 intact fluorescent. 1 bathroom standard, shade destroyed.	
HEATING/ VENTILATION PLUMBING:	☒ Radiators ☐ Vents/Fans ☐ Sink/Toilet/Urinal ☐ Other:	☒ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question		
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	Top of door frames stenciled: to room 116 - "M113." to room 117 - "M112." Sign at entrance - "456."	
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	ARCHITECTURAL SIGNIFICANCE:	☐ Most ☐ Some ☒ Minor ☐ Negligible

PHOTOGRAPHS: ① Sign at entrance ② View East

ROOM NO. H106



ROOM NO: 4107

LAST KNOWN USE: *Cowboy*SQUARE FEET: *191*

CEILING HEIGHT:

DATE: *16 Dec. 1986*

	FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	☒ Tile/Concrete ☐ Resilient <i>6" x 6"</i> ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
BASE:	☒ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
WALLS:	☒ Plaster ☐ Partitions ☐ Tile Wainscot ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
CEILING:	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
DOORS/ OPENINGS:	☒ Wood/Glass Panelled ☐ Wood Veneer ☒ Galvanized Metal ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☒ CML/Sconce ☐ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	<i>2 fluorescent 1 chain w/ fluted glass shade (bathroom st.).</i>
HEATING/ VENTILATION PLUMBING:	☒ Radiators ☐ Vents/Fans ☐ Sink/Toilet/Urinal ☐ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	ARCHITECTURAL SIGNIFICANCE: ☐ Most ☐ Some ☒ Minor ☐ Negligible

PHOTOGRAPHS: ① H107, View West



② H107A, View West



ROOM NO. H107/107A

ELLIS ISLAND

EXISTING CONDITION SURVEY

Immigrant Building

page: 552

ROOM NO: 4108

LAST KNOWN USE: Corridor

SQUARE FEET: 129

CEILING HEIGHT: 16 Dec. 1985

DATE:

	FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	Tile/Concrete Resilient Wood Other: Terrazzo	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	
BASE:	Tile/Concrete Resilient Wood Other: Terrazzo	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	
WALLS:	Plaster Partitions Tile Wainscot Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	E. wall, wood and glass partition w/ door.
CEILING:	Plaster Acoustic panels Cove Other:	☐ Good ☐ Fair ☒ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	
DOORS/ OPENINGS:	Wood/Glass Panelled Wood Veneer Galvanized Metal Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	E. door - (to Hall) wood + glass, upper 1/2 = single light. Painted Coast guard green. W. door (to outside), Metal + glass, double door, 8 lights each. 3-part transom light.
LIGHTING:	Incandescent/Type A Incandescent/Type B CML/Sconce Other: Fluorescent	☐ Intact ☐ Intact ☐ Intact ☐ Intact	1911-1923 1924-1933 1934-present In question	
HEATING/ VENTILATION PLUMBING:	Radiators Vents/Fans Sink/Toilet/Urinal Other:	☒ Intact ☐ Intact ☐ Intact ☐ Intact	1911-1923 1924-1933 1934-present In question	
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	Glass fire hose cabinet "2 fire hose" shelled in red on glass. Red extinguisher mount.
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	ARCHITECTURAL SIGNIFICANCE: Most Some Minor Negligible

② View East



PHOTOGRAPHS: ① View West



PHOTOGRAPHS:

ROOM NO: 501

LAST KNOWN USE: *None*

SQUARE FEET: 284


CEILING HEIGHT:

DATE: 16 Dec. 1985

	FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	☒ Tile/Concrete ☐ Resilient ☐ Wood ☒ Other: <i>paved stone Terrazzo</i>	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	As in hallway, beige, black + white chips, 2' 6 1/2" X 2' 3 1/4" sections, Brass dividing strips.
BASE:	☐ Tile/Concrete ☐ Resilient ☒ Wood ☒ Other: <i>Terrazzo</i>	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	Wood @ partition wall (W). Terrazzo @ other 3 walls.
WALLS:	☒ Plaster ☒ Partitions ☐ Tile Wainscot ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	best wall - bet. 501 and Hallway wood partition. E.N., S. walls plaster.
CEILING:	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
DOORS/ OPENINGS:	☐ Wood/Glass Panelled ☐ Wood Veneer ☐ Galvanized Metal ☐ Other:	☐ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	Framed square opening (approx. 2' x 2') in partition wall (window, no glass).
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☐ CML/Sconce ☒ Other: <i>fluorescent 2</i>	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
HEATING/ VENTILATION PLUMBING:	☒ Radiators ☐ Vents/Fans ☐ Sink/Toilet/Urinal ☐ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	green cloth rolled window-shade. Large (approx. 2" high, 7" wide) door sill.
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	ARCHITECTURAL SIGNIFICANCE:
				Most ☐ Some ☐ Minor ☐ Negligible ☒

PHOTOGRAPHS: ① View North ② View Southeast ③ View South

ROOM NO. 501





ROOM NO: 502	LAST KNOWN USE: Office	SQUARE FEET: 284	CEILING HEIGHT:	DATE: 16 Dec. 1985
FINISHES:		CONDITION:	DATE:	NOTES:
FLOOR:	☒ Tile/Concrete ☐ Resilient ☐ Wood ☒ Other: poured stone/terrazzo	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	As in hallways, beige, black + white chips, 2' 6 1/2" x 2' 3 1/4" sections, brass dividing strips.
BASE:	☒ Tile/Concrete ☒ Resilient ☒ Wood ☒ Other: terrazzo	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	Wood @ partition wall (w.) Terrazzo @ other 3 walls.
WALLS:	☒ Plaster ☒ Partitions ☒ Tile Wainscot ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	W. wall, wood partition.
CEILING:	☒ Plaster ☒ Acoustic panels ☐ Cove ☐ Other:	☐ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	Water stained, area of missing panels in SW corner.
DOORS/ OPENINGS:	☐ Wood/Glass Panelled ☐ wood Veneer ☐ Galvanized Metal ☐ Other:	☐ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	No door. Thick, curved wood doorsill, (approx 2" high x 7" wide).
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☐ CFL/Sconce ☒ Other: fluorescent	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☒ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	tracks for standard fluorescent lighting.
HEATING/ VENTILATION PLUMBING:	☒ Radiators ☐ Vents/Fans ☐ Sink/Toilet/Urinal ☐ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	small shelf on E. wall. (see bracket). Wood plaque w/ wire (phone?) S. wall.
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	ARCHITECTURAL SIGNIFICANCE:
				☐ Most ☐ Some ☐ Minor ☒ Negligible

PHOTOGRAPHS:

① view North

② view South

ROOM NO. 502



PHOTOGRAPHS:

(3) view Northeast

ROOM NO. 502




PHOTOGRAPHS:

ROOM NO.


RECREATION BUILDING

Exhibit 23


ARCHITECTURAL SIGNIFICANCE



SECOND FLOOR PLAN



FIRST FLOOR PLAN




356 26,013 / 7 of 8
DSC JUL 88


UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE DENVER SERVICE CENTER	
ARCHITECTS BETTER BLINDER BELLE / HOTTER PREGOLD & ALEXANDER 41 EAST 11 STREET NEW YORK, N.Y. 10003 (212) 777-1900	
STRUCTURAL ENGINEERS ROBERT BLUMAN ASSOCIATES, P.C. MECHANICAL & ELECTRICAL ENGINEERS BYSKA & HENNESSY INC.	
SURVEY OF STRUCTURES UNIT 4	
ELLIS ISLAND STATUE OF LIBERTY NATIONAL MONUMENT NEW YORK / NEW JERSEY	
DESIGNED DATE DRAWN CHECKED TECH REVIEW KEY	
TITLE OF SHEET RECREATION BLDG 1ST & 2ND FL PLANS	
DRAWING NO SUB SHEET NO	
TOTAL SHEET NO.	

Exhibit 21

EXISTING CONDITIONS




SECOND FLOOR PLAN



FIRST FLOOR PLAN

356 26,013 / 8 of 8
DSC JUL 88



UNITED STATES DEPARTMENT OF THE INTERIOR		ARCHITECTS	
NATIONAL PARK SERVICE DENVER SERVICE CENTER		BETTER BLINDER BELLE / ROTTER PHEGOLD & ALEXANDER 41 EAST 11 STREET NEW YORK, NY 10003 (212) 777-7800	
STRUCTURAL ENGINEERS		ROBERT SILMAN ASSOCIATES, P.C.	
MECHANICAL & ELECTRICAL ENGINEERS		BYSKA & HENNESSY INC.	
SURVEY OF STRUCTURES UNIT 4			
ELLIS ISLAND STATUE OF LIBERTY NATIONAL MONUMENT NEW YORK / NEW JERSEY			
DESIGNED	DATE	BY	REVIEW
DRAWN	DATE	BY	REVIEW
KEY			
TITLE OF SHEET RECREATION BLDG 1st & 2nd FL PLANS SUB SHEET NO. DRAWING NO.			

ROOM NO: 101/102/102A		LAST KNOWN USE: office		SQUARE FEET: 413		CEILING HEIGHT:		DATE: 6 Dec. 1985	
		FINISHES:		CONDITION:		DATE:		NOTES:	
FLOOR:	☒ Tile/Concrete	☒	Good	1911-1923	☒ Evidence of wall removal.				
	☐ Resilient	☐	Fair	1924-1933					
	☐ Wood	☐	Poor	1934-present					
	☐ Other:	☐	Destroyed	In question					
BASE:	☐ Tile/Concrete	☐	Good	1911-1923					
	☐ Resilient	☐	Fair	1924-1933					
	☐ Wood	☒	Poor	1934-present					
	☐ Other:	☐	Destroyed	In question					
WALLS:	☒ Plaster	☐	Good	1911-1923					
	☐ Partitions	☐	Fair	1924-1933					
	☐ Tile Wainscot	☒	Poor	1934-present					
	☐ Other:	☐	Destroyed	In question					
CEILING:	☒ Plaster	☐	Good	1911-1923					
	☐ Acoustic panels	☐	Fair	1924-1933					
	☐ Cove	☐	Poor	1934-present					
	☐ Other:	☒	Destroyed	In question					
DOORS/ OPENINGS:	☐ Wood/Glass Panelled	☐	Good	1911-1923					
	☒ Wood Veneer 3	☐	Fair	1924-1933					
	☐ Galvanized Metal	☒	Poor	1934-present					
	☐ Other:	☐	Destroyed	In question					
LIGHTING:	☐ Incandescent/Type A	☐	Intact	1911-1923					
	☐ Incandescent/Type B	☐	Intact	1924-1933					
	☐ CML/Sconce	☐	Intact	1934-present					
	☒ Other:	☐	Intact	In question					
HEATING/ VENTILATION PLUMBING:	☒ Radiators 2-	☒	Intact	1911-1923					
	☐ Vents/Fans	☐	Intact	1924-1933					
	☐ Sink/Toilet/Urinal	☐	Intact	1934-present					
	☐ Other:	☐	Intact	In question					
MISCELLANEOUS:			Good	1911-1923	102A: closet w/ clothes rods. Door closer on door.				
		Fair	1924-1933						
		Poor	1934-present						
		Destroyed	In question						
SUMMARY:			Good	1911-1923	ARCHITECTURAL SIGNIFICANCE:				
			Fair	1924-1933					
		☒	Poor	1934-present					
		☐	Destroyed	In question					
						Most Some Minor Negligible			

(2) view West



PHOTOGRAPHS: (1) view South



ROOM NO: 103

LAST KNOWN USE: Office


SQUARE FEET: 192

CEILING HEIGHT:



DATE: 6 Dec. 1985

	FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	☒ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
BASE:	☐ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:	☐ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
WALLS:	☒ Plaster ☐ Partitions ☐ Tile Wainscot ☐ Other:	☐ Good ☐ Fair ☒ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
CEILING:	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	☐ Good ☐ Fair ☐ Poor ☒ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
DOORS/ OPENINGS:	☒ Wood/Glass Panelled ☐ Wood Veneer 2 ☐ Galvanized Metal ☐ Other:	☐ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	2 6-light casement windows.
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☒ CML Sconce ☐ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☒ Destroyed ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
HEATING/ VENTILATION PLUMBING:	☒ Radiators 1 ☐ Vents/Fans ☒ Sink/Toilet/Urinal ☐ Other:	☒ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	1 wall-mounted sink.
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	signage on door in gold stencil: HOSPITAL R
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	ARCHITECTURAL SIGNIFICANCE:
				Most Some Minor Negligible

PHOTOGRAPHS: ① View South



② View North ③ View West



ROOM NO: 104

LAST KNOWN USE: Office

SQUARE FEET: 197

CEILING HEIGHT:

DATE: 6 Dec. 1985

	FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	☒ Tile <u>Concrete</u> ☐ Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
BASE:	☐ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:	☐ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
WALLS:	☒ Plaster ☐ Partitions ☐ Tile Wainscot ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
CEILING:	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	☐ Good ☐ Fair ☐ Poor ☒ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
DOORS/ OPENINGS:	☐ Wood/Glass Panelled ☒ Wood Veneer <u>3</u> ☐ Galvanized Metal ☐ Other:	☐ Good ☐ Fair ☒ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	2 6-light casement windows.
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☒ CFL/Sconce 1 ☐ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☒ Destroyed ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	base remains/globe destroyed
HEATING/ VENTILATION PLUMBING:	☒ Radiators ☐ Vents/Fans ☐ Sink/Toilet/Urinal ☐ Other:	☒ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	ARCHITECTURAL SIGNIFICANCE: Most Some ☒ Minor Negligible

PHOTOGRAPHS: ① View South



② View North



ROOM NO: 105

LAST KNOWN USE: Auditorium / Artifacts storage

SQUARE FEET: Aud. - 3844 Stage - 478

CEILING HEIGHT: 25'-10" DATE: 6 Dec. 1985

And: Stage 17'-5 1/2"

FINISHES:

CONDITION:

DATE:

NOTES:

FLOOR:	☒ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	Stage floor - resilient tile, good cond. Main space - concrete w/ evidence of tile overlay. 2 cracks in west band.
BASE:	☒ Tile/Concrete ☒ Resilient ☒ Wood ☒ Other:	☐ Good ☐ Fair ☒ Poor ☒ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	Probable wood base. Slate base on stage. Asphalt base w/ cove in area of wood paneling.
WALLS:	☒ Plaster ☐ Partitions ☐ Tile Wainscot ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	Exposure of structural tile in some areas.
CEILING:	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	Barrel vault. Hole in NE section - exposure of steel framing + support. Hole over fireplace.
DOORS/ OPENINGS:	☒ Wood/Glass Panelled ☒ Wood Veneer ☒ Galvanized Metal ☐ Other:	☐ Good ☐ Fair ☒ Poor ☒ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	6 wood veneer doors; 1 removed, 1 destroyed. Iron casement windows.
LIGHTING:	☒ Incandescent/Type A ☐ Incandescent/Type B ☒ CML/Sconce ☐ Other:	☐ Intact ☐ Intact ☒ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	10 central Type As. Bases + chains extent, globes removed. 2 wall-mounted fixtures over doors to 105A + 105B - Brass base, red bulb.
HEATING/ VENTILATION PLUMBING:	☒ Radiators ☒ Vents/Fans ☐ Sink/Toilet/Urinal ☐ Other:	☒ Intact ☒ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	6 radiators w/ screened covers. 3 screened vents. 4 circular vents in ceiling.
MISCELLANEOUS:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	Fireplace - E. wall. Canteen - N. wall. Stage - S. end.
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	ARCHITECTURAL SIGNIFICANCE: ☒ Most ☐ Some ☐ Minor ☐ Negligible

PHOTOGRAPHS: ① View North ② View North

③ Canteen ④ View Southwest

ROOM NO. 105



PHOTOGRAPHS: ⑤ View Northeast ⑥ View Southeast ⑦ Fireplace, East wall ROOM NO. 105



PHOTOGRAPHS:

ROOM NO.

ROOM NO: 105A LAST KNOWN USE: *Stage access wing* SQUARE FEET: 110 CEILING HEIGHT: DATE: 6 Dec. 1985

	FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	☒ Tile/ <u>Concrete</u> ☐ Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
BASE:	☒ Tile/ <u>Concrete</u> ☐ Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	flush w/ wall.
WALLS:	☒ Plaster ☐ Partitions ☐ Tile Wainscot ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	w. wall: patches of gray linoleum-type covering. Glass hatched w/ white lines creating approx. 5" squares.
CEILING:	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	some exposure of metal mesh. Loft w/ wood beams. Access to roof.
DOORS/ OPENINGS:	☐ Wood/Glass Panelled ☐ Wood Veneer ☐ Galvanized Metal ☐ Other:	☐ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	6-light iron french doors w/ 2-light transom. Outer grille. 1 Circular vented window.
LIGHTING:	☒ Incandescent/Type A ☐ Incandescent/Type B ☐ CML/Sconce ☐ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	Globe removed.
HEATING/ VENTILATION PLUMBING:	☒ Radiators ☐ Vents/Fans ☐ Sink/Toilet/Urinal ☐ Other:	☒ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	With upper metal shelf w/ curved side brackets.
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	- cement stairs to stage; rusting iron rail.; Iron ladder to roof bolted to E. wall; wood shelf on W. wall. Rusty crenelated box above shelf.
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	ARCHITECTURAL SIGNIFICANCE: Most ☒ Some ☐ Minor ☐ Negligible ☐

PHOTOGRAPHS: ① view North



② view South



ELLIS ISLAND EXISTING CONDITION SURVEY Recreation Building				page: 5/14	
ROOM NO: 105B	LAST KNOWN USE: Stage access wing	SQUARE FEET: 110	CEILING HEIGHT:	DATE: 6 Dec. 1985	
	FINISHES:	CONDITION:	DATE:	NOTES:	
FLOOR:	☒ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question		
BASE:	☒ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	flush w/ wall.	
WALLS:	☒ Plaster ☐ Partitions ☐ Tile Mainscot ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question		
CEILING:	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question		
DOORS/ OPENINGS:	☒ Wood/Glass Panelled ☐ Wood Veneer ☐ Galvanized Metal ☐ Other:	☐ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	Signage on exterior of door: "STAGE" Gold w/ black lined edge. Iron window sills. Circular window w/ screen.	
LIGHTING:	☒ Incandescent/Type A ☐ Incandescent/Type B ☐ CFL/Sconce ☐ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	1911-1923 1924-1933 1934-present In question		
HEATING/ VENTILATION PLUMBING:	☒ Radiators ☐ Vents/Fans ☐ Sink/Toilet/Urinal ☐ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	1911-1923 1924-1933 1934-present In question	w/ metal shelf as 105A.	
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	Cement stair to cement landing: Iron rail. -> entrance to stage.	
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	ARCHITECTURAL SIGNIFICANCE:	Most Some Minor Negligible

PHOTOGRAPHS: ① Door Signage

ROOM NO. 1050



ELLIS ISLAND			EXISTING CONDITION SURVEY			Recreation Building			page: 576		
ROOM NO: 106			LAST KNOWN USE: Men's toilet			CEILING HEIGHT: 7			DATE: 6 Dec. 1985		
			FINISHES:			CONDITION:			DATE:		
FLOOR:			☒ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:			☒ Good ☐ Fair ☐ Poor ☐ Destroyed			1911-1923 1924-1933 1934-present In question		
BASE:			☒ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:			☒ Good ☐ Fair ☐ Poor ☐ Destroyed			1911-1923 1924-1933 1934-present In question		
WALLS:			☐ Plaster ☐ Partitions ☒ Tile Wainscot ☐ Other:			☒ Good ☐ Fair ☐ Poor ☐ Destroyed			1911-1923 1924-1933 1934-present In question		
CEILING:			☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:			☒ Good ☐ Fair ☐ Poor ☐ Destroyed			1911-1923 1924-1933 1934-present In question		
DOORS/ OPENINGS:			☒ Wood/Glass Panelled ☐ Wood Veneer ☐ Galvanized Metal ☐ Other:			☒ Good ☐ Fair ☐ Poor ☐ Destroyed			1911-1923 1924-1933 1934-present In question		
LIGHTING:			☐ Incandescent/Type A ☐ Incandescent/Type B ☒ CFL/Sconce / ☐ Other:			☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed			1911-1923 1924-1933 1934-present In question		
HEATING/ VENTILATION PLUMBING:			☐ Radiators ☐ Vents/Fans ☒ Sink/Toilet/Urinal ☐ Other:			☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed			1911-1923 1924-1933 1934-present In question		
MISCELLANEOUS:						☐ Good ☐ Fair ☐ Poor ☐ Destroyed			1911-1923 1924-1933 1934-present In question		
SUMMARY:						☒ Good ☐ Fair ☐ Poor ☐ Destroyed			1911-1923 1924-1933 1934-present In question		
ARCHITECTURAL SIGNIFICANCE:									Most Some Minor Negligible		

4" beige square tiles.

Tile as floor.

exposure of cement substructure.

1 6-light casement window w/ patterned glass.

2 urinals
1 slop sink
1 central pedestal sink
toilet missing.

Structural glass toilet stall partition.
Rusted paper towel dispenser.

PHOTOGRAPHS: ① View South

② View West

ROOM NO. 106



PHOTOGRAPHS: ③ view Southeast

ROOM NO. 106




PHOTOGRAPHS:

ROOM NO.

ELLIS ISLAND			EXISTING CONDITION SURVEY			Recreation Building			page: 580		
ROOM NO:	107	LAST KNOWN USE: Storage			SQUARE FEET:			CEILING HEIGHT:	DATE: 6 Dec. 1985		
		FINISHES:			CONDITION:			DATE:	NOTES:		
FLOOR:		☒ Tile/Concrete	☒	Good		1911-1923		Patterned metal hatch in floor (5'x3' approx.).			
		☐ Resilient		Fair		1924-1933					
		☐ Wood		Poor		1934-present					
		☐ Other:		Destroyed		In question					
BASE:		☒ Tiled/Concrete	☒	Good		1911-1923		Concrete flush with wall.			
		☐ Resilient		Fair		1924-1933					
		☐ Wood		Poor		1934-present					
		☐ Other:		Destroyed		In question					
WALLS:		☒ Plaster	☒	Good		1911-1923					
		☐ Partitions		Fair		1924-1933					
		☐ Tile Mainscot		Poor		1934-present					
		☐ Other:		Destroyed		In question					
CEILING:		☒ Plaster	☒	Good		1911-1923					
		☐ Acoustic panels		Fair		1924-1933					
		☐ Cove		Poor		1934-present					
		☐ Other:		Destroyed		In question					
DOORS/ OPENINGS:		☒ Wood/Glass Panelled	☒	Good		1911-1923					
		☐ Wood Veneer		Fair		1924-1933					
		☐ Galvanized Metal		Poor		1934-present					
		☐ Other:		Destroyed		In question					
LIGHTING:		☐ Incandescent/Type A		Intact		1911-1923					
		☐ Incandescent/Type B		Intact		1924-1933					
		☐ CML/Sconce		Intact		1934-present					
		☐ Other:		Intact		In question					
HEATING/ VENTILATION PLUMBING:		☐ Radiators		Intact		1911-1923					
		☐ Vents/Fans		Intact		1924-1933					
		☐ Sink/Toilet/Urinal		Intact		1934-present					
		☐ Other:		Intact		In question					
MISCELLANEOUS:				Good		1911-1923					
				Fair		1924-1933					
				Poor		1934-present					
				Destroyed		In question					
SUMMARY:				Good		1911-1923					
				Fair		1924-1933					
				Poor		1934-present					
				Destroyed		In question					
ARCHITECTURAL SIGNIFICANCE:					Most Some Minor Negligible						

PHOTOGRAPHS: ① View East



② View Southwest



ELLIS ISLAND EXISTING CONDITION SURVEY Recreation Building										page: 582
ROOM NO: 108		LAST KNOWN USE: office		SQUARE FEET: 186		CEILING HEIGHT:		DATE: 6 Dec. 1986		
		FINISHES:		CONDITION:		DATE:		NOTES:		
FLOOR:	☒	☒ Tiles/Concrete ☐ Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐	☐	☐	☒ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question			
BASE:	☐	☐ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:	☐ Good ☐ Fair ☐ Poor ☐ Destroyed	☐	☒	☐	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question			
WALLS:	☒	☒ Plaster ☐ Partitions ☐ Tile Wainscot ☐ Other:	☐ Good ☐ Fair ☒ Poor ☐ Destroyed	☐	☒	☐	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question			
CEILING:	☒	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐	☒	☐	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	Cracking and damp areas.		
DOORS/ OPENINGS:	☒	☒ Wood/Glass Panelled ☒ Wood Veneer 3 ☒ Galvanized Metal ☐ Other:	☐ Good ☒ Fair ☒ Poor ☐ Destroyed	☐	☒	☐	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	Door to 107 - fair cond.		
LIGHTING:	☐	☐ Incandescent/Type A ☐ Incandescent/Type B ☒ CML Sconce 2 ☐ Other:	☐ Intact ☐ Intact ☒ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐	☒	☐	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	2 CMLs with glass globes.		
HEATING/ VENTILATION PLUMBING:	☒	☒ Radiators / ☐ Vents/Fans ☒ Sink/Toilet/Urinal ☐ Other:	☒ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐	☒	☐	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	1 wall-mounted sink w/ faucets.		
MISCELLANEOUS:	☐	☐	☐ Good ☐ Fair ☐ Poor ☐ Destroyed	☐	☒	☐	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	Tapes for venetian blinds. Holes for removed shelf or towel rack above sink.		
SUMMARY:				☒ Good ☐ Fair ☐ Poor ☐ Destroyed	☐	☒	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	ARCHITECTURAL SIGNIFICANCE:		
								Most Some Minor Negligible		

PHOTOGRAPHS: ① View North



② View South



ROOM NO. 108

ROOM NO:	LAST KNOWN USE:	SQUARE FEET:	CEILING HEIGHT:	DATE:	NOTES:
108A	Women's toilet			1911-1923 1924-1933 1934-present In question	4" beige square.
FLOOR:	☒ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed			
BASE:	☐ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:	☐ Good ☐ Fair ☐ Poor ☐ Destroyed			
WALLS:	☒ Plaster ☐ Partitions ☐ Tile Mainscot ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed			
CEILING:	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed			
DOORS/ OPENINGS:	☒ Wood/Glass Panelled ☐ Wood Veneer ☐ Galvanized Metal ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed			Signage on door: Gold w/ black edge = "WOMEN." 1 6-light casement window w/ patterned glass and interior screen. 1 Hanging fixture w/ fluted glass shade.
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☐ CML/Sconce ☒ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed			1 central pedestal sink w/ faucets. 1 toilet - no tank.
HEATING/ VENTILATION PLUMBING:	☒ Radiators / Vents / Fans ☒ Sink / Toilet / Urinal ☐ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed			Structural glass stall partition. Rusted metal swing door to stall.
MISCELLANEOUS:					
SUMMARY:					ARCHITECTURAL SIGNIFICANCE: Most Some ☒ Minor Negligible



ELLIS ISLAND

EXISTING CONDITION SURVEY

Recreation Building

page: 586

ROOM NO: 109

LAST KNOWN USE: Canteen

SQUARE FEET: 121

CEILING HEIGHT: 10'- $\frac{3}{4}$ "

DATE: 6 Dec. 1985

	FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	☒ Tile/Concrete ☒ Resilient ☐ Wood ☐ Other:	☐ Good ☐ Fair ☒ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	Brown composite tile. Concrete subsurface.
BASE:	☒ Tile/Concrete ☒ Resilient asphalt ☐ Wood ☐ Other:	☐ Good ☐ Fair ☐ Poor ☒ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	S.W. corner: remaining asphalt base - removed elsewhere.
WALLS:	☒ Plaster ☐ Partitions ☐ Tile Wainscot ☐ Other:	☐ Good ☐ Fair ☐ Poor ☒ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
CEILING:	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	☐ Good ☐ Fair ☐ Poor ☒ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
DOORS/ OPENINGS:	☐ Wood/Glass Panelled ☒ Wood Veneer I ☐ Galvanized Metal ☐ Other:	☐ Good ☐ Fair ☐ Poor ☒ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☐ CFL/Sconce ☐ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	
HEATING/ VENTILATION PLUMBING:	☐ Radiators ☐ Vents/Fans ☐ Sink/Toilet/Urinal ☐ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	grille to 105 has a central hinge. cupboards on N. wall - stained. Metal sheet over wood counter.
SUMMARY:		☐ Good ☒ Fair ☐ Poor ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	ARCHITECTURAL SIGNIFICANCE:
				Most Some Minor Negligible

② view West



① view Southeast



PHOTOGRAPHS:

ELLIS ISLAND

EXISTING CONDITION SURVEY

Recreation Building

page: 588

ROOM NO: 110/501


LAST KNOWN USE: Starhall

SQUARE FEET: 148

CEILING HEIGHT: 10'-2 3/4" DATE: 6 Dec. 1985

	FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	☒ Tiled Concrete ☒ Resilient ☐ Wood ☐ Other:	☐ Good ☐ Fair ☐ Poor ☒ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	Remnants of resilient tile attached to concrete substructure.
BASE:	☐ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:	☐ Good ☐ Fair ☐ Poor ☒ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
WALLS:	☒ Plaster ☐ Partitions ☐ Tile Mainscot ☐ Other:	☒ Good ☐ Fair ☐ Poor ☒ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	Some exposure of structural tile.
CEILING:	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	☐ Good ☐ Fair ☐ Poor ☒ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
DOORS/OPENINGS:	☒ Wood/Glass Panelled ☒ Wood Veneer 2 ☐ Galvanized Metal ☐ Other:	☐ Good ☐ Fair ☐ Poor ☒ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	2-light casement window w/ rusted metal sill. Dark stain on wood frame.
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☐ CML/Sconce ☐ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☒ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	
HEATING/VENTILATION/PLUMBING:	☒ Radiators ☐ Vents/Fans ☐ Sink/Toilet/Urinal ☐ Other:	☒ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☒ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	Steel stairs leading to second floor.
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☒ Destroyed	☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	ARCHITECTURAL SIGNIFICANCE:
				☐ Most ☐ Some ☒ Minor ☐ Negligible

② view West



PHOTOGRAPHS: ① view East



PHOTOGRAPHS: ③ Newel post

ROOM NO. 110/501



PHOTOGRAPHS:

ROOM NO.

ELLIS ISLAND EXISTING CONDITION SURVEY				Recreation Building		page: 592	
ROOM NO: H101		LAST KNOWN USE: Entrance Lobby		CEILING HEIGHT: 10'-0" DATE: 6 Dec. 1985			
		FINISHES:		CONDITION:		DATE:	
FLOOR:		☒ Tiled Concrete ☐ Resilient ☐ Wood ☐ Other:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed		☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
BASE:		☐ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed		☐ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	
WALLS:		☒ Plaster ☐ Partitions ☐ Tile Wainscot ☐ Other:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed		☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
CEILING:		☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed		☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
DOORS/ OPENINGS:		☒ Wood/Glass Panelled ☒ Wood Veneer ☐ Galvanized Metal ☐ Other:		☐ Good ☐ Fair ☒ Poor ☐ Destroyed		☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
LIGHTING:		☐ Incandescent/Type A ☐ Incandescent/Type B ☒ CFL/Sconce 1 ☐ Other:		☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed		☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
HEATING/ VENTILATION PLUMBING:		☐ Radiators ☐ Vents/Fans ☐ Sink/Toilet/Urinal ☐ Other:		☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed		☐ 1911-1923 ☐ 1924-1933 ☐ 1934-present ☐ In question	
MISCELLANEOUS:				☐ Good ☐ Fair ☐ Poor ☐ Destroyed		☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
SUMMARY:				☒ Good ☐ Fair ☐ Poor ☐ Destroyed		☐ 1911-1923 ☐ 1924-1933 ☒ 1934-present ☐ In question	
ARCHITECTURAL SIGNIFICANCE:						Most Some Minor Negligible	
3 veneer doors to rooms. 1 pair 12-light bench doors w/ 3-light side lights + 7-light transom.							
Metal grilles - same pattern as radiator grilles. 1 "Faraday" fire alarm.							

PHOTOGRAPHS: ① view West

ROOM NO. H101



ELLIS ISLAND				EXISTING CONDITION SURVEY				Recreation Building				page: 594			
ROOM NO: H101A		LAST KNOWN USE: closet		SQUARE FEET: 26		CEILING HEIGHT:		DATE: 6 Dec. 1985							
		FINISHES:		CONDITION:		DATE:		NOTES:							
FLOOR:		☒ Tile ☐ Concrete ☐ Resilient ☐ Wood ☐ Other:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed		1911-1923 1924-1933 ☒ 1934-present In question									
BASE:		☐ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed		1911-1923 1924-1933 ☒ 1934-present In question									
WALLS:		☒ Plaster ☐ Partitions ☐ Tile Wainscot ☐ Other:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed		1911-1923 1924-1933 ☒ 1934-present In question				wall-mounted wood board w/ hook.					
CEILING:		☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:		☐ Good ☐ Fair ☒ Poor ☐ Destroyed		1911-1923 1924-1933 ☒ 1934-present In question									
DOORS/ OPENINGS:		☒ Wood/Glass Panelled ☐ Wood Veneer ☒ Galvanized Metal ☐ Other:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed		1911-1923 1924-1933 ☒ 1934-present In question									
LIGHTING:		☒ Incandescent/Type A ☐ Incandescent/Type B ☐ CML/Sconce ☐ Other:		☒ Destroyed ☐ Intact ☐ Intact ☐ Intact ☐ Intact		1911-1923 1924-1933 ☒ 1934-present In question									
HEATING/ VENTILATION PLUMBING:		☐ Radiators ☐ Vents/Fans ☐ Sink/Toilet/Urinal ☐ Other:		☐ Destroyed ☐ Intact ☐ Intact ☐ Intact ☐ Intact		1911-1923 1924-1933 1934-present In question									
MISCELLANEOUS:				☐ Good ☐ Fair ☐ Poor ☐ Destroyed		1911-1923 1924-1933 ☒ 1934-present In question				circuiting boxes.					
SUMMARY:				☐ Good ☒ Fair ☐ Poor ☐ Destroyed		1911-1923 1924-1933 ☒ 1934-present In question				ARCHITECTURAL SIGNIFICANCE:					
										☐ Most ☐ Some ☒ Minor ☐ Negligible					

PHOTOGRAPHS:

ROOM NO. H101A


ELLIS ISLAND EXISTING CONDITION SURVEY										Recreation Building										page: 596									
ROOM NO: 201		LAST KNOWN USE: Office		SQUARE FEET: 197		CEILING HEIGHT: 6		DATE: 6 Dec. 1985																					
		FINISHES:		CONDITION:		DATE:		NOTES:																					
FLOOR:		☒	Tile/Concrete	☒	Good	1911-1923																							
		☐	Resilient	☐	Fair	1924-1933																							
		☐	Wood	☐	Poor	1934-present																							
		☐	Other:	☐	Destroyed	In question																							
BASE:		☒	Tile/Concrete	☒	Good	1911-1923				flush w/ wall.																			
		☐	Resilient	☐	Fair	1924-1933																							
		☐	Wood	☐	Poor	1934-present																							
		☐	Other:	☐	Destroyed	In question																							
WALLS:		☒	Plaster	☐	Good	1911-1923																							
		☐	Partitions	☐	Fair	1924-1933																							
		☐	Tile Mainscot	☒	Poor	1934-present																							
		☐	Other:	☐	Destroyed	In question																							
CEILING:		☒	Plaster	☐	Good	1911-1923																							
		☐	Acoustic panels	☐	Fair	1924-1933																							
		☐	Cove	☐	Poor	1934-present																							
		☐	Other:	☒	Destroyed	In question																							
DOORS/ OPENINGS:		☒	Wood/Glass Panelled	☐	Good	1911-1923				2 round windows.																			
		☐	Wood Veneer	☐	Fair	1924-1933				1 Veneer door.																			
		☐	Galvanized Metal	☒	Poor	1934-present																							
		☐	Other:	☐	Destroyed	In question																							
LIGHTING:		☐	Incandescent/Type A	☐	Intact	1911-1923																							
		☐	Incandescent/Type B	☐	Intact	1924-1933																							
		☐	CML/Sconce	☐	Intact	1934-present																							
		☐	Other:	☐	Intact	In question																							
HEATING/ VENTILATION PLUMBING:		☐	Radiators	☐	Intact	1911-1923				1 wall mounted sink.																			
		☒	Vents/Fans	☐	Intact	1924-1933																							
		☒	Sink/Toilet/Urinal	☐	Intact	1934-present																							
		☐	Other:	☐	Intact	In question																							
MISCELLANEOUS:		☐		☐	Good	1911-1923				Generator mounted on floor.																			
		☐		☐	Fair	1924-1933				"Trumbull Electric" circuitry boxes - rusted, on wall.																			
		☐		☐	Poor	1934-present				circular "cutler-Hammer" motor control.																			
		☐		☐	Destroyed	In question																							
SUMMARY:		☐		☒	Good	1911-1923				ARCHITECTURAL SIGNIFICANCE:																			
		☐		☐	Fair	1924-1933				Most																			
		☐		☐	Poor	1934-present				Some																			
		☐		☐	Destroyed	In question				Minor																			
		☐		☐						Negligible																			

PHOTOGRAPHS: ① View East



ROOM NO: 202	LAST KNOWN USE: Projection room	SQUARE FEET: 118	CEILING HEIGHT: 8'-2" (old ci. - 9' line)	DATE: 6 Dec. 1985
	FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	☒ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
BASE:	☒ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	finish of wall.
WALLS:	☒ Plaster ☐ Partitions ☐ Tile Wainscot ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	Wall signage: "STAGE LIGHT" "HOUSE LIGHT" Projection openings w/ sliding metal doors. Structural tile visible in N. wall + near ceiling.
CEILING:	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	☐ Good ☐ Fair ☐ Poor ☒ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
DOORS/ OPENINGS:	☐ Wood/Glass Panelled ☐ Wood Veneer ☒ Galvanized Metal ☐ Other:	☐ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	rusting metal door - signage: in Gold - "PROJECTION ROOM"
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☒ CML Sconce ☐ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
HEATING/ VENTILATION PLUMBING:	☐ Radiators ☒ Vents/Fans () ☒ Sink/Toilet/Urinal ☐ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	1 wall mounted sinks Metal shelf on brackets: E. wall. Generator.
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☐ 1934-present In question	
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	ARCHITECTURAL SIGNIFICANCE: Most ☒ Some ☐ Minor ☐ Negligible

PHOTOGRAPHS: ① View West



② View East



ROOM NO:	LAST KNOWN USE:	SQUARE FEET:	CEILING HEIGHT:	DATE:	NOTES:
203	office / Apartment storage	192	192	1985	
	FINISHES:	CONDITION:			
FLOOR:	☒ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question		
BASE:	☒ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question		flush w/ wall.
WALLS:	☒ Plaster ☐ Partitions ☐ Tile Wainscot ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question		
CEILING:	☒ Plaster ☐ Acoustic panels ☐ Cove ☐ Other:	☐ Good ☐ Fair ☐ Poor ☒ Destroyed	1911-1923 1924-1933 1934-present In question		
DOORS/ OPENINGS:	☒ Wood/Glass Panelled ☐ Wood Veneer ☒ Galvanized Metal ☐ Other:	☐ Good ☐ Fair ☐ Poor ☒ Destroyed	1911-1923 1924-1933 1934-present In question		2 round windows w/ screens. Veneer of doors destroyed.
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B ☐ CML/Sconce ☐ Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	1911-1923 1924-1933 1934-present In question		
HEATING/ VENTILATION PLUMBING:	☒ Radiators ☐ Vents/Fans ☒ Sink/Toilet/Urinal ☐ Other:	☒ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	1911-1923 1924-1933 1934-present In question		1 wall-mounted sink w/ faucet
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question		
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question		ARCHITECTURAL SIGNIFICANCE: Most ☐ Some ☒ Minor ☐ Negligible ☐

PHOTOGRAPHS: ① View West



② View Southeast



ROOM NO. 203

ROOM NO: H201 LAST KNOWN USE: *stairhall* SQUARE FEET: 149 CEILING HEIGHT: DATE: 6 Dec. 1985

	FINISHES:	CONDITION:	DATE:	NOTES:
FLOOR:	☒ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
BASE:	☒ Tile/Concrete ☐ Resilient ☐ Wood ☐ Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	flush w/ wall.
WALLS:	☒ Plaster Partitions Tile Wainscot Other:	☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	structural tiles visible in upper areas.
CEILING:	☒ Plaster Acoustic panels Cove Other:	☐ Good ☐ Fair ☐ Poor ☒ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	
DOORS/ OPENINGS:	☒ Wood/Glass Panelled Wood Veneer 3 Galvanized Metal Other:	☐ Good ☒ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	2 circular windows.
LIGHTING:	☐ Incandescent/Type A ☐ Incandescent/Type B CML/Sconce Other:	☐ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	1911-1923 1924-1933 1934-present In question	
HEATING/ VENTILATION PLUMBING:	☒ Radiators / Vents/Fans Sink/Toilet/Urinal Other:	☒ Intact ☐ Intact ☐ Intact ☐ Intact ☐ Destroyed ☐ Destroyed ☐ Destroyed ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	1 skylight - 1 ladder to skylight to roof. 1 soda acid extinguisher. wood mount and signage.
MISCELLANEOUS:		☐ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 1934-present In question	
SUMMARY:		☒ Good ☐ Fair ☐ Poor ☐ Destroyed	1911-1923 1924-1933 ☒ 1934-present In question	ARCHITECTURAL SIGNIFICANCE: Most ☐ Some ☒ Minor ☐ Negligible ☐

PHOTOGRAPHS: ① view West



CEILING HEIGHT:

DATE: 12/6/85

General:

Stairway serving the second floor with one run. Stair structure is cast iron with square newels, balusters, stringer and wood handrail. Wood built-in cupboards are located beneath the stair run on the first floor.

Treads are diamond patterned pressed metal.

Cast iron.

Painted plaster. Wood cupboard constructed beneath the stair run has a painted blue finish.

Painted plaster.

Good condition. Considerable surface rust. Stair has been overpainted with gray paint.

Good condition.

Surface rusting.

Plaster: considerable loss of finish coat and exposure of structural tile.
Wood: Surface wear and abrasion.

Destroyed.

NOTE: See photographs for room 110.

		Most
		Some
	XXX	Minor
		Negligible

PHOTOGRAPHS:

ROOM NO.

REVISED INTERIOR CONDITION SURVEY FORMS

REVISED INTERIOR CONDITION SURVEY FORMS

Included in this section are the revised survey forms completed for all those buildings surveyed following the discontinuation of interior field work due to the possibility of asbestos being present within the buildings of Units 2, 3 and 4.

These forms treat each structure, or building group, as an entity, and provide a concise summary of the description and condition for each building, or group of buildings, as a whole.

The interior condition survey includes building data (construction date, number of stories, square footage), and general description of the building and its condition by category (structure, rooms, hallways, stairhalls, bathrooms/toilets, unusual features). The form further summarizes the historic use and includes an assessment of condition for each building based upon 1985 field observations, prior reports and documented finish conditions for buildings fully surveyed.

CONSTRUCTION DATE: 1901		NO. OF STORIES: 1 1/2	SQUARE FEET: 7,440				
STRUCTURE:	Brick bearing wall with steel second floor and roof framing. Exposed interior steel and cast-iron columns: first floor. Wood, concrete and composition floors. Wood and slate base. Plaster walls and ceilings. Wood chair rails, doors, door frames and sash.						
ROOMS:	First floor: 10 rooms, 2 halls. Second floor: 11 rooms, central hall. One stairhall. Plaster: general flaking loss of painted finish, random spalling loss. Extensive spalling loss with rusting and loss of underlying wire mesh: linen exchange. Wood floors: loss of finish. Wood trim: general overpainting. Concrete: good condition.						
HALLWAYS:	Plaster walls, concrete and wood floors. Plaster: flaking loss of painted finish. Evidence of early wall finish: second floor hall. Concrete: good condition. Wood floors: loss of surface finish.						
STAIRHALLS:	Cast iron stair: cast iron stringers, risers, newels. Black slate treads and landings. Wrought iron balustrade. Oak rail. Plaster walls and ceiling. Wood chair rail. Iron: surface rust. Ceiling plaster: spalling, loss, exposure of underlying wire mesh.						
BATHROOMS/ TOILET:	Plaster walls. Floor material undocumented.						
UNUSUAL FEATURES:	Laundry equipment: first floor. Exposed simulated Doric cast iron columns: first floor. Metal: surface rusting.						
HISTORIC USE:	1901-1922: Laundry, disinfecting, morgue and autopsy facility. Nurse's housing. 1925-1951: Laundry, linen exchange, nurse's housing. 1951-1954: Coast Guard laundry.						
SUMMARY:	CONDITION:	<table><tr><td>GOOD</td></tr><tr><td>XXX</td></tr><tr><td>FAIR</td></tr><tr><td>POOR</td></tr></table>		GOOD	XXX	FAIR	POOR
GOOD							
XXX							
FAIR							
POOR							

CONSTRUCTION DATE: 1907		NO. OF STORIES	2	SQUARE FEET	4,080								
STRUCTURE:	Structural steel frame on interior cast iron columns and exterior bearing walls. Composition, terrazzo and ceramic tile floors. Plaster walls with glazed tile wainscot in toilets and baths. Plaster ceilings. Wood and marble trim. Metal window and radiator guards.												
ROOMS:	First and second floor: 12 rooms, 1 hallway. One stairhall. Composition flooring: destroyed. Plaster: flaking loss of painted finish, random spalling loss. Severe deterioration: southern rooms, first and second floors. Metal: surface rust.												
HALLWAYS:	Plaster walls and ceilings. Material of flooring: unnoted. Plaster: random spalling with southern section being poor to destroyed.												
STAIRHALLS:	Unexamined.												
BATHROOMS/ TOILET:	White glazed tile wainscot below painted plaster walls. Ceramic tile floors. Marble window and door trim. Tile: good condition. Plaster: flaking loss of painted finish, some spalling. Marble: good condition.												
UNUSUAL FEATURES:	Woven wire interior window guards. Wire mesh pipe and lighting guards: second floor. Metal: surface rusting.												
HISTORIC USE:	1907-1949: Facility for the mentally ill. 1949-1951: Use in question. 1951-1952: Coast Guard sick bay. 1952-1954: Coast Guard sick bay and brig facility.												
SUMMARY:	CONDITION:		<table><tr><td></td><td>GOOD</td></tr><tr><td>XXX</td><td>FAIR</td></tr><tr><td></td><td>POOR</td></tr><tr><td></td><td>DESTROYED</td></tr></table>				GOOD	XXX	FAIR		POOR		DESTROYED
	GOOD												
XXX	FAIR												
	POOR												
	DESTROYED												

CONSTRUCTION DATE: 1901		NO. OF STORIES: 3 1/2	SQUARE FEET: 24,545
STRUCTURE:	Steel frame with structural tile infill on brick bearing walls. Wood,poured and laid composition concrete, ceramic tile and marble floors. Plaster walls with glazed tile wainscot in toilets and baths. Wood chair and picture rails: some rooms. Plaster ceilings. Wood and marble trim. Wood doors.		
ROOMS:	First floor: 16 rooms, 3 hallways. Second floor: 22 rooms, 2 hallways. Third floor: 16 rooms, 1 hallway. Three stairhalls. Laid composition flooring: poor to destroyed condition. Poured composition: some overpainting. Plaster: fair to poor condition, some areas destroyed. Some early painted finish, H104, first floor. Wood doors: fair condition with some removal. Wood doors and trim overpainted.		
HALLWAYS:	Plaster walls with wood chair rail. Plaster ceilings. Poured, composition floors; marble: first floor vestibules. Plaster: fair to poor condition. Some removal of wood chair rail.		
STAIRHALLS:	Unexamined.		
BATHROOMS/ TOILET:	White glazed tile wainscot below painted plaster walls. Ceramic tile floors. Wood and marble trim. Plaster: some loss and exposure of structural tile. Some removal and severe deterioration of wood trim.		
UNUSUAL FEATURES:	Brick fireplace with wood surround and mantelpiece, first floor. Condition: fair. Mantle removed. Operating room: unexamined.		
HISTORIC USE:	1901-1911: Hospital facility. 1911-1914: Not in use. 1914-1951: Hospital facility. 1951-1954: Coast Guard barracks, workshops, offices.		
SUMMARY:	CONDITION:	GOOD FAIR POOR DESTROYED	XXX

CONSTRUCTION DATE: 1907		NO. OF STORIES	SQUARE FEET
		3 1/2	12,850
STRUCTURE:	Steel frame with structural tile infill on bearing walls and interior steel columns. Concrete, wood, tile, composition and marble floors. Plaster walls with glazed tile wainscot in toilets and baths. Wood picture rails: some rooms. Plaster ceilings. Marble and wood window and door trim. Wood doors.		
ROOMS:	First floor: 8 rooms, 1 hallway, 2 vestibules. Second floor: 8 rooms, 1 hallway. Third floor: 14 rooms, 3 hallways. One stairhall. Wood floors: loss of finish; some linoleum overlay of wood floors. Plaster: random exposure of structural tile. Tile wainscot: random removal. Wood trim: deteriorating varnished finish, some overpainting. First floor: walls encased by protective partitioning.		
HALLWAYS:	Linoleum composite tile over wood and concrete subflooring. Plaster walls and ceilings. Wood trim. Wood and metal doors. Linoleum/composite tile: generally poor to destroyed condition. Plaster: random exposure of structural tile. Early painted dado remains in some areas. Wood: some overpainting of varnished finishes.		
STAIRHALLS:	Cast iron stair, slate landing and treads. Wood handrail. Plaster walls and ceilings. Metal: surface rusting. Plaster: some exposure of structural tile. Some evidence of early painted dados.		
BATHROOMS/ TOILET:	White glazed tile wainscot below painted plaster walls. Plaster ceilings. Tile floors. Wood and marble trim. Tile wainscot: some removal. Plaster: some exposure of structural tile.		
UNUSUAL FEATURES:	Area of exposed graffiti: third floor hallway, H301.		
HISTORIC USE:	1907-1951: Hospital facility, Island 2 kitchen. 1951-1954: Coast Guard barracks, offices, kitchen.		
SUMMARY:	CONDITION:	GOOD FAIR POOR DESTROYED	

CONSTRUCTION DATE: 1909		NO. OF STORIES: 2 1/2	SQUARE FEET: 2,600
STRUCTURE:	Brick bearing wall, reinforced concrete floor joists, structural tile infill and wood framed roof. Linoleum, composition tile and terrazzo floors. Plaster walls and ceiling. Wood picture rails. Marble wainscot: bathrooms. Wood doors and trim. Brick fireplaces with wood surrounds. Concrete stair.		
ROOMS:	First floor: 5 rooms, 1 hallway, 2 vestibules. Second floor: 5 rooms, central hall. One stairhall. Linoleum: destroyed. Composition tile: fair condition. Wood floors: loss of surface finish. Plaster: fair to good condition, exposure of structural tile, room 204. Wood trim: generally overpainted.		
HALLWAYS:	Plaster walls. Wood floors. Plaster: flaking loss of painted finish. Wood: deterioration, north section, first floor hall.		
STAIRHALLS:	Concrete risers, stringer. Slate treads, wrought iron balustrade, wood handrail. Stair blocked by large item of furniture.		
BATHROOMS/ TOILET:	Marble wainscot below plaster walls and ceilings. Terrazzo floors with marble border. Unexamined.		
UNUSUAL FEATURES:	Two brick fireplaces with wood surrounds and mantels, first floor. Varnished wood laboratory cupboards, metal laboratory hood: second floor.		
HISTORIC USE:	1911-1928: office, laboratory, pharmacist's quarters. 1928-1951: Nurse's quarters, laboratory.		
SUMMARY:	CONDITON:	GOOD FAIR POOR	XXX

CONSTRUCTION DATE: 1909		NO. OF STORIES: 1	SQUARE FEET: 330
STRUCTURE:	Brick bearing wall. Concrete floor. Plaster walls and ceiling. Wood door and frame.		
ROOMS:	One room. Floor: obscured by debris. Plaster: flaking loss of painted finish. Wood door frame: deterioration and rot, lower section of frame.		
HALLWAYS:			
STAIRHALLS:			
BATHROOMS/ TOILET:			
UNUSUAL FEATURES:	Six wall mounted slate slabs supported by iron brackets have been removed from the mortuary.		
HISTORIC USE:	1909-1928: Morgue. 1928-1951: called "Animal House": laboratory animal housing.		
SUMMARY:	CONDITION:	XXX GOOD FAIR POOR DESTROYED	

CONSTRUCTION DATE: 1908		NO. OF STORIES: 2	SQUARE FEET: 15,660
STRUCTURE:	Concrete slab and concrete pile foundation. Reinforced concrete joists and steel beams on brick bearing walls. Concrete, linoleum and wood floors. Exposed brick, reinforced concrete and plaster walls. Plaster and acoustical tile ceilings, concrete stair. Wood and steel doors. Wood trim.		
ROOMS:	First floor: 14 rooms, one hallway. Second floor: 25 rooms, 2 hallways. Two stairhalls. Wood floors: rotting, area of east chimney. Linoleum: destroyed. Plaster: fair condition. Some spalling and exposure of brick and ceiling structural tile. Some severe water damage. Acoustical tile: staining and loss of tile squares.		
HALLWAYS:	Linoleum floors. Plaster walls and ceilings. Linoleum: destroyed. Plaster: some severe loss of plaster finish.		
STAIRHALLS:	Concrete stair, iron balustrades. Plaster walls and ceilings. Concrete: good condition. Metal: surface rusting. Plaster: unexamined.		
BATHROOMS/ TOILET:	Concrete floors and wainscots. Marble stall partitions. Unexamined.		
UNUSUAL FEATURES:	Exposed steel truss: powerhouse section. Mortuary/autopsy room: stepped concrete observation platform, 8 door cadaver refrigerator.		
HISTORIC USE:	1909-1951: Powerhouse, laundry, employee quarters, isolation pavilion kitchen; 1938: autopsy theatre and morgue. 1951-1954: Powerhouse.		
SUMMARY:	CONDITION:	XXXX GOOD FAIR POOR	XXXX GOOD FAIR POOR

CONSTRUCTION DATE: 1907-1909		NO. OF STORIES	2	SQUARE FEET:	Total for 8 bldgs: 49,160
STRUCTURE:	Concrete joists and steel beams on bearing walls, wood roof framing. Wood, composition, clay terrazzo and ceramic tile floors. Plaster walls and ceilings. Some acoustical ceiling tile. Glazed tile wainscot: bathrooms and toilets. Wood and metal doors and trim. Some wood picture molding.				
ROOMS:	Typical ward: 7 rooms, 1 corridor. Second floor: 7 rooms, 1 corridor. One stair hall. Composition flooring: poor to destroyed condition. Plaster: fair condition. Early painted finish. stairwell Measles Ward D. Wood: general overpainting.				
HALLWAYS:	Specific finishes not noted.				
STAIRHALLS:	Steel stair, slate treads. Plaster walls and ceilings. Metal: surface rusting. Plaster: flaking loss of painted finish. Specific deterioration undocumented.				
BATHROOMS/ TOILET:	Clay, ceramic and terrazzo floors. Clay or glazed tile wainscot below plaster walls and ceilings.				
UNUSUAL FEATURES:	Linen rooms, built-in varnished wood cupboards: probable good condition if original varnished finish remains.				
HISTORIC USE:	1911-1951: Contagious disease wards. 1924: Ward F, warrant cases, stowaway intermnment facility; Wards B and D, storage/closed. 1934: Ward D, ambulatory patients' dining room. 1950: Ward A, E and F, mental wards.				
SUMMARY:	CONDITON:		GOOD FAIR POOR DESTROYED		

XX

CONSTRUCTION DATE: 1907 NO. OF STORIES: 3 1/2 SQUARE FEET: 14,100

STRUCTURE:	Masonry load bearing, reinforced concrete flooring system, wood roof framing. Linoleum, wood, concrete, terrazzo and ceramic tile flooring. Plaster walls and ceiling. Clay tile and glazed tile bathroom wainscot. Wood doors, window and door trim.							
ROOMS:	First floor: 15 rooms, 2 hallways. Second floor: 16 rooms, 2 hallways. Third floor: 17 rooms, 2 hallways. One stairhall. Linoleum: poor to destroyed condition. Wood floors: sound, loss of surface finish. Plaster: fair to good condition with some areas in poor condition due to water infiltration. Wood trim: general overpainting.							
HALLWAYS:	Specific finish and condition undocumented.							
STAIRHALLS:	Concrete risers, stringers, slate treads and landings, wrought iron balustrade, wood hand rail.							
BATHROOMS/ TOILET:	Terrazzo flooring, marble border. Marble wainscot below plaster walls and ceilings.							
UNUSUAL FEATURES:	Second floor: operating room and sterilizing room. Concrete floor and wainscot.							
HISTORIC USE:	1911-1951: Island 3 administrative facility, staff quarters, medical operating facility, staff dining rooms.							
SUMMARY:	<table><tr><td rowspan="3">CONDITON:</td><td>GOOD</td><td></td></tr><tr><td>XX</td><td>FAIR</td></tr><tr><td></td><td>POOR</td></tr></table>	CONDITON:	GOOD		XX	FAIR		POOR
CONDITON:	GOOD							
	XX		FAIR					
		POOR						

CONSTRUCTION DATE: 1907		NO. OF STORIES: 1	SQUARE FEET: 1400
STRUCTURE:	Masonry load bearing, wood roof framing, 10" square clay tile flooring. Glazed tile wainscot below plaster walls and ceiling with exposed plastered beams.		
ROOMS:	Three rooms. Clay and glazed tile wainscot: good condition. Plaster: flaking painted finish.		
HALLWAYS:			
STAIRHALLS:			
BATHROOMS/TOILET:			
UNUSUAL FEATURES:	Paneled oak ice box: north end. Exposed beams.		
HISTORIC USE:	1911-1951: contagious disease ward kitchen.		
SUMMARY:	CONDITION:	GOOD FAIR POOR DESTROYED	

CONSTRUCTION DATE: 1908		NO. OF STORIES	1 1/2	SQUARE FEET	Total for 3 buildings. 20,160
STRUCTURE:	Masonry load bearing walls with steel frames, reinforced concrete joists flooring system and wood roof framing. Concrete, ceramic tile, composition and wood floors. Plaster walls and ceilings. Some glazed tile wainscot. Wood doors and window and door trim.				
ROOMS:	First floor: 14 rooms, 4 hallways. Second floor: 8 rooms, 2 attic spaces, 2 hallways. Two stairhalls. Composition floors: poor to fair condition. Wood, ceramic and concrete floors: good condition. Plaster: good to fair condition, some random cracking and exposure of structural tile. Wood: generally overpainted.				
HALLWAYS:	Concrete floor. Plaster walls and ceiling. Early painted dado remains in some areas.				
STAIRHALLS:	Concrete stair. Plaster walls and ceiling.				
BATHROOMS/ TOILET:	Ceramic tile floor. Glazed tile wainscot below plaster walls and ceilings.				
UNUSUAL FEATURES:	Linen rooms: built-in varnished wood cupboards. Operating room or dental laboratory: Ward I. Skylit ceilings, 2nd floor: destroyed condition, Ward K; unexamined, Wards I and L.				
HISTORIC USE:	1911-1951; Isolation wards, employee quarters. 1920 - c.1934: Ward K, library; 1924 schoolroom. 1938: Ward L, general wards, dental laboratory.				

SUMMARY:	CONDITON:	GOOD	FAIR	POOR	REMARKS
			XXX		

EXTERIOR CONDITION SURVEY FORMS

EXTERIOR CONDITION SURVEY FORMS

As an extension of the original existing condition survey work at Ellis, a new form was developed which describes all materials and finish conditions observed on the exterior of the buildings. The following section includes the forms that were completed for all extant structures of Units 2, 3, and 4. A summary condition evaluation for the building as a whole is included at the end of each form.


CONSTRUCTION DATE: 1934-1936

SURVEY DATE: 12/85

DESCRIPTION:	Stepped central pavilion with tower; 1 story flanking wings. Steel frame resting on exterior bearing walls. Reinforced concrete floor and roof slabs. Brick clad with limestone base; terra cotta roof coping, lintel course, central pavilion window surround; wooden marquee and lead plate clad tower.											
	MATERIALS:	CONDITIONS:										
FACADE FOUNDATION/ BASE:	Brick.	Fair condition. Some cracking: east elevation. Efflorescence: all elevations. Areas of general detachment and flaking loss. Areas of mortar deterioration and loss. Dark biological staining: upper areas, central pavilion.										
TRIM:	Limestone. Terra cotta. Lead plate. ~~Wood marquee.~~	All surfaces exhibit general surface weathering. Cracking and displacement: northeast corner. Iron staining: north and east elevations. Random cracking, flaking and minor loss. Severe cracking, iron staining: south and east elevations. Displacement and loss. Severe deterioration and loss: undersurface.										
ROOF:	Tar with aggregate over composition of 2-5 ply roof felt topped with asphalt and ballast.	Fair condition. Some displacement and loss of tarred overcoating.										
WINDOWS/ DOORS:	Steel sash. Glass. Hollow metal.	Good condition. General surface rusting. Random breakage and loss of glass. Poor condition. Severe deterioration: south and east elevations.										
MISC.:	Ferry dock: wood plank over timber structure.	Poor condition: hazardous. Wood plank: severe deterioration. Large areas of loss, rot. Collapse of dock area. Timber structure: fair condition; requires structural examination.										
SUMMARY:	CONDITION:	<table><tr><td>GOOD</td><td>XXX</td></tr><tr><td>FAIR</td><td></td></tr><tr><td>POOR</td><td></td></tr><tr><td>DESTROYED</td><td></td></tr></table>			GOOD	XXX	FAIR		POOR		DESTROYED	
GOOD	XXX											
FAIR												
POOR												
DESTROYED												



East elevation, view
southeast.



East elevation, view northwest.

CONSTRUCTION DATE: 1901 SURVEY DATE: 1/19/85

DESCRIPTION:	1 1/2 story brick wall structure with steel second floor and roof framing. Brick clad with bluestone sill, brick quoins and limestone trim. Wood sash. Clay tile hip roof with dormers, skylights, wood eave and brick chimney trimmed with limestone, wrought iron and copper. Copper gutters and downspouts.												
	MATERIALS:	CONDITIONS:											
FACADE FOUNDATION/ BASE:	Brick. Bluestone.	Occasional areas of flaking loss and mortar deterioration. General soot staining. Green biological staining: all elevations. Efflorescence under overpaint: north entry. General spalling.											
TRIM:	Brick. Limestone. Wrought iron.	General surface weathering. Carbon soot staining. Occasional copper staining: window sills. Mortar joints caulked with tar: window sills. Iron staining: chimney trim. Surface rusting.											
ROOF:	Clay tile. Glass (skylights). Wood. Copper.	Considerable loss of roof tile. General weathering. Dark discoloration. Some displacement. Loss of most downspouts.											
WINDOWS/ DOORS:	Wood. Glass.	General weathering. Breakage and loss of glass. Occasional metal and wood infill.											
MISC.:	Wood frame enclosure: north elevation.												
SUMMARY:	CONDITION:	<table><tr><td>GOOD</td><td></td></tr><tr><td>FAIR</td><td>XXX</td></tr><tr><td>POOR</td><td></td></tr><tr><td>DESTROYED</td><td></td></tr></table>				GOOD		FAIR	XXX	POOR		DESTROYED	
GOOD													
FAIR	XXX												
POOR													
DESTROYED													



South elevation, view northeast.



North elevation, view southeast.

CONSTRUCTION DATE: 1907		SURVEY DATE: 5/2/86	
DESCRIPTION:	2 story steel frame resting on interior cast iron columns and exterior bearing walls. Brick clad with concrete base parging. Limestone quoins, window sills, springers and keystones. Terra cotta cornice. Wood sash with wrought iron grilles. Flat composition roof and brick, limestone and wrought iron parapet, copper downspouts.		
	MATERIALS:	CONDITIONS:	
FACADE FOUNDATION/ BASE:	Brick. Cement parging.	Flaking loss of brick surfaces. Some areas of severe weathering and erosion. Cracking: west elevation. Severe cracking: south elevation. General mortar deterioration. Random efflorescence. Some green biological staining: lower areas. Green biological staining. Rust staining.	
TRIM:	Limestone. Terra cotta. Wrought iron.	General surface weathering. Carbon soot staining. Dislodged parapet coping block: south elevation. Painted signage: 1st quoin, all elevations. Damage due to removal of downspouts. Rust staining. Carbon soot deposits. Surface rusting.	
ROOF:	Composition. Copper.	Not examined. Loss of downspouts.	
WINDOWS/ DOORS:	Wood. Glass.	Flaking loss of painted finish. Weathered exposed wood surfaces. Alteration and infill: west elevation. Breakage, loss.	
MISC.:	Metal stair: south elevation.	Corrosion and loss. Loss of ground level support.	
SUMMARY:	CONDITION:	GOOD FAIR POOR DESTROYED (south elevation)	



South elevation, View northeast.



East elevation, view northwest.

CONSTRUCTION DATE: 1901

SURVEY DATE: 5/2/86

DESCRIPTION:	3 1/2 story central pavilion with two 2 1/2 story wings, connected by recessed bays. Steel frame with structural tile infill resting on brick bearing walls. Brick clad with granite base. Limestone quoins, sill and lintel coursing, window and door trim. Wood sash. Wood doors. Granite stairs with limestone balustrade. 2 story south elevation verandahs with steel framing, concrete floors, steel columns, balustrades and stairs. Central pavilion clay tile hip roof with copper ridge, limestone chimney coping cornice, and copper cheneau. Copper, brick and limestone dormers. Wing and connecting bay dormered clay tile hip and tarred flat. (CONTINUED ON BACK)		
	MATERIALS:	CONDITIONS:	
FACADE FOUNDATION/ BASE:	Brick Granite.	Some spalling and loss: north elevation. General mortar deterioration. Efflorescence: all elevations. Carbon soot staining: all elevations. Good condition: carbon soot staining. General mortar loss.	
TRIM:	Limestone. Concrete paving. Metal.	General weathering. Mortar loss. Copper staining: window sills below flyscreens, cornice and under removed downspouts. Carbon soot staining: protected areas. Iron staining: below north elevation center dormer. Cracking, spalling and loss. General corrosion. Displacement and loss: south elevation verandahs.	
ROOF:	Clay tile. Copper.	Generally intact. Random loss of individual tiles. Sheathing of skylight sidewalls: extensive loss. Some loss of ridge: west wing. Replacement of north elevation center dormer roof with ferrous metal. Loss of gutters: south elevations (CONTINUED ON BACK)	
WINDOW S/ DOORS:	Wood. Metal/copper sash. Glass.	Flaking loss of painted finish. Deterioration of wood sub-surface. Displacement and loss of sash parts. Some infill of dormer pivot sash. Random breakage.	
MISC.:			
SUMMARY:	CONDITION:	GOOD FAIR POOR DESTROYED	

DESCRIPTION (continued)

roofs with wire glass, metal and copper sash, tile walled skylights.

MATERIALS:

Copper

Tarred surface.

ROOF: (continued)

CONDITIONS:

of wings. Perforations of surfaces: gutters.




North elevation, view southwest.




South elevation, view northwest.

CONSTRUCTION DATE: 1907		SURVEY DATE:		Administration Building		
DESCRIPTION:	3 1/2 story with recessed connecting bays. Steel frame with structural tile infill on brick bearing walls and interior steel columns. Brick clad with granite base. Limestone quoins, sill and lintel coursing, window and door trim. Wood sash covered by plexiglass panels. Wood doors. Granite stairs with limestone balustrades. Clay tile hip roof with copper ridge, terra cotta cornice, chimney coping, copper cheneau and brick, terra cotta and copper dormers.					
	MATERIALS:	CONDITIONS:				
FACADE FOUNDATION/ BASE:	Brick. Granite.	Good condition. Random mortar deterioration. Efflorescence: all elevations. Severe green biological growth: west connector, north elevation.				
TRIM:	Limestone. Terra cotta.	General weathering. Random iron staining. Carbon soot, green biological and copper staining. General weathering. Some areas of surface cracking and crazing. Carbon soot deposits: protected areas.				
ROOF:	Clay tile. Copper.	Good condition. Good condition.				
WINDOWS/ DOORS:	Wood. Glass. Plexiglass.	Good condition.				
MISC.:						
SUMMARY:	CONDITION:	XXX	GOOD	FAIR	POOR	DESTROYED



North elevation, view east.



Entrance, south elevation.

CONSTRUCTION DATE: 1909 SURVEY DATE: 11/1986

DESCRIPTION:	3 1/2 story central pavilion with two 2 1/2 story wings connected by recessed bays. Steel frame and bearing wall construction. Brick clad with granite base. Limestone quoins, sill and lintel coursing, window and door surrounds. Wood sash. Wood doors. Granite and concrete stairs with limestone and brick stairwalls. 2 story south south elevation verandahs with granite foundations, steel framing, brick and terra cotta cladding, concrete parging, and basement wrought iron window grilles. Central pavilion clay tile hip roof (CONTINUED ON BACK)		
	MATERIALS:	CONDITIONS:	
FACADE FOUNDATION/ BASE:	Brick.	Random areas of cracking: all elevations. Severe bulging and displacement: south elevation porches. General carbon soot staining. Green biological staining. Moderate to severe efflorescence. Flaking loss. Random mortar deterioration and displacement. Carbon soot staining. Green biological staining.	
	Granite.		
TRIM:	Limestone.	General weathering. Random iron staining. Copper staining: window sills below flyscreens.	
	Terra cotta.	Chipping, breakage and loss: cornice block. Displacement: northeast corner, east elevation. Severe displacement, spalling and loss: south elevation verandahs.	
	Concrete parging.	Poor condition: verandah balustrades; rust staining. spalling, and loss. Surface cracking, random loss: stair parging. (CONTINUED ON BACK)	
ROOF:	Clay tile.	Frequent displacement and loss.	
	Copper.	Tearing and loss of valley and ridge flashing. North elevation center dormer: damaged. South elevation dormer: loss of dormer.	
	Tarred surface.	Areas of erosion and loss.	
WINDOW S/ DOORS:	Wood.	Flaking loss of painted finish. General surface weathering. Wood rot and random loss. Severe deterioration: east elevation door.	
	Metal/copper sash.	Random breakage and loss.	
	Glass.		
MISC.:	Wood frame sheds: south elevations.	Deteriorated.	
SUMMARY:	CONDITION:	GOOD FAIR POOR DESTROYED XXX XXX (south elevation verandahs)	


DESCRIPTION:
(CONTINUED)

with terra cotta
cornice, dormer
cotta dormers. Wing and connecting bay clay tile domtered hip and tarred flat roofs with
wire glass metal and copper sash, tile walled skylights.

TRIM: (CONTINUED)

MATERIALS:
Concrete parging.
Wrought iron/exposed steel framing.

CONDITIONS:
Copper staining: south and east elevation stairs.
Pitting and surface rusting. Severe corrosion,
delamination, displacement and compression: south
verandah exposed framing.



North elevation, view South.



South elevation, view northwest.

CONSTRUCTION DATE: 1909		SURVEY DATE: 11/20/85	
DESCRIPTION:	2 1/2 story brick bearing wall structure with reinforced concrete floor joists, structural tile infill and wood framed roof. Pebble dash stucco facade, brick base, window springers and keystones. Limestone window sills and north elevation portico. Granite stair. Wood doors and window sash. Clay tile hip roof with copper dormers. Wood eave. Copper gutters.		
	MATERIALS:	CONDITIONS:	
FACADE FOUNDATION/ BASE:	Pebble dash. Brick.	Fair condition. Random loss of surface aggregate. Some separation of surface layer of stucco from subsurface: west elevation. Cracking. Carbon soot staining and spotty green biological staining. Vine cover. Carbon soot and green biological staining. Spotty mortar loss.	
TRIM:	Brick. Limestone. Granite.	Spotty mortar loss. Surface weathering. Carbon soot and copper staining.	
ROOF:	Clay tile. Wood. Copper.	Poor condition, loss of roof and ridge tile. Surface weathering. 70% loss of wood eave: west elevation. Loss of downspouts.	
WINDOWS/ DOORS:	Glass. Wood.	Random breakage. Some wood and masonite infill. Surface weathering.	
MISC.:			
SUMMARY:	CONDITION:	GOOD FAIR POOR DESTROYED	



View southwest.



Portico, north elevation.

CONSTRUCTION DATE: 1909

SURVEY DATE: 11/20/85

DESCRIPTION:	1 story brick bearing wall structure. Pebble dash stucco facade and brick base, quoins, window springers and keystones. Limestone window sills. Wood door and sash. Clay tile hip roof with copper roof ventilator and gutters.			
	MATERIALS:	CONDITIONS:		
FACADE FOUNDATION/ BASE:	Pebble dash. Brick.	Damage due to removal of downspout. Vine cover. Carbon soot staining. Green biological staining. Some possible overpainting. Cracking: north elevation. Carbon soot and green biological staining. Spotty mortar loss.		
TRIM:	Brick. Limestone.	Spotty mortar loss. Carbon soot staining.		
ROOF:	Clay tile. Wood. Copper.	Appears in stable condition. Surface weathering. Loss of downspouts. Punctured surfaces.		
WINDOWS/ DOORS:	Wood.	Surface weathering.		
MISC.:	Iron door in base: north elevation.	Corrosion and exfoliation of lintel. General rusting.		
SUMMARY:	CONDITION:	GOOD FAIR POOR DESTROYED		




West elevation, view from covered way 9A.

CONSTRUCTION DATE: 1908

SURVEY DATE: 11/21/85

DESCRIPTION:	CONDITIONS:	
2 story. Concrete slab and concrete pile foundation with reinforced concrete joists, steel beams on bearing walls and wood roof framing. Pebble dash stucco facade with brick base and granite sill. Brick quoins, window springers and keystones with limestone sills. Wood sash. Clay tile hip roof supported on wood eave and brackets. Copper gutters and downspouts.		
	MATERIALS:	
FACADE FOUNDATION/ BASE:	Pebble dash stucco. Brick. Granite. Brick. Limestone.	Fair condition. Some loss of aggregate. Cracking at infill and repair areas. Carbon soot staining. Spotty green biological staining. Iron staining. Vine cover. Carbon soot staining. Green biological staining. Cracking of random base areas with displacement at the west elevation. Random mortar separation and loss.
TRIM:		Carbon soot staining. Surface weathering. Some over painting.
ROOF:	Clay tile. Wood. Copper.	Random areas of displacement and loss. Weathered surfaces. Flaking loss of painted finish. Loss of downspouts. Perforations of ventilator surfaces.
WINDOWS/ DOORS:	Wood. Glass. Steel doors: west elevation.	General loss of finish. Weathered wood surfaces. Breakage and loss of glass. Some infill of windows. Installation of metal window grilles: south elevation. Surface corrosion.
MISC.:	Metal fireescapes: south and east elevations. Octagonal yellowbrick chimney stack. Metal fan/vent housing.	General rusting. Vine cover above roof level. Mortar loss. General corrosion and loss.

SUMMARY:	CONDITION:	GOOD FAIR POOR DESTROYED
	XXX	



West elevation, view north.



South elevation, view east.

CONSTRUCTION DATE: 1908		SURVEY DATE: 5/1/86	
DESCRIPTION:	2 stories. Concrete joists and steel beams on bearing walls; wood roof framing. Pebble dash stucco facade, brick base, granite sill. Brick quoins, window springers, keystones. Limestone window lintels, sills. Wood sash. Clay tile hip roof. Wood eaves. Copper roof ventilator, gutters. North elevation connected to corridor 9B.		
	MATERIALS:	CONDITIONS:	
FACADE FOUNDATION/ BASE:	Pebble dash stucco. Brick. Granite.	Severe carbon soot staining at juncture with corridor 9B and under eaves. Random loss of pebble dash aggregate. Vine cover: west elevation. Biological staining.	
TRIM:	Brick. Limestone.	Copper staining: east elevation.	
ROOF:	Clay tile. Wood. Copper.	General weathering. Loss of downspouts.	
WINDOWS/ DOORS:	Wood. Glass. South elevation: no door.	Surface weathering. Some opaque glass, inconsistent type. Broken glass, masonite infill.	
MISC.:	Chain link fence: west end of south elevation. Masonite hood shaped structure constructed against west elevation.	Flaking blue overpaint.	
SUMMARY:	CONDITION:	GOOD FAIR POOR DESTROYED	
		XXX	



South elevat: 7, view north.




West elevation at connection with covered way 9B.

CONSTRUCTION DATE: 1908		SURVEY DATE: 5/1/86	
DESCRIPTION:	2 stories. Concrete joists and steel beams on bearing walls; wood roof framing. Pebble dash stucco facade, brick base, granite sill. Brick quoins, window springers, keystones. Limestone window lintels, sills. Clay tile hip roof. Wood eaves. Copper gutters. North elevation connected to corridor 9D.		
	MATERIALS:	CONDITIONS:	
FACADE FOUNDATION/ BASE:	Pebble dash stucco.	Some cracking, often from corner of window sill. Patchy loss of aggregate: west elevation, south end. Carbon soot staining at juncture with corridor. 9D and under eaves.	
	Brick.	Random mortar loss. Some damage to brick in area of pipe protruding from interior of building: north end, east elevation. Cracking and damaged brick: west end of south elevation.	
	Granite. Brick. Limestone.	Green biological staining. Efflorescence.	
TRIM:			
ROOF:	Clay tile. Wood eave. Copper gutters.	Weathered surfaces.	
WINDOWS/ DOORS:	Wood sash.	Deteriorated finish, weathered sash. Some opaque glass infill, inconsistent with window glass type.	
MISC.:			
SUMMARY:	CONDITION:	GOOD XXX FAIR POOR DESTROYED	



South elevation, view north.



East elevation, view west.


CONSTRUCTION DATE: 1909

SURVEY DATE: 5/1/86

DESCRIPTION:	2 stories. Concrete joists and steel beams on bearing walls; wood roof framing. Pebble dash stucco facade, brick base, granite sill. Brick quoins, window springers, keystones. Limestone window lintels, sills: wood and steel sash. Clay tile hip roof. Wood eaves. Copper roof ventilator, gutters. South elevation connected to corridor 9B.		
	MATERIALS:	CONDITIONS:	
FACADE FOUNDATION/ BASE:	Pebble dash stucco. Brick. Granite.	Olive green coloration due to green biological staining. Heavy vine cover: west elevation. Severe biological staining: west elevation.	
TRIM:	Brick. Limestone.	General weathering.	
ROOF:	Clay tile. Wood eaves. Copper gutters/roof ventilator.	Loss of several ridgetop tiles: west hip, north elevation. Surface weathering. Damage to gutters due to tree abrasion. Loss of downspouts. Perforations.	
WINDOWS/ DOORS:	Wood sash: first floor. Steel sash. Metal door with 9-light windows: north elevation.	Weathered surfaces. Some opaque glass infill. Flaking paint, surface rust. Flaking paint, rusting.	
MISC.:	Metal stair with wire grille enclosure: north elevation. Concrete stair: north elevation.	Rusting. Cracking.	
SUMMARY:	CONDITION:	GOOD FAIR POOR DESTROYED	




East elevation, view west.




West elevation, view southeast.

CONSTRUCTION DATE: 1909		SURVEY DATE: 5/1/86									
DESCRIPTION:	2 stories. Concrete joists and steel beams on bearing walls; wood roof framing. Pebble dash stucco facade, brick base, granite sill. Brick quoins, window springers, keystones. Limestone window lintels, sills. Wood sash. Clay tile hip roof. Wood eaves. Copper gutters. South elevation connected to corridor 9D.										
	MATERIALS:	CONDITIONS:									
FACADE FOUNDATION/ BASE:	Pebble dash stucco. Brick. Granite.	Carbon soot staining: undersurfaces. Vinecover: north and east elevations. Random cracking: northwest window, west elevation, and northeast window, east elevation. Green biological staining which extends upwards in areas of removed downspouts. Efflorescence. Random mortar loss.									
TRIM:	Brick. Limestone.										
ROOF:	Clay tile. Wood. Copper.	Loss of one ridgetop tile: west hip, north elevation. Gutters clogged with growth. Loss of downspouts.									
WINDOWS/ DOORS:	Wood. Glass.	Weathered surfaces. Some opaque infill.									
MISC.:											
SUMMARY:	CONDITION:	<table><tr><td>GOOD</td><td>FAIR</td><td>POOR</td><td>DESTROYED</td></tr><tr><td>XXX</td><td></td><td></td><td></td></tr></table>		GOOD	FAIR	POOR	DESTROYED	XXX			
GOOD	FAIR	POOR	DESTROYED								
XXX											



west elevation, view east.



North elevation, view south.

CONSTRUCTION DATE: 1908		SURVEY DATE: 5/1/86	
DESCRIPTION:	2 stories. Concrete joists and steel beams on bearing walls; wood roof framing. Pebble dash stucco facade, brick base, granite sill. Brick quoins, window springers, keystones. Limestone window lintels, sills. Steel sash. Clay tile hip roof. Wood eaves. Copper roof ventilator, gutters. North elevation connected to corridor 9B.		
	MATERIALS:	CONDITIONS:	
FACADE FOUNDATION/ BASE:	Pebble dash stucco. Brick. Granite.	Vine cover: east elevation. Carbon soot staining: under eaves and undersurfaces. Biological staining.	
TRIM:	Brick. Limestone.		
ROOF:	Clay tile. Wood. Copper.	General weathering.	
WINDOW S/ DOORS:	Steel sash, wire glass. Door with wire screen: second level, south elevation.	Tar or black paint: underside of window lintel. Alteration: original window opening.	
MISC.:	Concrete stair: south elevation. Iron stair with wire grille enclosure: south elevation.	Surface rusting.	
SUMMARY:	CONDITION:	GOOD FAIR POOR DESTROYED	



South elevation.




East elevation

CONSTRUCTION DATE: 1909		SURVEY DATE: 5/1/86	
DESCRIPTION:	2 stories. Concrete joists and steel beams on bearing walls; wood roof framing. Pebble dash stucco facade, brick base, granite sill. Brick quoins, window springers, keystones. Limestone window lintels, sills. Wood sash. Clay tile hip roof. Wood eaves. Copper roof ventilator, gutters. North elevation connected to corridor 9D.		
	MATERIALS:	CONDITIONS:	
FACADE FOUNDATION/ BASE:	Pebble dash stucco. Brick. Granite.	Minor cracking. Random loss of surface aggregate: west elevation. Efflorescence. Green biological staining.	
TRIM:	Brick. Limestone.	Efflorescence: west elevation.	
ROOF:	Clay tile. Wood. Copper.	Loss of downspouts.	
WINDOWS/ DOORS:	Wood. Glass.	Some deterioration of sash. Some opaque glass. Random broken glass panes. South elevation: holes remain within window opening as a result of removal of grilles. First floor: masonite and wood infill.	
MISC.:	Concrete stair: south elevation.	Cracking.	
SUMMARY:	CONDITION:	GOOD FAIR POOR DESTROYED	
	XXXX		



CONSTRUCTION DATE: 1909		SURVEY DATE: 5/1/86	
DESCRIPTION:	2 stories. Concrete joists and steel beams on bearing walls; wood roof framing. Pebble dash stucco facade, brick base, granite sill. Brick quoins, window springers, keystones. Limestone window lintels, sills. Steel sash. Clay tile hip roof. Wood eaves. Copper roof ventilator, gutters. South elevation connected to corridor 9B.		
	MATERIALS:	CONDITIONS:	
FACADE FOUNDATION/ BASE:	Pebble dash stucco. Brick. Granite.	Vine cover. Carbon soot staining: under eaves, undersurfaces. Green biological staining. Random loss. Area of exposed brick under surface: west elevation. Some efflorescence of brick base. Severe green biological staining: protected areas.	
TRIM:	Brick. Concrete stair balustrades. Limestone.	Cracked, rust stained. North elevation: rust staining of some window sills.	
ROOF:	Clay tile. Wood. Copper.	Loss of several roof tiles: west elevation. General weathering. General weathering. Random gutter perforations. Loss of downspouts. Some crushing of gutter.	
WINDOWS/ DOORS:	Steel sash. Glass.	Surface rusting. Random broken glass. Installation of metal grilles: second floor windows, west and south elevations.	
MISC.:	Metal stair with wire enclosure: to second level, north elevation.	Rusting. Detachment of sections of stair enclosure.	
SUMMARY:	CONDITION:	GOOD FAIR POOR DESTROYED	

XXX



North elevation, exterior stair.



North elevation, view south.



CONSTRUCTION DATE: 1909

SURVEY DATE: 5/1/86

DESCRIPTION:	2 stories. Concrete joists and steel beams on bearing walls; wood roof framing. Pebble dash stucco facade, brick base, granite sill. Brick quoins, window springers, keystones. Limestone window lintels, sills. Wood sash. Clay tile hip roof. Wood eaves. Copper roof ventilator, gutters. South elevation connected to corridor 9D.				
	MATERIALS:	CONDITIONS:			
FACADE FOUNDATION/ BASE:	Pebble dash stucco. Brick Granite.	Vine cover. Cracking in area of north elevation first floor windows with evidence of gray and tan cementitious repair. Vertical cracking north elevation. Green biological staining. Green biological staining.			
TRIM:	Brick. Limestone.				
ROOF:	Clay tile. Wood. Copper.	Loss of several hipcapping tiles: north hip. Weathered, dark discoloration of some areas. Loss of downspouts. Gutter clogged with growth.			
WINDOWS/ DOORS:	Wood. Glass. Metal door with 9 lights: north elevation. Concrete stair: north elevation.	Some deterioration of wood sash. Installation of wood vent: west elevation. Random broken glass. Wood and opaque glass infill and replacement.			
MISC.:					
SUMMARY:	CONDITION:	GOOD FAIR POOR DESTROYED			



North elevation, view south.




East and north elevations, view southwest.


CONSTRUCTION DATE: 1907

SURVEY DATE: 5/1/86

DESCRIPTION:	3 1/2 stories. Masonry load bearing structure, reinforced concrete flooring system, wood framed roof. Pebble dash facade, brick base, granite sill. Brick quoins, window springers, keystones. Limestone window lintels, sills and main entrance surround. Granite entrance stair. Wood sash. Clay tile hip roof. Wood eaves and dormers. Copper roof ventilators and gutters. South elevation connected to corridor 9C.			
	MATERIALS:	CONDITIONS:		
FACADE FOUNDATION/ BASE:	Pebble dash stucco. Brick. Granite.	Appears sound. Random areas of damage and cracking. Green biological staining of lower surfaces. Vine cover: west elevation, severe on north elevation. Efflorescence and green biological staining.		
TRIM:	Brick. Limestone. Granite.	Damage and displacement of bricks due to downspout removal: east elevation.		
ROOF:	Clay tile. Wood. Copper.	General weathering and dark discoloration of wood eave. Loss of lower section of northwest downspout.		
WINDOWS/ DOORS:	Wood. Glass. Iron balustrades: east and west elevations.	Weathered. Random broken panes. Some opaque glass replacement. Rusting of metal surfaces.		
MISC.:				
SUMMARY:	CONDITION:	GOOD FAIR POOR DESTROYED		



North and east elevations, view
southwest.



North entrance.

CONSTRUCTION DATE:

SURVEY DATE:

DESCRIPTION:	1 story. Masonry load bearing structure, wood framed roof. Pebble dash stucco facade, brick base, granite sill. Brick quoins, window springers, keystones. Limestone window sills. Wood and metal sash. Brick chimney constructed against east elevation. Clay tile hip roof, flat composition, north connector. Wood eaves. Roof ventilator. Copper gutters.		
	MATERIALS:	CONDITIONS:	
FACADE FOUNDATION/ BASE:	Pebble dash stucco. Brick. (continued on back of page)	Severe green biological staining under removed downspout: west elevation Severe carbon soot staining. Ghost of removed structure: south elevation; holes in pebble dash stucco. Spalling loss: west elevation of connector. Random flaking loss. Damage and loss of brick: east end south elevation. Loss of section of west elevation base of connector to corridor 9C. Efflorescence. Carbon soot staining of window sills.	
TRIM:	Brick. Limestone.		
ROOF:	Clay tile. Composition. Wood. Copper.	Broken tile: east elevation. Condition obscured by severe vegetative growth. Deteriorated tarred surface. Weathered. Loss of copper ventilator cladding. Loss of downspouts.	
WINDOWS/ DOORS:	Wood sash. Metal sash. Wood door: south elevation.	Infilled windows on either side of chimney: east elevation. Tar smeared above windows: east and south elevation. Corrosion. Flaking paint.	
MISC.:	Granite stair, metal railing.	Loss of east railing.	
SUMMARY:	CONDITION:	GOOD FAIR POOR DESTROYED	
		XX	

CONDITIONS:

MATERIALS:
Granite

FACADE
FOUNDATION/
BASE.
(continued)




South elevation.



East elevation.

CONSTRUCTION DATE: 1909		SURVEY DATE: 12/85, 5/1/86	
DESCRIPTION:	1 1/2 stories. Masonry bearing walls with steel frame and reinforced concrete joist flooring system. Pebble dash stucco facade, brick base and granite belt course. Brick quoins, string coursing, window springers and keystones. Limestone window sills. Granite stoop with iron railing. Wood sash. Clay tile hip roof with dormers, copper ventilators and skylights. Wood eaves. Copper gutters. North elevation connected to covered way 9A.		
	MATERIALS:	CONDITIONS:	
FACADE FOUNDATION/ BASE:	Pebble dash stucco. Brick. Granite.	Carbon soot staining; severe in north protected areas and under eave, east elevation. Vine cover: north and east elevation. Green biological staining. Efflorescence. Random mortar loss. Carbon soot staining. Green biological staining.	
TRIM:	Brick. Limestone.	Carbon soot staining under eaves. Weathered surfaces. Chipping: window sill.	
ROOF:	Clay tile. Wood. Copper. Dormers.	Weathering. Random loss of eave parts. Damage to eave horizontal boards: west end, central bay. Loss of downspouts.	
WINDOWS/ DOORS:	Wood. Glass.	Weathered wood sash. Random broken glass. Infill of second window from south end: west elevation.	
MISC.:	Iron vent door: south elevation. Granite stoop. Iron railings.	Rusting.	
SUMMARY:	CONDITION:	GOOD FAIR POOR DESTROYED	



South elevation, view northeast.

CONSTRUCTION DATE: 1909		SURVEY DATE: 12/85, 5/1/86	
DESCRIPTION:	1 1/2 stories. Masonry bearing walls with steel frame and reinforced concrete joists flooring system. Pebble dash stucco facade, brick base and granite belt course. Brick quoins, string coursing and springers and keystones. Limestone window sills. Granite stoops with iron railings. Wood sash. Clay tile hip roof with dormers; copper ventilators and skylights. Wood eaves. Copper gutters. North elevation connected to covered way 9A.		
	MATERIALS:	CONDITIONS:	
FACADE FOUNDATION/ BASE:	Pebble dash stucco. Brick. Granite.	Application of tar or paint under window sills. Vine cover: north and west elevations. Green biological staining.	
TRIM:	Brick. Limestone. Concrete.	Carbon soot staining under eaves. Surface weathering.	
ROOF:	Clay tile. Wood. Copper. (CONTINUED ON BACK OF PAGE)	Random loss of tile. Weathered. Some displacement. Loss of downspouts. Perforated surfaces. Deformation of some areas of gutters.	
WINDOWS/ DOORS:	Wood. Glass.	Loss of wood sash parts: south elevation. Installation of window: north elevation, west bay, with concrete lintel. Random broken glass. Spot light protrudes from dormer window.	
MISC.:	Granite stoop with iron railing. Metal vent door: south elevation.	Rusting of metal.	
SUMMARY:	CONDITION:	GOOD FAIR POOR DESTROYED	

DESCRIPTION:

ROOF:

(continued)

MATERIALS:

Dormers

CONDITIONS:

Some loss of tile side walls.



East elevation, view northwest



South elevation, view northwest.


CONSTRUCTION DATE: 1908

SURVEY DATE: 12/85, 5/1/86

DESCRIPTION:	1 1/2 stories. Masonry bearing walls with steel frame and reinforced concrete joists flooring system. Pebble dash stucco facade, brick base and granite belt course. Brick quoins, coursing. and window springers and keystones. Limestone window sills. Granite stoops with iron railings. Wood sash. Clay tile hip roof with dormers, copper ventilators and skylights. Wood eaves. Copper gutters. Not connected to covered way 9A.		
	MATERIALS:	CONDITIONS:	
FACADE FOUNDATION/ BASE:	Pebble dash stucco. Brick. Granite.	Coating of carbon soot. Occasional diagonal cracking, usually at brick springer and limestone sill. Cracking: central bay, north elevation. Efflorescence. Green biological staining. Carbon soot staining. Green biological staining. Carbon soot staining.	
TRIM:	Brick. Limestone.	Carbon soot staining under eaves. Surface weathering.	
ROOF:	Clay tile. Wood. Copper. Dormers.	Random dislodged tiles. Loss of eave parts: north elevation near center dormer. Clogged gutters. Loss of downspouts. Tar applied to side walls of dormers.	
WINDOWS/ DOORS:	Wood. Wood door: east elevation.	Dormer windows: displacement of sash. Stucco infill: second window from north end: east elevation. Lifting of overpaint. Rusting of metal lintel.	
MISC.:	Granite stoop. Iron stair railings.	Lower concrete step: displaced. Rusting.	
SUMMARY:	CONDITION:	GOOD FAIR POOR DESTROYED	



North elevation, view southwest.



West and north elevations, view east.

CONSTRUCTION DATE: 1909		SURVEY DATE: 11/27/85	
DESCRIPTION:	2 1/2 story masonry load bearing structure . Pebble dash stucco facade, brick base, granite base course and east elevation stair. Brick quoins, springers, keystones. Limestone window sills, west elevation portico, east elevation porch columns and south elevation stair treads. Wood doors. Wood and metal sash with 1st floor wrought iron trim. Clay tile hip roof with copper dormers and gutters.		
	MATERIALS:	CONDITIONS:	
FACADE FOUNDATION/ BASE:	Pebble dash stucco. Brick. Granite.	Olive-green coloration due to green biological staining. Vine cover. Carbon soot staining on under surfaces. Patching and infill. Some separation at limestone sills. Cracking. Severe green biological growth. Random mortar loss. Minor cracking of brick surfaces. Random flaking loss. Carbon soot staining.	
TRIM:	Brick. Limestone. Iron. /	Random mortar loss. Gray overpaint: portico. Copper and iron staining. General weathered surfaces. Rusting and pitting.	
ROOF:	Clay tile. Wood. Copper.	Random loss of clay tile. Dislodged hip capping. Weathered. Displacement and loss of parts. Loss of downspouts. Perforations of gutter surfaces. Dormers are coated with tar. Torn flashing. Clogged gutters.	
WINDOWS/ DOORS:	Wood. Metal.	Weathered. Corrosion, deterioration and loss.	
MISC.:			
SUMMARY:	CONDITION:	GOOD FAIR POOR DESTROYED	



South and east elevations, view north.




North and west elevations, view south east.

CONSTRUCTION DATE: 1935		SURVEY DATE: 1/17/85	
DESCRIPTION:	1 story masonry bearing wall with roof and floor of concrete joists and beams. Brick clad with terra cotta window sills and roof coping faced with copper flashing. Steel sash. Hollow metal and wood doors. Flat wood roof surfaced with tar containing small aggregate. Metal roof ventilators.		
	MATERIALS:	CONDITIONS:	
FACADE FOUNDATION/ BASE:	Brick.	General flaking loss. Cracking: east elevation. Random mortar deterioration and separation from brick surfaces. Efflorescence: all elevations.	
TRIM:	Terra cotta. Copper.	General weathering: Random chipping. Iron staining: most sill surfaces. Carbon soot staining. Biological staining: window sills, most elevations.	
ROOF:	Tar/aggregate. Metal.	Fair condition. Bubbling along roofing felt seams. Water accumulation: southeast corner, south wing. Some damage and areas of loss.	
WINDOWS/ DOORS:	Steel. Glass. Hollow metal. Wood.	General surface pitting and rusting. General loss of painted finish. General cracking, breaking and loss of glass. Rusting resulting in some loss. Replacement. Severely deteriorated.	
MISC.:	Metal and wood grilles.	Wood: some deterioration and loss.	
SUMMARY:	CONDITION:	GOOD FAIR POOR DESTROYED XXX	




North elevation, view southwest.



East elevation, view southwest towards Covered way 7B.

CONSTRUCTION DATE: 1937		SURVEY DATE: 2/9/85	
DESCRIPTION:	2 story steel frame and masonry bearing wall on concrete spread footings and piles. Brick cladding with limestone base and limestone terra cotta trim. Steel sash. Wood and metal doors. Clay tile gable roof and flat felt, asphalt and ballast wing roofs. Copper gutters with lead coated copper downspouts.		
	MATERIALS:	CONDITIONS:	
FACADE FOUNDATION/ BASE:	Brick. Limestone.	Vertical cracking and bulging: east elevation. Some flaking loss and fine cracking of surfaces. Random mortar loss. Vine growth: east elevation. Efflorescence: all elevations. Green biological staining. Copper staining. General weathering. Black crust in protected areas.	
TRIM:	Terra cotta. Limestone.	Horizontal cracking: east elevation. Carbon soot staining: protected areas. Chipping and flaking loss. Mortar loss. Surface weathering. Black crust: protected areas. Some iron staining: north and west elevations.	
ROOF:	Clay tile. Roof felt/asphalt/ballast. Copper.	Intermittant loss of tile with 4 foot wide swath of loss: east elevation. Gutters and downspouts: clogging, damage and loss of parts.	
WINDOWS/ DOORS:	Steel/metal. Wood. Glass.	Surface corrosion. Plexiglass and wood window infill.	
MISC.:			
SUMMARY:	CONDITION:	GOOD FAIR POOR DESTROYED	



East elevation.




North elevation, view southwest.


CONSTRUCTION DATE: 1937

SURVEY DATE: 5/1/86

DESCRIPTION:	1 story pavilion with central open double colonnade. Masonry load bearing walls with reinforced concrete slab floor on spread footings and piles. Brick clad with terra cotta trim. Steel sash. Wood and glass paneled doors to north and south rooms. Flat felt, asphalt and ballast roof.													
	MATERIALS:	CONDITIONS:												
FACADE FOUNDATION / BASE:	Brick	Areas of mortar loss: north and west elevations. Efflorescence: all elevations. Vine cover. Green biological staining: upper areas of west and north elevations.												
TRIM:	Terra cotta	General surface weathering, chipping, spalling and some breakage. Mortar disintegration. Carbon soot staining.												
ROOF:	Roof felt /asphalt/ballast													
WINDOWS/ DOORS:	Steel Wood Glass	General surface rusting. Some breakage of window glass: east facade.												
MISC.:														
SUMMARY:	CONDITION:	<table><tr><td>GOOD</td><td></td></tr><tr><td>FAIR</td><td>XXX</td></tr><tr><td>POOR</td><td></td></tr><tr><td>DESTROYED</td><td></td></tr></table>			GOOD		FAIR	XXX	POOR		DESTROYED			
GOOD														
FAIR	XXX													
POOR														
DESTROYED														



East elevation, view northwest.



View north, inside pavilion.

BIBLIOGRAPHY
ELLIS ISLAND HISTORIC STRUCTURE REPORT
DOCUMENTATION

Prepared for the U.S. Department of Interior/National Park Service, Denver Service Center
by Beyer Blinder Belle/Notter Finegold Alexander

HISTORIC STRUCTURES REPORTS

Volume 1	The Main Building June 1, 1984	NPS D-41
Volume 2 Part One	Unit One Buildings December 1985	NPS D-42
Volume 2 Part Two	Unit One Buildings December 1985	NPS D-42
Volume 3	Powerhouse December 1985	NPS D-43
Volume 4 Part One	Units 2, 3 and 4 August 30, 1986	NPS D-44
Volume 4 Part Two	Units 2, 3 and 4 August 30, 1986	NPS D-44
Volume 4 Part Three	Units 2, 3 and 4 August 30, 1986	NPS D-44

EXISTING CONDITION SURVEYS

Volume 1 Appendix A	Main Building February 1, 1984	NPS D-41
Volume 2 Appendix D	Unit One Buildings July 1985	NPS D-42
Volume 3 Appendix A	Powerhouse December 1985	NPS D-43
Volume 4 Appendix A Part One	Units 2, 3 and 4 July 1986	NPS D-44
Volume 4 Appendix A Part Two	Units 2, 3 and 4 July 1986	NPS D-44

As the nation's principal conservation agency, the Department of the Interior has basic responsibilities to protect and conserve our land and water, energy and minerals, fish and wildlife, parks and recreation areas, and to ensure the wise use of all these resources. The department also has major responsibility for American Indian reservation communities and for people who live in island territories under U.S. administration.

Publication services were provided by the graphics staff of the Denver Service Center.
NPS D-44 September 1988

